

DEP/Lee Co Estero Bay Water Quality Monitoring

Site ID	Site Description	Date	Time	YSI				Weather					Site Comments	
				Temp C	Salinity (ppt)	DO (mg/L)	pH	Spec Cond (mS/cm)	Wind Dir	Wind Speed	Seas	Cloud Cover %		
HENDGR01	Hendry Creek under power lines. N 26 29' 15.4" W 81 52' 55.8"	2/5	12:35	22.83		6.88	7.49	33011	S	5-10	CALM LC	1-25	Secchi	total Depth
HENDGR02	Hendry Cr. can see 1st house N 26 30' 47.9" W 81 52' 46.1"	2/5	11:50	23.09		3.95	7.39	24025	S	0-4	CALM ^{OK} LC	1-25	1.0	1.35
MULLGR01	Mullock Cr. Y near marker 22 N 26 27' 53.0" W 81 51' 56.8"	2/5	10:50	22.32		5.93	7.42	32520	S	0-4	CALM LC	1-25	5	0.7
MULLGR02	Mullock Creek; marker 55 N 26 28' 14.1" W 81 51' 21.3"	2/5	10:15	22.39		6.12	7.25	30062	SW	0-4	CALM	1-25	5	1.0
SPRIGR01	Spring Cr. near marker 21 N 26 22' 54.0" W 81 50' 10.4"												3	0.75
SPRIGR02	Spring Cr. near marker 51 N 26 22' 28.6" W 81 49' 55.0"													
IMPBGR01	Imperial R. house w/ 3 arches N 26 20' 12.4" W 81 50' 2.0"													
FCEB_1	FCEB (Equipment Blank)	2/5	12:10	25.44		8.95	6.8	8						
FCEB_2	FCEB (Equipment Blank)													
	Field Duplicate													

Monitor(s): MARYANN DWIGAN
KEUSEY LANC?

Wind Dir: N / NE / NW / S / SE / SW / E / W
Wind Speed: Calm / 0-4 / 5-10 / 11-15 / 16-20 / >20
Seas: Calm / R / LC / MD / HC
Cloud Cover %: 0 / 1-25 / 26-50 / 51-75 / 76-99 / 100