

DEP/Lee Co Estero Bay Water Quality Monitoring

Monitor(s): MD, KL

Site ID	Site Description	Date	Time	YSI					Weather					Site Comments	
				Temp C	Salinity (ppt)	DO (mg/L)	pH	Spec Cond (mS/cm)	Wind Dir	Wind Speed	Seas	Cloud Cover %	Weather Comments		
HENDGR01	Hendry Creek under power lines. N 26 29' 15.4" W 81 52' 55.8"	4/25	11:50	27.0	34.01	4.2	7.52	51774	NW	0-4	R	1-25		1.4	1m
HENDGR02	Hendry Cr. can see 1st house N 26 30' 47.9" W 81 52' 46.1"	4/25	11:35	26.6	30.88	2.43	7.33	47530	NW	0-4	R	1-25		0.9	S
MULLGR01	Mullock Cr. Y near marker 22 N 26 27' 53.0" W 81 51' 56.8"	4/25	10:35	26.3	33.66	4.11	7.50	51307	W	calm	LC	26-50%		0.8	S
MULLGR02	Mullock Creek; marker 55 N 26 28' 14.1" W 81 51' 21.3"	4/25	10:00	26.6	29.19	3.63	7.36	45777	W	calm	LC	26-50%		0.75	S
SPRIGR01	Spring Cr. near marker 21 N 26 22' 54.0" W 81 50' 10.4"														
SPRIGR02	Spring Cr. near marker 51 N 26 22' 28.6" W 81 49' 55.0"														
IMPRGR01	Imperial R. house w/ 3 arches N 26 20' 12.4" W 81 50' 2.0"														
FCEB_1	FCEB (Equipment Blank)	4/25	10:15	25.9	0.0	8.59	6.71	1.5	Wind Dir: N / NE / NW / S / SE / SW / E / W Wind Speed: Calm / 0-4 / 5-10 / 11-15 / 16-20 / >20 Seas: Calm / R / LC / MD / HC Cloud Cover %: 0 / 1-25 / 26-50 / 51-75 / 76-99 / 100						
FCEB_2	FCEB (Equipment Blank)														
	Field Duplicate														