

DEP/Lee Co Estero Bay Water Quality Monitoring

Monitor(s): Nicole Reistad, Marjann Dwyer
Kelsey Lang, Austin Walters

Site ID	Site Description	Date	Time	YSI					Weather					Secchi Depth	
				Temp C	Salinity (ppt)	DO (mg/L)	pH	Spec Cond (mS/cm)	Wind Dir	Wind Speed	Seas	Cloud Cover %	Weather Comments	Site	Comments
HENDGR01	Hendry Creek under power lines. N 26 29' 15.4" W 81 52' 55.8"	7/24/18	9:50	30.2	6.19	3.62	7.34	11025	S	5-10	LC	50	storm to the north	0.9	1.1
HENDGR02	Hendry Cr. can see 1st house N 26 30' 47.9" W 81 52' 46.1"														
MULLGR01	Mullock Cr. Y near marker 22 N 26 27' 53.0" W 81 51' 56.8"														
MULLGR02	Mullock Creek; marker 55 N 26 28' 14.1" W 81 51' 21.3"														
SPRIGR01	Spring Cr. near marker 21 N 26 22' 54.0" W 81 50' 10.4"														
SPRIGR02	Spring Cr. near marker 51 N 26 22' 28.0" W 81 49' 08.0"														
IMPRGR01	Imperial R. house w/ 3 acres N 26 20' 12.4" W 81 50' 2.0"														
FCEB_1	FCEB (Equipment Blank)	7/24/18	10:50	29.7	0.0	7.68	3.6	1	Wind Dir: N/NE/NW/S/SE/SW/E/W Wind Speed: Calm / 0-4 / 5-10 / 11-15 / 16-20 / >20 Seas: Calm / R / LC / MD / HC Cloud Cover %: 0 / 1-25 / 26-50 / 51-75 / 76-99 / 100						
FCEB_2	FCEB (Equipment Blank)														
FCEB_3	FCEB (Equipment Blank)														