

DEP/Lee Co Estero Bay Water Quality Monitoring

Monitor(s): Maryann Dugan, Kelley Lang, Davis Johanson

Site ID	Site Description	Date	Time	YSI					Weather					Depth	
				Temp C	Salinity (ppt)	DO (mg/L)	pH	Spec Cond (mS/cm)	Wind Dir	Wind Speed	Seas	Cloud Cover %	Weather Comments	Secchi	Depth
HENDGR01	Hendry Creek under power lines. N 26 29' 15.4" W 81 52' 55.8"														
HENDGR02	Hendry Cr. can see 1st house N 26 30' 47.9" W 81 52' 46.1"	8/6	10:10	30.1	1	3.79	6.99	1981	N/A	C	C	1-25	no wind	0.8	1.2
MULLGR01	Mullock Cr. Y near marker 22 N 26 27' 53.0" W 81 51' 56.8"	8/6	11:35	30.1	9.81	5.14	7.69	91518	N/E	5-10	LC	26-50		S	0.8
MULLGR02	Mullock Creek; marker 55 N 26 28' 14.1" W 81 51' 21.3"	8/6	11:05	30.0	0.80	5.98	7.26	1513	E	0-4	C	1-25	no wind	S	1.2
SPRIGR01	Spring Cr. near marker 21 N 26 22' 54.0" W 81 50' 10.4"														
SPRIGR02	Spring Cr. near marker 51 N 26 22' 28.6" W 81 49' 55.0"														
IMPRGR01	Imperial R. house w/ 3 arches N 26 20' 12.4" W 81 50' 2.0"														
FCB1_1	FCB1 (Equipment Blank)	8/6	1125	29.8	0	7.31	5.33	0.5	Wind Dir: N/NE/NW/S/SE/SW/E/W Wind Speed: Calm / 0-4 / 5-10 / 11-15 / 16-20 / >20 Seas: Calm / R / LC / MD / HC Cloud Cover %: 0 / 1-25 / 26-50 / 51-75 / 76-99 / 100						
FCB1_2	FCB1 (Equipment Blank)														
	Field Duplicate														