

DEP/Lee Co Estero Bay Water Quality Monitoring

Monitor(s): MD, JB

Site ID	Site Description	Date	Time	YSI					Weather					Site Comments
				Temp C	Salinity (ppt)	DO (mg/L)	pH	Spec Cond (mS/cm)	Wind Dir	Wind Speed	Seas	Cloud Cover %	Weather Comments	
MULLGR01 HENDGR01	Hendry Creek under power lines. N 26 29' 15.4" W 81 52' 55.8"	5/24/19	0945	28.9	16.37	3.23	7.45	26842	E	5 KTS	calm	0	clear	TD - 1.2m Secchi - 1.0m
HENDGR02	Hendry Cr. can see 1st house N 26 30' 47.9" W 81 52' 48.1"	5/24/19	1150	27.5	10.49	1.84	7.45	11441	E	5 KTS	calm	0	clear	TD - 1.1m Secchi - 1.1m
HENDGR01 MULLGR01	Mullock Cr. Y near marker 22 N 26 27' 53.0" W 81 51' 56.8"	5/22/19	1115	28.7	11.38	1.92	7.41	19261	E	5 KTS	calm	0	clear	TD - 0.9m Secchi - 0.9m
MULLGR02	Mullock Creek; marker 55 N 26 28' 14.1" W 81 51' 21.3"	5/24/19	1015	28.8	9.42	3.81	7.57	16101	E	5 KTS	calm	0	clear	TD - 1.1m Secchi - 1.1m
SPRIGR01	Spring Cr. near marker 21 N 26 22' 54.0" W 81 50' 10.4"													
SPRIGR02	Spring Cr. near marker 51 N 26 22' 28.0" W 81 49' 53.0"													
IMPRGR01	Imperial R. house w/ 3 arches N 26 20' 12.4" W 81 50' 0.0"													
FCEB_1	FCEB (Equipment Blank)	5/24/19	1035	28.0	0	7.33	8.65	5.0	Wind Dir: N / NE / NW / S / SE / SW / E / W Wind Speed: Calm / 0-4 / 5-10 / 11-15 / 16-20 / >20 Seas: Calm / R / LC / MD / HC Cloud Cover %: 0 / 1-25 / 26-50 / 51-75 / 76-99 / 100					
FCEB_2	FCEB (Equipment Blank)													
	Field Duplicate													