

DEP/Lee Co Estero Bay, Water Quality Monitoring

Monitor(s):

Miranda Cantu + Kirby White

Site ID	Site Description	Date	Time	YSI						Weather				Site Comments
				Temp C	Salinity (ppt)	DO (mg/L)	pH	Spec Cond (mS/cm)	Wind Dir	Wind Speed	Seas	Cloud Cover %	Weather Comments	
HENDGR01	Handy Creek under power lines. N 26 29' 15.4" W 81 52' 55.8"													
HENDGR02	Handy Cr. can see 1st house N 26 30' 47.9" W 81 52' 46.1"													
MULLGR01	Mullock Cr. Y near marker 22 N 26 27' 53.0" W 81 51' 56.8"	11/17/20	10:40	26.3	1.10	6.09	7.52	2258	NE	10-15	calm	0		Seas: 0.5 Total: 0.5 D07-74.3
MULLGR02	Mullock Creek; marker 55 N 26 28' 14.1" W 81 51' 21.3"	11/17/20	10:45	25.3	0.57	6.06	7.50	1197	NE	10-15	calm	0		Seas: 0.8 Total: 0.8 D07-73.4
SPRIGR01	Spring Cr. near marker 21 N 26 22' 54.0" W 81 50' 10.4"													
SPRIGR02	Spring Cr. near marker 51 N 26 22' 28.6" W 81 49' 55.0"													
IMPRGR01	Imperial R. house w/ 3 arches N 26 20' 12.4" W 81 50' 2.0"													
FCER_1	FCER (Equipment Blank)	11/17/20	12:00	-	-	-	-	-						
FCER_2	FCER (Equipment Blank)													
	Field Duplicate													

Wind Dir: N/NE/NW/S/SE/SW/E/W
Wind Speed: Calm/0-4/5-10/11-15/16-20/>20
Seas: Calm/R/LC/MD/HC
Cloud Cover %: 0/1-25/26-50/51-75/76-99/100