

DEP/Lee Co Estero Bay Water Quality Monitoring

Monitor(s): Kirby Wile + Monday

Site ID	Site Description	Date	Time	YSI					Weather				Site Comments
				Temp C	Salinity (ppt)	DO (mg/L)	pH	Spec Cond (mS/cm)	Wind Dir	Wind Speed	Seas	Cloud Cover %	
HENDGR01	Hendry Creek under power lines. N 26 29' 15.4" W 81 52' 55.8"	11/24/20	1010	23.4	11.10	6.03	7.68	8762	NE	10	Calms	D	Total Depth: 1.9 DO: Secchi: 1.1
HENDGR02	Hendry Cr. can see 1st house N 26 30' 47.9" W 81 52' 46.1"	11/24/20	1035	22.3	29.2	4.43	7.52	621	NE	10	Calms	D	ID: 1.3 DO: Secchi: 1.0
MULLGR01	Mullock Cr. Y near marker 22 N 26 27' 53.0" W 81 51' 56.8"												ID: Secchi:
MULLGR02	Mullock Creek; marker 55 N 26 28' 14.1" W 81 51' 21.3"												ID: Secchi:
SPRIGR01	Spring Cr. near marker 21 N 26 22' 54.0" W 81 50' 10.4"												
SPRIGR02	Spring Cr. near marker 51 N 26 22' 28.6" W 81 49' 55.0"												
SPRIGR01	Spring Cr. house w/ 3 arches N 26 20' 12.4" W 81 50' 2.0"												
FCEB_1	FCEB (Equipment Blank)	11/24/20	1100										Wind Dir: N/NE/NW/S/SE/SW/E/W Wind Speed: Calm/0-4/5-10/11-15/16-20/>20 Seas: Calm/R/LC/MD/HC Cloud Cover %: 0/1-25/26-50/51-75/76-99/100
FCEB_2	FCEB (Equipment Blank)												
	Field Duplicate												