

DEP/Lee Co Estero Bay Water Quality Monitoring

John Barryman
Cory Sisk

Monitor(s):

Site ID	Site Description	Date	Time	YSI					Weather					Site Comments
				Temp C	Salinity (ppt)	DO (mg/L)	pH	Spec Cond (mS/cm)	Wind Dir	Wind Speed	Seas	Cloud Cover %	Weather Comments	
HENDGR01	Hendry Creek under power lines. N 26 29' 15.4" W 81 52' 55.8"	11/10/12	1145	22.1	0.88	4.73	7.58	1723	N	5-10	calm	1-25	—	0.6 TD Uob
HENDGR02	Hendry Cr. can see 1st house N 26 30' 47.9" W 81 52' 46.1"	11/19/12	1125	21.6	4.54	5.92	7.54	2075	N	5-10	calm	0	—	1.5 TD Uob
MULLGR01	Mullock Cr. Y near marker 22 N 26 27' 53.0" W 81 51' 56.8"	11/19/12	1040	21.7	1.95	6.54	7.50	2501	N	5-10	calm	0	—	0.4 TD Uob
MULLGR02	Mullock Creek; marker 55 N 26 28' 14.1" W 81 51' 21.3"	11/19/12	1015	21.7	1.69	6.24	7.36	2525	N	5-10	calm	0	—	1.1 TD Uob
SPRIGR01	Spring Cr. near marker 21 N 26 22' 54.0" W 81 50' 10.4"													
SPRIGR02	Spring Cr. near marker 51 N 26 22' 28.6" W 81 49' 55.0"													
IMPRGR01	Imperial R. house w/ 3 arches N 26 20' 12.4" W 81 50' 2.0"													
FCEB_1	FCEB (Equipment Blank)	11/19/12	1150											
FCEB_2	FCEB (Equipment Blank)													
	Field Duplicate													

Wind Dir: N / NE / NW / S / SE / SW / E / W
Wind Speed: Calm / 0-4 / 5-10 / 11-15 / 16-20 / >20
Seas: Calm / R / LC / MD / HC
Cloud Cover %: 0 / 1-25 / 26-50 / 51-75 / 76-99 / 100

Wind Dir: N / NE / NW / S / SE / SW / E / W
Wind Speed: Calm / 0-4 / 5-10 / 11-15 / 16-20 / >20
Seas: Calm / R / LC / MD / HC
Cloud Cover %: 0 / 1-25 / 26-50 / 51-75 / 76-99 / 100