



*Figure 1 – Upstream section of abutment of the Myakka State Park bridge at East End Bent..*



*Figure 2 – View of the upstream section of the Myakka State Park bridge at East End Bent..*



*Figure 3 - Downstream section of East End Bent.*



*Figure 4 - View of the downstream section of the Myakka State Park bridge. East end bent in foreground*





*Figure 5 – Upstream view. West end bent in foreground.*



*Figure 6 – Top of rail and bridge slab. Damaged Riprap at West End Bent*



*Figure 7 – Damaged Sand Cement riprap at West End Bent*



*Figure 8 – Bridge surroundings*





*Figure 9 – Forested overbank area west of the bridge*



*Figure 10 – Bent dimensions*



*Figure 11 – View of the bridge's bent and piles.*



*Figure 12 – Bridge overbank area.*