


Forestry Suppliers, Inc.

1-800-647-5368

49354 Level Book

Steeley Anderson
791-1248

528-2846
GUY



~~January~~ ^{JAN} 8, 2008

McGrover BA1 VC 1

top of dredge spoil
cored to ≈ 15 feet

~~30 22 07.3~~

~~87 10 52.0~~

① BA1 VC1 Elevation 6.8 ft. Acc. 9.0 ft

N 30 22 05.8

W 87 10 51.4

② BA 1 VC 2 #

Low on dredge spoil pile

vibrocored to ≈ 8 feet not

resistance continued to ≈ 11 feet

pulled core approximately 7 feet
of core recovered more or less again

N 30 22 06.3

W 87 10 50.3

③ BA1 VC3

15' over from VC 2

N 30 22 06.4

W 87 10 50.1 Elev 12'

Jan ~~Dec~~ 9, 2008

DI VC1
South end of island on
Dredge mound

N30 21 49.6
W87 11 22.3 $\approx 10'$

DI VC2

Second from South
end of island $\approx 9'$
Dredge mound

N30 21 51.2
W87 11 19.8
Look like $\approx 7'$ of core

DI VC3

Third from South
end of island $\approx 9'$ pm

Natural Island
middle of Island

N30 21 53.2
W87 11 18.7

elevation 6'

Jan ~~Dec~~ 10, 2008

Pulled ~~DI~~ DI VC3

DI VC4

North end of Island near where
island joins spit approximately
10 feet from where point is
exposed penetrated to approximately
10 feet

N30 22 06.4
W87 11 12.4 elevation approx 2'

DI VC5

North end of Island side next to old
Navy Cove $\approx 15'$ from MLW

N30 22 05.6
W87 11 13.4

penetrated to approximately 7' when
tube parted just below vibrator head
moved head & penetrated to $\approx 9'$

DI VC6

N30 21 59.2
W87 11 14.9

DI VC7 In channel South of
Island 15' of sea wall to the right
 $\approx 5'$ of core N30 21 48.25
W87 11 22.84

~~Jan~~ 12, 2008

DI VZ 8

N 30 22 09.2

W 87 11 14.4

U

O

VL30

In water off beach
pile

245 3131
June 28, 2010 933 2423

Rocky over cast hydrothermal
* St. Joe SET site
no longer extant.
Erosion has removed
Cast photo by Mr. Laine
for comparison

* Apalachee La River
Upstream site not
found marked ground
location with white
pale in marsh of white
pale on bank appears
as if the marsh had
burned in the area. This
marks maybe lost
Site B lost site marked
bank with white pale
this is a site we searched
for several times and did
not find.

June 29, 2010

Okalochee Bay Set
Site Turtle Island
used known GPS
to get to point but
down a 10 foot creek
didn't find
marked with white pipe

Okalochee Bay Set
Site Bald Post
used known GPS
found site & marked
it with white pipe
Both Birds & pipe
in place since
didn't find pipe in
SET pipe
longer used
of board

2:35
6:51

4:00

Aculla River Set Sites
all three sites found
all three sites marked
with 3" PVC in
Set pipe one 4".
PVC pipe in middle
boards all gone except
for one

St Marks Inter tidal
recorded location
3005 ~~354.6~~
94 12 29.8

Board floating sitting
well can be found need
to visit at low tide
to find Set Pipe
Photo taken

Set is in spartina
I floats board over the
St Marks Super tidal
can be seen

next page

St Marks Superficial
notched with 44
PVC Shelly and
both bands are in
place need to
measure in low tide
or near it

Took photos

30 .10576 06.340

84 .21652 12.493

Put 2" PVC pipe in
SET Pipe hole

St Mark original Sub. box
Location put in new USGS

Multiple Locations

4 or 5 original

30 06 03.6

84 12 41.0

Put 2" PVC in

3 Set pipes

To find St Marks
go to marker 29
then step 210'