

Attachment III – Site Photos
Cape Canaveral Energy Center PA 08-53
Storm Surge Mitigation

Photo 1 - East Embankment of Pond C (Looking South)



Photo 2 - Pipeline and Existing Seawall (Looking South)




Photo 3 - Pipeline and Existing Seawall (Looking North)



Photo 4 - Area for Soil Cement Installation (Looking North - East of Pond A)



Photo 5 - Flowable Fill Sea Wall Seal with Concrete Sidewalk Area
(Looking Southeast)

