

APPENDIX 10.7.1.1

FPL TURKEY POINT UNITS 6 & 7 PROJECT PHOTOGRAPHS



Photograph 1. Units 6 & 7 Site –Cooling canal (FLUCFCS 510) with mud flats (FLUCFCS 650) in background and fill areas/roadways (FLUCFCS 744) in foreground.



Photograph 2. Units 6 & 7 Site (northwestern portion) – Ditches (FLUCFCS 511) dead-end cooling canal.



Photograph 3. Units 6 & 7 Site (west laydown area) - Open water (FLUCFCS 531) looking south in cooling canals.



Photograph 4. Units 6 & 7 Site - Mangrove head (FLUCFCS 612A) in cooling canal with existing Turkey Point Plant in background.



Photograph 5. Units 6 & 7 Site – (western laydown area) - Dwarf mangroves (FLUCFCS 612B)



Photograph 6. Units 6 & 7 Site – (west laydown area) - stressed dwarf mangroves (FLUCFCS 612B) and open water (FLUCFCS 531) in cooling canal.



Photograph 7. Units 6 & 7 Site - Mud flats (FLUCFCS 650)



Photograph 8. Units 6 & 7 Site - Mud flats (FLUCFCS 650) with upland spoils pile (FLUCFCS 743) and existing Turkey Point Plant in background.



Photograph 9. Units 6 & 7 Site - Wetland spoils pile (FLUCFCS 743-Wet) adjacent to remnant cooling canal (FLUCFCS 511).



Photograph 10. Site of nuclear administration building, training building and parking area—Mangroves (FLUCFCS 612)



Photograph 11. Site of nuclear administration building, training building and parking area – Mangrove/Willow (FLUCFCS 612/618)



Photograph 12. Spoils area – Grand Canal berm (FLUCFCS 743)



Photograph 13. Radial collector wells – upland fill area (FLUCFCS 744) with mangroves (FLUCFCS 612) in background.



Photograph 14. Turning basin (FLUCFCS 510) focused on area of proposed expansion with existing Turkey Point facility in background.