Quarterly Temperature Verification
Regional Operation Centers

DEP SOP FT 1400; Acceptance Criteria for Temp. ± 0.5°C.
Correction factor needed if acceptance criteria are exceeded.
Record all digits displayed for temperature readings. Do not round before reporting measurements.

Meter ID#: BOOP NON Date of Last Verification: 3/2/18
Date: 6/1/18 Time: 1050 (ETZ) / CTZ NIST Reference Device ID#: 844016
Cold Bath (between 0 – 10°C): Sonde: 8.30 °C; NIST: 8.4 °C; Result: (Pass) / Fail
Warm Bath (between 30 – 40°C): Sonde: 38.20 °C; NIST: 37.9 °C; Result: (Pass) / Fail
Is Correction Factor Needed? Y / (N) If yes, describe: _____
Person Performing Verification: Mike Drennan

Comments: _____

Meter ID#: Betty 67 Date of Last Verification: 3/2/18
Date: 6/1/18 Time: 1050 (ETZ) / CTZ NIST Reference Device ID#: 844016
Cold Bath (between 0 – 10°C): Sonde: 8.13 °C; NIST: 8.20 °C; Result: (Pass) / Fail
Warm Bath (between 30 – 40°C): Sonde: 38.00 °C; NIST: 37.9 °C; Result: (Pass) / Fail
Is Correction Factor Needed? Y / (N) If yes, describe: _____
Person Performing Verification: Mike Drennan

Comments: _____

Meter ID#: _____ Date of Last Verification: _____
Date: _____ Time: _____ ETZ / CTZ NIST Reference Device ID#: _____
Cold Bath (between 0 – 10°C): Sonde: _____ °C; NIST: _____ °C; Result: Pass / Fail
Warm Bath (between 30 – 40°C): Sonde: 3 °C; NIST: _____ °C; Result: Pass / Fail
Is Correction Factor Needed? Y / N If yes, describe: _____
Person Performing Verification: _____

Comments: _____