CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Meter ID: KCJS RQ- 2019-04-08-04 Project: CLT

Boldly "X" this box if there are qualified data on this page.

Notes: (1) Always wait for meter to stabilize before recording any readings.
(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).
(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Temperature (Quarterly) FT 1400 Date of Last Temperature Verification 3/19/19

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp °C	Barom. meter mmHg	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	S. Cofer	4/24/19	0704	24.69	760	8.31	8.32	100.0	50.2	–	P / F	L / F
ICV	"	"	0706	24.19	760	8.39	8.39	100.0	51.2	–	P / F	L / F
CCV	Barrenkow	4/24/19	1632	24.95	760	8.26	8.29	100.1	50.2	–	P / F	L / F
CCV											P / F	L / F

DO Acceptance criteria from Table ± 0.3 mg/L. **Rapid-Pulse Sensors:** DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.
Optical: DO gain range 0.85 to 1.15 (Pro DSS 0.75 to 1.50); DO charge N/A. **Steady-state & Galvanic Sensors:** DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard µmhos/cm	Meter Reading µmhos/cm	Pass / Fail	Lab / Field
Calibr.	S. Cofer	4/24/19	0710	2810641	10/20	500	500	P / F	L / F
ICV	"	"	0715	2901833	12/20	1400	1003	P / F	L / F
CCV	Barrenkow	4/24/19	1634	2811465	11/20	100	101	P / F	L / F
CCV	Barrenkow	4/24/19	1635	2811660	11/20	50000	49604	P / F	L / F

Conductivity Acceptance criteria ± 5%

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Temp °C	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	S. Cofer	4/24/19	0716	187601	11/20	6.994	25.23	6.96	-9.5	P / F	L / F
Calibr.	"	"	0720	183218	7/20	4.011	25.99	3.99	150.5	P / F	L / F
Calibr.	"	"	0725	186877	10/20	10.003	25.64	9.98	-177.0	P / F	L / F
ICV	"	"	0730	183210	7/20	4.011	26.66	3.94	162.7	P / F	L / F
CCV	Barrenkow	4/24/19	1636	186877	10/20	10.00	26.01	10.02	—	P / F	L / F
CCV										P / F	L / F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50; mV pH 4 Range +180 ± 50; mV pH 10 Range -180 ± 50;
If mV are recorded: slope from 7 to 10 168.5, slope from 4 to 7 180 (both must be between 165 and 180 mV)

Does meter have a depth sensor that will be used to measure total depth & sample depth? YES / NO / NA (not surf. water project)
If **YES**, complete daily Calibr. & ICV below and list date of last quarterly depth verification: _____
If **NO**, what will be used? (circle one) **Secchi Disk line / Sonar** Unique ID: Decker Bu.552 Date of last verification: 12/26/18

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value, meters	Pass / Fail	Lab / Field
Pressure mode in air						P / F	L / F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria ± 5 % or ± 0.05m, whichever is greater.

MMENTS:

Form effective August 1, 2018