From: Jeff Baylor
To: DEP-Overflowmicro
Subject: RE: SMP FORT LAUDERDALE (Pace Project # 35444669)
Date: Monday, February 11, 2019 3:58:34 PM

Kara,
When the lab was setting up the Enterococcus MPN tests for this project, they ran 3 of the 4 samples but neglected to run G4SE0037. I was alerted of the issue once the final report was completed on 2/7/19. I have requested a corrective action from management for the lab to find a method to prevent such a mistake in the future.
Thank you

Jeff Baylor
Project Manager
Pace Analytical Services
8 East Tower Circle
Ormond Beach, FL 32174
386.676.4806 | 386.672.5668
www.pacelabs.com

>>> DEP-Overflowmicro <DEP-Overflowmicro@dep.state.fl.us> 2/11/2019 1:27 PM >>>
>
Hey Jeff,

I'm just wondering, what was the internal lab issue with the sample for field ID G4SE0037?

Thanks! Kara

From: Paceport Email Notification <jeff.baylor@pacelabs.com>
Sent: Thursday, February 7, 2019 2:51 PM
To: jeff.baylor@pacelabs.com; DEP-Overflowmicro <DEP-Overflowmicro@dep.state.fl.us>
Subject: SMP FORT LAUDERDALE (Pace Project # 35444669)

Paceport Login

Pace Automated Email Notification

This email contains EDDs and Reports generated by Paceport's automated deliverable service. The attached files have been authorized to be sent to you due to the completion of project 35444669. Your Pace project manager has been CC'ed on this email so that you may request any further assistance.

To access this project's page in paceport click on the following link.
http://paceport.pacelabs.com/ClientPortal/mvc/projectDetails/modelAndView?projectID=35444669&systemID=lims35

Copyright © 2012 Pace Analytical Services, Inc