

Other Checks

Documentation

- All field sheets, photos, and lab reports were saved to the BMAP folder here:
Y:\BMAP\2018\21FLCEN
- Depth/Temp verifications were scanned and saved to the BMAP folder, however daily calibration logs were not. These were saved in the SMP folder and should be moved to the appropriate project folder.

Project Completion

- BMAP Sampling was complete for each project as described here:
<https://floridadep.sharepoint.com/dear/ceroc/SitePages/BMAP.aspx>