

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there are qualified data on this page.

Meter ID: KEYS

RQ: 2019-01-28-68

Project: Caloosa projects

- Notes: (1) Always wait for meter to stabilize before recording any readings.
 (2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).
 (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 12/26/2018

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp °C	Baro- meter mmHg	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Gary Swartz	1/31/19	0730	24.2	760	8.39	8.39	100	58.4	-	(P) F	(D) F
ICV		"	0731	24.1	760	8.40	8.38	99.8	58.4		(P) F	(D) F
CCV	Gary Swartz	1/31/19	1630	24.4	760	8.36	8.16	97.6	57.4		(P) F	(D) F
CCV											P / F	L / F

DO Acceptance criteria from Table ± 0.3 mg/L. Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.
 Optical: DO gain range 0.85 to 1.15 (Pro DSS 0.75 to 1.50); DO charge N/A. Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ hos/cm	Meter Reading μ hos/cm	Pass / Fail	Lab / Field
Calibr.	Gary Swartz	1/31/19	0726	2810627	10/20	1000	1000	(P) F	(D) F
ICV		"	0728	280884	07/20	100	103	(P) F	(D) F
CCV	Gary Swartz	1/31/19	1627	1865223	06/19	10,000	9763	(P) F	(D) F
CCV								P / F	L / F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Temp °C	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Gary Swartz	1/31/19	0734	185764	8/20	6.997	25.12	7.00	10.0	(P) F	(D) F
Calibr.		"	0735	185488	08/20	4.01	25.26	4.0	155.4	(P) F	(D) F
Calibr.		"	0739	185490	09/20	10.01	25.02	10.0	177.3	(P) F	(D) F
ICV		"	0730	185488	08/20	4.01	25.21	3.98	156.0	(P) F	(D) F
CCV	Gary Swartz	1/31/19	1634	185490	07/20	10.01	25.30	10.14	182.3	(P) F	(D) F
CCV										P / F	L / F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ; mV pH 4 Range $+180 \pm 50$; mV pH 10 Range -180 ± 50 ;
 If mV are recorded: slope from 7 to 10 _____, slope from 4 to 7 _____ (both must be between 165 and 180 mV)

Does meter have a depth sensor that will be used to measure total depth & sample depth? YES / NO / NA (not surf. water project)

If YES, complete daily Calibr. & ICV below and list date of last quarterly depth verification: _____

If NO, what will be used? (circle one) Secchi Disk Line / Sonar Unique ID: Deepa Blue; Date of last verification: 12/26/18

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value, meters	Pass/ Fail	Lab / Field
Pressure mode in air						P / F	L / F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS: