

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this page.

Meter Quanta #1 RQ- 2016-CQ-12-27 Project MASSACHUSETTS EAST 2

- Notes:** (1) Numbers ≤ 4 , are rounded down; numbers ≥ 5 are rounded up (e.g., 5.15 becomes 5.2).
 (2) Always wait for meter to stabilize before recording any readings.
 (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification

7/2016 07/2016

DO FDEP SOP FT 1500	Name	Date	Time CT-ET	Temp	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	P O'Connor	09/15/16	0600	24.0	8.40	8.40	100.0	—	—	Pass	LAB
ICV	↓	↓	0610	24.1	8.40	8.38	99.9	—	—	Pass	LAB
CCV	P O'Connor	09/15/16	1415	24.3	8.37	8.49	101.6	—	—	Pass	LAB
CCV											

Report DO mg/L with one decimal figure and DO % saturation as a whole number with no decimals.

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	P O'Connor	09/15/16	0614	160616A	06/2017	1000	1000	Pass	LAB
ICV	↓	↓	0616	15113A	11/2016	100	100	Pass	LAB
CCV	P O'Connor	09/15/16	1420	1298116	04/2017	12900	13240	Pass	LAB
CCV									

Report specific conductance as a whole number with no decimal figure.

Conductivity Acceptance criteria $\pm 5\%$

pH FDEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	P O'Connor	09/15/16	0618	2404E04	06/2018	7.0	7.00	—	Pass	LAB
Calibr.	↓	↓	0623	2402556	01/2018	4.0	4.00	—	Pass	LAB
Calibr.	↓	↓	0627	2510A88	04/2017	10.0	9.89	—	Pass	LAB
ICV	↓	↓	1430	2406E04	06/2018	7.0	6.97	—	Pass	LAB
CCV										
CCV										

Report pH with one decimal place; pH Acceptance criteria ± 0.2 SU;

mV pH7 Range 0 $\pm$ 50;

mV pH 4 Range

+180 $\pm$ 50; mV pH 10 Range -180 $\pm$ 50;

Slope from 7 to 10 and 4 to 7 must be between 165

and 180mV

Depth (Quarterly)

Date of Last Depth Verification

1/17

Depth Sensor (Daily)	Name	Date	Time CT-ET	Zero the Sensor	ICV Value	Pass/ Fail	Lab/ Field
Pressure mode in air				0.000			

ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater