

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this name.

Meter ID: B007/NUN

RQ- 2017-12-18-30

Project: S m P

Notes: (1) Always wait for meter to stabilize before recording any readings.

(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).

(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification

12/17

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	T. Riordan	12/11/17	740	19.91	9.111	9.11	100.1	41.0	0.9497	<u>0</u> /F	<u>L</u> /F
ICV				20.06	9.074	9.10	100.2	41.0		<u>0</u> /F	<u>L</u> /F
CCV			1720	21.54	8.891	8.77	99.1	41.0	0.9487	<u>0</u> /F	<u>0</u> /F
CCV					8.829					P/F	L/F

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ hos/cm	Meter Reading μ hos/cm	Pass / Fail	Lab / Field
Calibr.	T. Riordan	12/11/17	740	170831	9/18	1000	999.20	<u>0</u> /F	<u>L</u> /F
ICV				171023	11/18	100	98	<u>0</u> /F	<u>L</u> /F
CCV			1720	171023	11/18	100	99	<u>0</u> /F	<u>0</u> /F
CCV								P/F	L/F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	T. Riordan	12/11/17	740	165674	8/18	7.0	7.00	-46.4	<u>0</u> /F	<u>L</u> /F
Calibr.				171629	4/19	4.0	4.00	135.7	<u>0</u> /F	<u>L</u> /F
Calibr.				172191	3/19	10.0	10.00	-222.4	<u>0</u> /F	<u>L</u> /F
ICV				171629	4/19	4.0	4.02	134.8	<u>0</u> /F	<u>L</u> /F
CCV			1720	172191	3/19	10.0	10.04	-225.1	<u>0</u> /F	<u>L</u> /F
CCV									P/F	L/F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ;

mV pH 4 Range $+180 \pm 50$;

mV pH 10 Range -180 ± 50 ;

If mV are recorded: slope from 7 to 10 _____, slope from 4 to 7 _____ (both must be between 165 and 180 mV)

Is meter equipped with depth sensor? Yes / No If yes, list date of last quarterly depth verification _____

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value meters	Pass / Fail	Lab / Field
Pressure mode in air						P/F	L/F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS:

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this name

Meter ID: Betty 67

RQ-

Project: SMP

Notes: (1) Always wait for meter to stabilize before recording any readings.

(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).

(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 12/17

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Natalie Ayala	12/11/17	830	21.37	8.85	8.88	100.4	33.9	1.0234	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
ICV	↓	↓	831	21.36	8.85	8.89	100.4	33.9	↓	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
CCV	T. Riordan	12/14/17	715	20.21	9.05	8.91	98.7	33.3	1.0234	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
CCV										P/F	L/F

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ hos/cm	Meter Reading μ hos/cm	Pass / Fail	Lab / Field
Calibr.	Natalie Ayala	12/11/17	0834	170831	9/18	1000	1000	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
ICV	↓	↓	0835	171023	11/18	100	100	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
CCV	T. Riordan	12/14/17	715	171023	11/18	100	98	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
CCV								P/F	L/F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Natalie Ayala	12/11/17	0839	165674	8/18	7.0	7.00	-22.4	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
Calibr.	↓	↓	↓	171629	4/19	4.0	4.00	151.0	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
Calibr.	↓	↓	↓	172191	3/19	10.0	10.01	-198.4	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
ICV	↓	↓	↓	171629	4/19	4.0	3.95	154.1	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
CCV	T. Riordan	12/14/17	715	172191	3/19	10.0	10.12	-204.3	<u>Ⓟ</u> /F	<u>Ⓟ</u> /F
CCV									P/F	L/F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ;

mV pH 4 Range $+180 \pm 50$;

mV pH 10 Range -180 ± 50 ;

If mV are recorded: slope from 7 to 10 , slope from 4 to 7 (both must be between 165 and 180 mV)

Is meter equipped with depth sensor? Yes / No If yes, list date of last quarterly depth verification

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value meters	Pass / Fail	Lab / Field
Pressure mode in air						P/F	L/F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS:

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this page.

Meter ID: Tally / AR

RQ: 2017-11-13-55

Project: SMP

Notes: (1) Always wait for meter to stabilize before recording any readings.

(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).

(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 12/17

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	<u>Leif Boman</u>	<u>12/11/17</u>	<u>8:55</u>	<u>21.38</u>	<u>8.846</u>	<u>8.84</u>	<u>100.0</u>	<u>69.6</u>	<u>0.94655</u>	<u>P</u> / F	<u>L</u> / F
ICV	<u> </u>	<u> </u>	<u>1</u>	<u>21.45</u>	<u>8.829</u>	<u>8.81</u>	<u>99.7</u>	<u>68.6</u>		<u>P</u> / F	<u>L</u> / F
CCV	<u> </u>	<u> </u>	<u>14:35</u>	<u>21.17</u>	<u>8.880</u>	<u>8.87</u>	<u>98.9</u>	<u>56.3</u>	<u>0.94655</u>	<u>P</u> / F	<u>L</u> / F
CCV										P / F	L / F

DO Acceptance criteria from Table ± 0.3 mg/L.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ hos/cm	Meter Reading μ hos/cm	Pass / Fail	Lab / Field
Calibr.	<u>Leif Boman</u>	<u>12/11/17</u>	<u>8:55</u>	<u>170831</u>	<u>09/18</u>	<u>1000</u>	<u>1080</u>	<u>P</u> / F	<u>L</u> / F
ICV	<u> </u>	<u> </u>	<u>1</u>	<u>171629</u>	<u>04/19</u>	<u>100</u>	<u>99</u>	<u>P</u> / F	<u>L</u> / F
CCV	<u> </u>	<u> </u>	<u>14:35</u>	<u>171629</u>	<u>04/19</u>	<u>100</u>	<u>99</u>	<u>P</u> / F	<u>L</u> / F
CCV								P / F	L / F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	<u>Leif Boman</u>	<u>12/11/17</u>	<u>8:55</u>	<u>165674</u>	<u>08/18</u>	<u>7.0</u>	<u>7.00</u>	<u>-20.3</u>	<u>P</u> / F	<u>L</u> / F
Calibr.	<u> </u>	<u> </u>	<u> </u>	<u>171629</u>	<u>04/19</u>	<u>4.0</u>	<u>4.00</u>	<u>135.0</u>	<u>P</u> / F	<u>L</u> / F
Calibr.	<u> </u>	<u> </u>	<u> </u>	<u>172191</u>	<u>03/19</u>	<u>10.0</u>	<u>10.00</u>	<u>-172.9</u>	<u>P</u> / F	<u>L</u> / F
ICV	<u> </u>	<u> </u>	<u> </u>	<u>171629</u>	<u>04/19</u>	<u>4.0</u>	<u>4.00</u>	<u>135.3</u>	<u>P</u> / F	<u>L</u> / F
CCV	<u> </u>	<u> </u>	<u>14:35</u>	<u>172191</u>	<u>03/19</u>	<u>10.0</u>	<u>10.14</u>	<u>-181.1</u>	<u>P</u> / F	<u>L</u> / F
CCV									P / F	L / F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ;

mV pH 4 Range $+180 \pm 50$;

mV pH 10 Range -180 ± 50 ;

If mV are recorded: slope from 7 to 10 _____, slope from 4 to 7 _____ (both must be between 165 and 180 mV)

Is meter equipped with depth sensor? Yes / No If yes, list date of last quarterly depth verification _____

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value meters	Pass / Fail	Lab / Field
Pressure mode in air						P / F	L / F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS: