

Boldly "X" this box if there are qualified data on this page.

7

2018-08-06-45

51 Willows WW

2015-08-27-39

SMP

- (2) Report all digits displayed. **Do not** round before reporting measurements. (See special instructions for depth).
- (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Date of Last Temperature Verification

6/19/18

[illegible]

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15 (Pro DSS 0.75 to 1.50); DO charge N/A. **Steady-state & Galvanic Sensors:** DO Gain & Charge N/A.

[illegible]Conductivity Acceptance criteria $\pm 5\%$ [illegible]

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ; mV pH 4 Range $+180 \pm 50$; mV pH 10 Range -180 ± 50 ;

If mV are recorded: slope from 7 to 10 169, slope from 4 to 7 171 (both must be between 165 and 180 mV)

Does meter have a depth sensor that will be used to measure total depth & sample depth? YES / **NO** / NA (not surf. water project)

If YES, complete daily Calibr. & ICV below and list date of last quarterly depth verification:

If **NO**, what will be used? (circle one) **Secchi Disk Line / Sonar** Unique ID: 3312A ; Date of last verification: 7/10/18

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value, meters	Pass / Fail	Lab / Field
Pressure mode in air						P / F	L / F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or $\pm 0.05m$, whichever is greater.

COMMENTS: