

Quarterly Temperature Verification Regional Operation Centers

DEP SOP FT 1400; Acceptance Criteria for Temp. $\pm 0.5^{\circ}\text{C}$.

Correction factor needed if acceptance criteria are exceeded.

Record all digits displayed for temperature readings. Do not round before reporting measurements.

Meter ID#: 13529 Date of Last Verification: N/A
Date: 1/29/18 Time: 0725 ETZ / CTZ NIST Reference Device ID#: SN 3575
Cold Bath (between $0 - 10^{\circ}\text{C}$): Sonde: 4.0 $^{\circ}\text{C}$; NIST: 4.0 $^{\circ}\text{C}$; Result: PO
Warm Bath (between $30 - 40^{\circ}\text{C}$): Sonde: 36.9 $^{\circ}\text{C}$; NIST: 37.0 $^{\circ}\text{C}$; Result: O
Is Correction Factor Needed? Y / N If yes, describe: _____
Person Performing Verification: J. P. S.

Comments: _____

Meter ID#: _____ Date of Last Verification: _____
Date: _____ Time: _____ ETZ / CTZ NIST Reference Device ID#: _____
Cold Bath (between $0 - 10^{\circ}\text{C}$): Sonde: _____ $^{\circ}\text{C}$; NIST: _____ $^{\circ}\text{C}$; Result: Pass / Fail
Warm Bath (between $30 - 40^{\circ}\text{C}$): Sonde: _____ $^{\circ}\text{C}$; NIST: _____ $^{\circ}\text{C}$; Result: Pass / Fail
Is Correction Factor Needed? Y / N If yes, describe: _____
Person Performing Verification: _____

Comments: _____

Meter ID#: _____ Date of Last Verification: _____
Date: _____ Time: _____ ETZ / CTZ NIST Reference Device ID#: _____
Cold Bath (between $0 - 10^{\circ}\text{C}$): Sonde: _____ $^{\circ}\text{C}$; NIST: _____ $^{\circ}\text{C}$; Result: Pass / Fail
Warm Bath (between $30 - 40^{\circ}\text{C}$): Sonde: _____ $^{\circ}\text{C}$; NIST: _____ $^{\circ}\text{C}$; Result: Pass / Fail
Is Correction Factor Needed? Y / N If yes, describe: _____
Person Performing Verification: _____

Comments: _____