

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Meter ID: 154127 RQ: 2020-10-26-44 Project: 2020 SMP

Body "X" this box if there are qualified data on this page.

- Notes: (1) Always wait for meter to stabilize before recording any readings.
(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).
(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification: 07/20

DO DEP SOP FT 1500	Name	Date	Time CT-8	Temp °C	Baro-meter mmHg	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Ben Harden	10/27/20	0740	21.7	758.6	8.8	8.78	99.9		1.019	0/F	0/F
ICV	"	"	0759	21.8	758.6	8.8	8.79	100.3			0/F	0/F
CCV	"	"	1410	21.8	758.6	8.8	8.91	101.5			0/F	0/F
CCV											P/F	L/F

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15 (Pro DSS 0.75 to 1.50); DO charge N/A. Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-8	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	Ben Harden	10/27/20	0749	20407D	04/21	100	100.2	0/F	0/F
ICV	"	"	0750	20407D	07/21	100.0	99.7	0/F	0/F
CCV	"	"	1411	19107E	10/20	50,000	50354	0/F	0/F
CCV								P/F	L/F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-8	Lot #	Expir. Date	pH Buffer SU	Temp °C	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Ben Harden	10/27/20	0754	200407C	10/21	7.01	21.8	7.02	-13.1	0/F	0/F
Calibr.	"	"	0756	200221A	09/21	4.01	21.7	4.00	167.9	0/F	0/F
Calibr.	"	"	0757	200407A	10/21	10.01	21.8	10.01	-175.3	0/F	0/F
ICV	"	"	0758	"	"	10.01	21.8	9.98	-175.3	0/F	0/F
CCV	"	"	1412	200221A	09/21	4.01	21.7	4.00	165.0	0/F	0/F
CCV										P/F	L/F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ; mV pH 4 Range $+180 \pm 50$; mV pH 10 Range -180 ± 50 .
If mV are recorded: slope from 7 to 10 162.2, slope from 4 to 7 181.0 (both must be between 165 and 180 mV)

Does meter have a depth sensor that will be used to measure total depth & sample depth? YES / NO / NA (not surf. water project)

If YES, complete daily Calibr. & ICV below and list date of last quarterly depth verification: 07/20

If NO, what will be used? Secchi Disk Line / Sonar Unique ID: _____; Date of last verification: _____

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-8	Calibrated Value (0.00 or other), meters	ICV Value, meters	Pass / Fail	Lab / Field
Pressure mode in air	Ben Harden	10/27/20	0744	0.000	0.000	0/F	0/F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS: