

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there are qualified data on this page.

Meter ID: Hedon

RQ- 2020-06-08-41

Project: hmp

- Notes: (1) Always wait for meter to stabilize before recording any readings.
 (2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).
 (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 04/28/20

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp °C	Baro-meter mmHg	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Drew Liddick	06/09	0920	26.1	756.0	8.12 nd	8.02	99.8	—	1.04	(P) F (L) F	F
ICV	"	"	0924	26.0	756.0	8.01	8.03	98.9	—	1.04	(P) F (L) F	F
CCV	Jordan Skaggs	06/09	15:00	28.2	755	7.70	7.69	98.6	—	—	(P) F (L) F	F
CCV											P / F	L / F

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15 (Pro DSS 0.75 to 1.50); DO charge N/A. Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	Drew Liddick	06/09	0926	2911829	10/21	1000	1000	(P) F (L) F	F
ICV	"	"	0928	1002B20	02/22	100	102.8	(P) F (L) F	F
CCV	Jordan Skaggs	06/09	15:05	2911829	10/21	1000	1000	(P) F (L) F	F
CCV								P / F	L / F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Temp °C	Meter reading SU 7.01	mV	Pass / Fail	Lab / Field
Calibr.	Drew Liddick	06/09	0930	194546	07/21	7.0	23.0	27.2	27.4	(P) F (L) F	F
Calibr.	"	"	0932	196401	09/21	4.0	23.2	4.00	145.1	(P) F (L) F	F
Calibr.	"	"	0934	192995	05/21	10.0	23.2	10.02	207.0	(P) F (L) F	F
ICV	"	"	0936	192995	05/21	10.0	23.2	10.04	207.0	(P) F (L) F	F
CCV	Jordan Skaggs	06/09	15:10	194900	02/21	4.0	22.3	4.02	145.5	(P) F (L) F	F
CCV										P / F	L / F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ;

mV pH 4 Range $+180 \pm 50$;

mV pH 10 Range -180 ± 50 ;

If mV are recorded: slope from 7 to 10 179.6, slope from 4 to 7 172.5 (both must be between 165 and 180 mV)

Does meter have a depth sensor that will be used to measure total depth & sample depth? YES / NO / NA (not surf. water project)

If YES, complete daily Calibr. & ICV below and list date of last quarterly depth verification: 04/28/20

If NO, what will be used? (circle one) Secchi Disk Line / Sonar Unique ID: _____; Date of last verification: _____

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value, meters	Pass / Fail	Lab / Field
Pressure mode in air	Drew Liddick	06/09	0938	0.06	0.00	(P) F (L) F	F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS: