

Appendix D

Pre- vs. Post-Construction Beach Photographs



Figure D-1. Pre-Construction Condition near T-104 (Nov. 2020)



Figure D-2. Post-Construction Condition near T-104 (Apr. 2021)



Figure D-3. Pre-Construction Condition near R-105 (Nov. 2020)



Figure D-4. Post-Construction Condition near R-105 (Apr. 2021)



Figure D-5. Pre-Construction Condition near R-106 (Nov. 2020)



Figure D-6. Post-Construction Condition near R-106 (Apr. 2021)



Figure D-7. Pre-Construction Condition near R-107 (Nov. 2020)



Figure D-8. Post-Construction Condition near R-107 (Apr. 2021)



Figure D-9. Pre-Construction Condition near R-108 (Nov. 2020)



Figure D-10. Post-Construction Condition near R-108 (Apr. 2021)



Figure D-11. Pre-Construction Condition near R-109 (Nov. 2020)



Figure D-12. Post-Construction Condition near R-109 (Apr. 2021)



Figure D-13. Pre-Construction Condition near T-110 (Nov. 2020)



Figure D-14. Post-Construction Condition near T-110 (Apr. 2021)



Figure D-15. Pre-Construction Condition near R-111 (Nov. 2020)



Figure D-16. Post-Construction Condition near R-111 (Apr. 2021)



Figure D-17. Pre-Construction Condition near T-112 (Oct. 2020)




Figure D-18. Post-Construction Condition near T-112 (Apr. 2021)



Figure D-19. Pre-Construction Condition near R-113 (Oct. 2020)



Figure D-20. Post-Construction Condition near R-113 (Apr. 2021)



Figure D-21. Pre-Construction Condition near T-114 (Oct. 2020)



Figure D-22. Post-Construction Condition near T-114 (Apr. 2021)



Figure D-23. Pre-Construction Condition near R-115 (Oct. 2020)



Figure D-24. Post-Construction Condition near R-115 (Apr. 2021)