Site Name Pine Log Ck SR2 Walton Co. Date 01/30/2018

WIN ID 33040015 Field ID 33040015

Visit ID 78189

RPS ID 9898

VPDB ID N/A

HA ID 14992

- [x] SCI
- [ ] RPS/LVS Only
- [x] Sample Site Created in SBIO
- [x] Phys/Chem entered in SBIO
- [x] HA entered in SBIO Initial FB ☐ Date and Initial QA: _____
- [x] RPS entered in SBIO Initial FB ☐ Date and Initial QA: _____
- [ ] LVS entered in SBIO Initial _____ ☐ Date and Initial QA: _____
  - [x] < 2 m^2 vegetation
  - [ ] Plants getting verified Date submitted: _____
  - [ ] Plants verified Date returned: _____

Project. Reference Streams.

RQ-2018-01-29-08

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
STRATEGIC MONITORING PROGRAM FIELD SHEET

January 2018

Data Qualified? Yes / (No)

Location/STORET Station Name: PINE LOG CREEK S.R.2 WALTON CO. **Date:** 01/30/2018 (mm/dd/yyyy)

WIN ID 33040015 **WBID:** 101 **Latitude:** 30.898367 (Decimal Degrees)

County: Walton **RQ -** 2018-01-29-08 **ORG ID:** 21FLPNS **Longitude:** -86.348206 (Decimal Degrees)

Receiving Body of Water: Yellow River **Field ID:** 33040015 Time Zone Time @ S:t 11:15 CST

Sampling Team Members	WQ Measurements	Sample Collection	Documentation	Preservation	Preservation Check
Frank Butera					
Stoher Slade					
Whitney Bretana					

Sampling Equipment
- [x] Sample Container [ ] Van Dorn [ ] Pole
- [ ] Carboy [x] Syringe
- [ ] Dipper [ ] Other
- Equipment ID

Collection Method
- [x] Wading [ ] Canoe/Kayak
- [ ] From Shore [ ] Electric Motor
- [ ] Other [ ] Gasoline Motor

Water Level: Dry / (Low) / Normal / Above Normal / Flooded **Meter ID#** 113529 **Matrix:** (Fresh) / Marine / DI

Photos: (Yes) / No **Flow:** No Flow / Intestital (Flowing) / NA **Tide:** Rising/ Falling/ Slack/ (NA) **Tide Times:** High Low

Time Zone	Time	Total Depth (m)	Sample Depth (m)	Secchi Disk (m)	DO (mg/L)	DO (%SAT)	pH	Salinity (PPTh)	Sp COND (µmhos/cm)	Temp. (C°)
(EST)	11:15	0.1	0.05	VOB 71.0m	9.50	88.8	5.24	0.01	33	12.31
CEN										

Biological Samples Collected: None (HA) (SCI) (RPS) Algae ID LVS LVI Other:

SBIO ID Numbers: SBIO-ID: HA-ID: RPS-ID: Macrophyte-ID: LIMS#:

Parameter Suite	Parameter Methods	Preservation	Lot#	Expiration	pH Check
Preserved Nutrients	[x] W-NH3 / W-NO2NO3 / W-TKN / W-TOC / W-S-A-TP	[x] Ice [ ] H_2SO_4	SA7233030	08/21/2018	[x] <2
Metals	[x] W-ICPMS [x] W-ICP	[x] Ice [ ] HNO_3	NA-7226050	08/14/2018	[ ] <2
Filtered Nutrients	[x] W-PO4-F [x] Field Filtered 0.45 µm Filter	[x] Ice	9798594		
Chlorophyll	[x] CHLSUITE-W	[x] Ice			
Physical/Aggregate (Fresh)	[x] Alkalinity / W-F / W-TSS / TURBIDITY / W-Cl-IC / W-COLOR / W-SO4-IC / W-TDS	[x] Ice			
Physical/Aggregate (Marine)	[ ] Alkalinity / W-F / W-TSS / TURBIDITY	[ ] Ice			
Macroinvertebrates	[x] MI-FW-QLDC	[x] Formalin			
Periphyton	[ ] ALGAE-ID	[ ] Ice			
Microbiology	[x] E Coli [x] F Coli [ ] Enterococci	[x] Ice			
Molecular	[ ] PCR-FILTER [x] PCR-HF183 [x] PCR-BacR [ ] PCR-GULL2 [x] PCR-GFD	[x] Ice			
Tracers	[x] W-SUC-AA-R [x] W-UHERB-AA [x] W-AHERB-AA	[x] Ice			
Pesticides	[ ] W-PSNP-TQ [ ] W-UHERB-AA [ ] W-AHERB-AA [ ] W-CARB-AA [ ] W-PCL-SQ-R [ ] W-PYR-AA-R [ ] W-GLYPH [ ] W-SUC-AA-R	[ ] Ice [ ] Other			

Place Preservative Sticker(s) Here (If Available)

Notes:
Project. Reference Streams 2018.
SBIO VISIT ID 78189

Field/WIN ID 33040015

Location PINE LOG CK SR 2 WALTON

Signature: [signature] **Date:** 01/30/2018

Enter Field Parameters, Verify Station ID In LIMS DMT: _____ (Initials/Date) QC Station ID, Field Parameters In LIMS DMT: _____ (Initials/Date)

Scan/Save Field Sheets [initials] (Initials/Date) Migrate Data to WIN: _____ (Initials/Date) Verify Data In WIN: _____ (Initials/Date)

DEP Form FD 9000-3 Physical/Chemical Characterization Field Sheet

SAMPLE ID 78189 ORG ID 21FLPNS LATITUDE 30.898367
COUNTY Walton WIN ID/STORET # 33040015 LONGITUDE -86.348206
DATE 01/30/2018 TIME 11:15 CST SAMPLING AGENCY FL DEP - NWROC
SITE NAME Pine Log Ck SR 2 Walton Co.
FIELD ID/NAME 33040015 RECEIVING BODY OF WATER Yellow River WBID 101 Project Reference Streams

RIPARIAN ZONE / STREAM FEATURES

PREDOMINANT LAND-USE IN WATERSHED (specify relative percent in each category) :

Forest/Natural	Silviculture	Field/Pasture	Agricultural	Residential	Commercial	Industry	Other (Specify)
X	2	2	X				

Landscape Development Intensity Index (LDI)

Local Watershed Erosion (select one) : ☐ None ☐ Slight ☐ Moderate ☒ Heavy

Local Watershed NPS Pollution : ☐ No evidence ☒ Slight ☐ Moderate ☐ Heavy

Typical Width (m) Depth (m)/Velocity (m/sec) Transect

0 m | 6 m wide

.33 m/s	.33 m/s	.33 m/s
0.3 m deep	0.3 m deep	0.3 m deep

Width of Riparian Vegetation (m) on Each Buffer Side
Left Bank : 718 Right Bank : 718

Hydrologic Modification Score (per FT 3101) 2

High Water Mark: 3.0+ (m) + 1.0 (above present water level) = 4.0+ (present depth) (above bed)

Artificially Impounded ☐ Yes ☒ No

Artificially Channelized : ☒ No ☐ Some recovery ☐ Mostly recovered, more sinuous ☐ Recent, severe

Canopy Cover % ☐ Open ☒ Lightly Shaded (11-45%) ☐ Heavily Shaded ☒ Moderate Shaded (46-80%)

SEDIMENT / SUBSTRATE

Sediment Oils ☒ Absent ☐ Slight ☐ Moderate ☐ Profuse

Sediment Odors ☒ Normal ☐ Sewage ☐ Petroleum ☐ Chemical ☐ Anaerobic ☐ Other (Specify) :

Smothering of Substrates

Sand Smothering:	☐ None	☐ Slight	☐ Moderate	☒ Severe
Silt Smothering:	☐ None	☐ Slight	☐ Moderate	☒ Severe
Algae Smothering:	☐ None	☒ Slight	☐ Moderate	☐ Severe

SUBSTRATE TYPE

Assessment Tool: ☒ SCI ☒ RPS ☐ LVS ☐ LCI ☐ BioRecon

	% Coverage	INVERT # Times Sampled	PERI # Times Sampled
Woody Debris (Snags)	7.3	5	
Undercut Banks / Roots	2.6	5	
Leaf Packs or Mat	1.1	5	
Aquatic Vegetation			
Rock or Shell Rubble..			
Sand.....	88.8	3	
Mud / Muck / Silt			
Other GRVL	0.2	2	
Other			

ABUNDANCE

	Not Obs.	Rare	Common	Abundant
Periphyton:	☐	☐	☒	☐
Fish:	☐	☐	☒	☐
Aquatic Plants:	☒	☐	☐	☐
Iron/Sulfur Bacteria:	☒	☐	☐	☐

WATER QUALITY

	Depth (M)	Temp. (°C)	pH (SU)	D.O. (MG/L)	D.O. Sat (%)	Cond. (UMHO/CM)	Salinity (PPT)	SECCHI (M)
Top :	0.05	12.31	5.24	9.50	88.8	33	0.01	
Mid:								☒ VOB
Bottom	0.1							TOTAL DEPTH
Meter ID:	113529 Meter Post-Verify ✓							1.0

Water Odors Normal ☒ Petroleum ☐ Sewage ☐ Chemical ☐ Other ☐

Water Surface Oils Normal ☐ Sheen ☐ Globs ☐ Slick ☐ Other ☐

Water Sample Taken? ☒ Yes ☐ No
Sample Preserved? ☐ Yes ☐ No
Lot Number:_____ Exp:_____

Color Tannic ☒ Green (Algae) ☐ Clear ☐ Other (Specify) ☐

Algae Sample Taken? ☐ Yes ☒ No
Sample Preserved? ☐ Yes ☐ No
Lot Number:_____ Exp:_____

Clarity Clear ☒ Slightly Turbid ☐ Turbid ☐ Opaque ☐

System Type: Stream ☒ Lake ☐ Wetland ☐ Estuary ☐ Other(Specify) ☐

AMBIENT FIELD CONDITIONS / NOTES: RQ-2018-01-29-08
< 2m² Veg. No LVS. Collapsed Banks

☒ The antecedent hydrologic conditions have been met to my best knowledge.

SAMPLING TEAM: Frank Butera, Stopher Slade, Whitney Bretana

SIGNATURE: [signature]

DATE : 1/30/2018

Stream/River Habitat Sketch Sheet, Form FD 9000-4 (June 1, 2001)_
Length of grid represents 100 m of stream (not linear meters).
(Horizontal scale is double vertical scale, draw proportionately).



WIN ID 33040015

Substrates: Code key, draw proportionate habitat abundance.

- 1 Snags 44/600 = 7.3
- S Roots/undercut banks 15.9/600 = 2.6
- O Leaf Packs (or mats) 6.6/600 = 1.1
- △ Macrophytes
- E Erosion/slough
- S Silt / BG = Blue Green
- P Pool / Gravel 1.9/600 = 0.2

Velocity:
Note where velocity measures were taken (B) 0 m

Habitat Smothering:
Note areas (on map) where sand or silt is something substrates, limiting habitability.

Bank Stability:
Note areas (on map) with unstable, eroding banks.

Riparian Buffer Width:
Note areas (on map) where natural vegetation is altered or eliminated.

Average width 6 m
Average depth 0.3 m
WQ & chemistry taken @ 0 m
SBIO ID 781
Pine Log Ck. S.R. 2 Walton Co.
Project. Reference Streams
Sampled By/Date: FS / 01-30-18

0 m Latt. 34.89853
0 m Long. 86.34839
100 m Latt 34.89893
100 m Long 86.34861

DEP Form FD 9000-5 Stream/River Habitat Assessment Field Sheet

SAMPLING AGENCY: 21FLPNS		STORET STATION NUMBER: 33040015	DATE (MM/DD/YY): 01/30/2018	RECEIVING BODY OF WATER: Yellow River
REMARKS: WBID 101	COUNTY: Walton	LOCATION: Pine Log Ck. S.R. 2 Walton Co.		FIELD ID/NAME: 33040015

Habitat Parameter	Optimal	Suboptimal	Marginal	Poor
Primary Habitat Components **Substrate Diversity** 13	Four or more major productive habitats present [snags, tree roots, aquatic vegetation, leaf packs (partially decayed), rock] 20 19 18 17 16	Three major productive habitats present. Adequate habitat. Some substrates may be new fall (fresh leaves or snags) 15 14 (13) ~~12~~ 12 11	Two major productive habitats present. Less than desirable habitat, frequently disturbed or removed 10 9 8 7 6	One or less major productive habitat. Lack of habitat is obvious, substrates unstable or smothered 5 4 3 2 1
Substrate Availability 8	Greater than 30% major productive habitat present at site 20 19 18 17 16	16% to 30% major productive habitat, by aerial extent 15 14 13 12 11	6% to 15% major productive habitat 10 9 (8) 7 6	Less than 5% major productive habitat 5 4 3 2 1
Water Velocity 20	Max. observed at typical transect: > 0.25 m/sec. But < 1 m/sec ≥0.33 0.31 0.29 0.27 >0.25 (20) 19 18 17 16	Max. observed at typical transect: >0.1 to 0.25 m/sec 0.25 0.21 0.17 0.13 >0.1 15 14 13 12 11	Max. observed at typical transect: 0.05 to 0.1 m/sec 0.1 0.09 0.07 0.06 0.05 10 9 8 7 6	Max. observed at typical transect: <0.05 m/sec; or spate occurring: > 1 m/sec <0.05 0.04 0.03 0.01 <0.01 5 4 3 2 1
Habitat Smothering 16 Primary Score 57	Adequate number of stable pools (1-2 per 12 times width) and <25% of habitats affected by sand, silt, or algae. 20 19 18 17 (16)	Adequate number of stable pools (1-2 per 12 times width) and >25% of habitats affected by sand, silt, or algae. 15 14 13 12 11	Does not have required number of stable pools (1-2 per 12 x width) and/or has shallow pools (<2 x prevailing depth). 10 9 8 7 6	Stable pools are absent. Most habitats affected by sand, silt, or algae accumulation. 5 4 3 2 1
Secondary Habitat Components **Artificial Channelization** 20	Expected sinuosity given the stream width. No evidence of dredging or artificial straightening. No spoil banks. (20) 19 18 17 16	Good sinuosity within old channelized area. Evidence of dredging in the past (>25 yrs) but mostly recovered. 15 14 13 12 11	Straightened with trapezoidal cross section, but has a small degree of sinuosity developed within channelized area. 10 9 8 7 6	Straightened or engineered by dredging, has trapezoidal or box cut cross section, lacks required pools. May have spoil banks. 5 4 3 2 1
Bank Stability Right Bank 5 Left Bank 4	Bankfull > 60% of bank height. Slope of bank ≤ 60° from bankful to top of bank. Bankfull is within or above the root zone with few raw, eroded areas. 10 9	Only meets 2 of the 3 requirements for optimal bank stability. 8 7 6	Only meets 1 of the 3 requirements for optimal bank stability. (5) (4)	Bankfull < 60% of bank height. Slope of bank > 60°. Bankfull is below the root zone with raw, eroded areas. 3 2 1
Riparian Buffer Zone Width Right Bank 10 Left Bank 10	Width of vegetation greater than 18 m (10) 9	Width of vegetation >12 to 18m 8 7 6	Width of vegetation 6 to 12 m. human activities close to system 5 4	Less than 6 m of buffer zone due to intensive human activities 3 2 1
Riparian Zone Vegetation Quality Right Bank 9 Left Bank 9 Secondary Score 67	Over 80% of riparian surfaces consist of normal, expected plant community for given sunlight & habitat conditions (e.g., native plants; tree, shrub, and forbs represented, if appropriate). Minimal disturbance. 10 (9)	>50% to 80% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Some disruption in community observed. 8 7 6	25% to 50% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Disruption obvious. 5 4	Less than 25% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). 3 2 1

124 **TOTAL SCORE** 124/160 = 77.5%

Date: 01/30/2018	Analyst: F. Butera	Signature:

SBIO ID: 78189 HA ID: 14992

62-160.800, F.A.C.

Revision Date: March 1, 2014

DEP FORM FD 9000-25 Rapid Periphyton Survey Field Sheet

Site: Pine Log Ck SR 2 Walton Co. | County: Walton | Date: 01/30/2018 | Investigators: F. BUTERA

STORET Station Number: 33040015

Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover
0	1	N	NO	
	2			
	3			
	4			
	5			67
	6			
	7			
	8			
	9	N	NO	
10	1	N	NO	
	2			
	3			
	4			
	5			45
	6			
	7			
	8			
	9			
20	1	3	NO	
	2	3		
	3	N		
	4			
	5			5.0
	6			
	7			
	8			
	9			
30	1	N	NO	
	2			
	3			
	4			
	5			40
	6			
	7			
	8			
	9	N	NO	
40	1	N	NO	
	2			
	3			
	4			
	5			
	6			80
	7			
	8			
	9			
50	1	N	NO	
	2			
	3			
	4			
	5			75
	6			
	7			
	8			
	9			

Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover
60	1	N	NO	
	2			
	3			
	4			
	5			90
	6			
	7			
	8			
	9	N	NO	
70	1	N	NO	
	2			
	3			
	4			
	5			83
	6			
	7	3 N		
	8			
	9			
80	1	N	NO	
	2			
	3			
	4			
	5			90
	6	3		
	7	N		
	8			
	9			
90	1	N	NO	
	2			
	3			
	4			
	5			70
	6			
	7		NO	
	8		NO	
	9	N	NO	
100	1	N	NO	
	2			
	3			
	4			
	5			~~74~~ 35
	6			30
	7			
	8			
	9			

Secchi depth	0.8
Estimated?	No

# points ranked 4-6	0
total points assessed	99
% points ranked 4-6	0

Check accompanying data collected at same site/date.	
Algal mat sample	
Linear Veg Survey	
Habitat Assessment	✓
SCI/Biorecon	✓
Water sample	✓
RQ-2018-01-29-08	

Algal Thickness Rank	
N	rough, no algae, slimy, algae up to 1mm
3	>1mm - 6mm
4	>6mm - 20mm
5	>20mm - 10 cm
6	>10 cm

~~Amec Foster Wheeler~~
SBIO ID 78189
RPS ID 9898

Record "N" and check "Estimated" for points deeper than the Secchi depth; algae are presumed absent. Check "Estimated" if thickness estimated for deep points which can be seen but not reached.

Record "X" for points shallower than Secchi depth for which substrate cannot be seen or reached with the hand. No estimated rank.

Record canopy cover as the number of small densiometer quadrants (out of 96) that HAVE canopy cover. Measure facing upstream at point 4, 5, or 6.

Collect algal mat sample following DEP SOP FS 7240 if the percentage of total sampled points with a thickness rank of 4, 5, or 6 is >20%.

DEP FORM FD 9000-32: LINEAR VEGETATION SURVEY FIELD SHEET

Pine Log Ck SR 2 Walton Co.	Date: 1/30/18	County: Walton	Storet Number: 33040015
Analyst: [illegible]		Signature:	

Comments: SBIO ID: 78189 Macro ID: N/A NO Aquatic Veg - LUS not performed

Instructions: Note taxa growing in the water with a checkmark if present, "D" if dominant, and "C" if codominant (dominance only if 1 m^2 of taxa present). Note in the boxes below if no dominant are selected, and note total macrophyte abundance rank for each section. Only the most common taxa are listed, so use blank spaces for additional taxa names.

HERBACEOUS SPECIES	Meter Mark 0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100	Specimen collected (check)
Alternanthera philoxeroides											
Bacopa caroliniana											
Bacopa monneri											
Bidens mitis											
Boehmeria cylindrica											
Centella asiatica											
Ceratophyllum demersum											
Chara											
Cicuta maculata											
Cladium jamaicense											
Colocasia esculenta											
Commelina diffusa											
Commelina virginica											
Crinum americanum											
Diodia virginiana											
Eichhornia crassipes											
Eleocharis (wispy viviparous)											
Hydrilla verticillata											
Hydrocotle											
Hygrophila polysperma											
Hymenocallis											
Lachnanthes caroliniana											
Landoltia punctata											
Lemna											
Limnophila sessiflora											
Ludwigia leptocarpa											
Ludwigia palustris											
Ludwigia peruviana											
Ludwigia repens											
Luziola fluitans											
If no Dominant or Co-Dominant were selected, indicate with "X"	X	X	X	X	X	X	X	X	X	X	
Indicate % cover macrophytes per section											
0-5% Macrophyte Coverage	X	X	X	X	X	X	X	X	X		
>5 and ≤10% Macrophyte Coverage											
>10 and ≤25% Macrophyte Coverage											
>25 and ≤50% Macrophyte Coverage											
> 50% Macrophyte Coverage											

HERBACEOUS SPECIES	Meter Mark 0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100	Specimen collected (check)
Micranthemum glomeratum											
Micranthemum umbrosum											
Myriophyllum aquaticum											
Najas guadelupensis											
Nuphar luteum											
Orontium aquaticum											
Panicum hemitomon											
Panicum repens											
Panicum rigidulum											
Pistia stratioides											
Polygonum glabra											
Polygonum hydropiperoides											
Polygonum punctatum											
Pontedaria cordata											
Potamogeton illinoensis											
Ruellia simplex											
Sacciolepis striata											
Sagittaria kurziana											
Sagittaria lancifolia											
Sagittaria latifolia											
Salvinia minima											
Samolus parviflora											
Saururus cernuus											
Sparganium americanum											
Typha											
Vallisneria americana											
Zizania aquatica											

3304015
Pineloy Ck.

Plants see observed
out of Banks

1/30/2018

American Holly
MAG GRAND
Ac. Sp Magnum
Oak - Water Oak
Sweet Gum
Yaupon Holly
Rubus
Smilax
Cyrilla
Quercus Michauxii
BLACK Gum (Liquid AMBAR STYRA.)

FedEx Express **Package US Airbill**

FedEx Tracking Number 8119 7781 0902

Form ID No. 0215

1/31/2018 9:58 EST

Sender's Copy

m *Please print and press hard.*

01/30/2018 Sender's FedEx Account Number

SENDER'S FEDEX ACCOUNT NUMBER ONLY

der's FRANK BUTERA Phone (850 595-8340

pany FL DEP - NW ROC

ress 160 W. GOVERNMENT St. Dept/Floor/Suite/Room

PENSACOLA State FL ZIP 32502

r Internal Billing Reference OPTIONAL
4 characters will appear on invoice.

pient's SAMPLE RECEIVING Phone (850) 245-8085

pany FLORIDA DEP/CHEMISTRY SECTION

ress 2600 BLAIRSTONE RD
annot deliver to P.O. boxes or P.O. ZIP codes. Dept/Floor/Suite/Room

Hold Weekday FedEx location address REQUIRED. NOT available for FedEx First Overnight.

Hold Saturday FedEx location address REQUIRED. Available ONLY for FedEx Priority Overnight and FedEx 2Day to select locations.

ress
his line for the HOLD location address or for continuation of your shipping address.

TALLAHASSEE State FL ZIP 32399

0127857428

Ship it. Track it. Pay for it. All online. Go to fedex.com

4 Express Package Service

* To most locations.

Packages up to 150 lbs. *For packages over 150 lbs., use the FedEx Express Freight US Airbill.*

Next Business Day

- ☐ FedEx First Overnight — Earliest next business morning delivery to select locations. Friday shipments will be delivered on Monday unless Saturday Delivery is selected.
- ☒ FedEx Priority Overnight — Next business morning.* Friday shipments will be delivered on Monday unless Saturday Delivery is selected.
- ☐ FedEx Standard Overnight — Next business afternoon.* Saturday Delivery NOT available.

2 or 3 Business Days

- ☐ FedEx 2Day A.M. — Second business morning.* Saturday Delivery NOT available.
- ☐ FedEx 2Day — Second business afternoon.* Thursday shipments will be delivered on Monday unless Saturday Delivery is selected.
- ☐ FedEx Express Saver — Third business day.* Saturday Delivery NOT available.

5 Packaging

* Declared value limit $500.

☐ FedEx Envelope* ☐ FedEx Pak* ☐ FedEx Box ☐ FedEx Tube ☒ Other

6 Special Handling and Delivery Signature Options

Fees may apply. See the FedEx Service Guide.

☐ Saturday Delivery — NOT available for FedEx Standard Overnight, FedEx 2Day A.M., or FedEx Express Saver.

☐ No Signature Required — Package may be left without obtaining a signature for delivery.

☐ Direct Signature — Someone at recipient's address may sign for delivery.

☐ Indirect Signature — If no one is available at recipient's address, someone at a neighboring address may sign for delivery. For residential deliveries only.

Does this shipment contain dangerous goods?

One box must be checked.

☒ No ☐ Yes As per attached Shipper's Declaration. ☐ Yes Shipper's Declaration not required. ☐ Dry Ice Dry Ice, 9, UN 1845 _____ x _____ kg

Restrictions apply for dangerous goods — see the current FedEx Service Guide. ☐ Cargo Aircraft Only

7 Payment *Bill to:*

Enter FedEx Acct. No. or Credit Card No. below.

☐ Sender Acct. No. in Section 1 will be billed. ☒ Recipient ☐ Third Party ☐ Credit Card ☐ Cash/Check

FedEx Acct. No. / Credit Card No. 4490-2262-9 Exp. Date

Total Packages	Total Weight	Total Declared Value†
1	60 lbs.	$ 0 .00

†Our liability is limited to US$100 unless you declare a higher value. See back for details. By using this airbill you agree to the service conditions on the back of this airbill and in the current FedEx Service Guide, including terms that limit our liability.

611

Rev. Date 5/15 • Part #163134 • ©1994–2015 FedEx • PRINTED IN U.S.A. SRM