

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this anaer.

Meter ID:

7

RQ:

2018-01-22-33

Project:

SNELL CREEK

Notes: (1) Always wait for meter to stabilize before recording any readings.

(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).

(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification

1/8/18

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	JOHN BARRINGTON	1/17/18	0740	25.7	8.2	8.2	100	43.1	0.92	(P) F	(L) F
ICV	JOHN BARRINGTON	1/17/18	0742	25.4	8.2	8.4	101	42.0	-	(P) F	(L) F
CCV	Steve COFAR	1/17/18	1353	23.7	8.4	8.5	100	41.0	-	(P) F	(L) F
CCV										P / F	L / F

DO Acceptance criteria from Table ± 0.3 mg/L.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	JOHN BARRINGTON	1/17/18	0744	17211D	12/18	500	500	(P) F	(L) F
ICV	JOHN BARRINGTON	1/17/18	0746	17211C	12/18	1000	1032	(P) F	(L) F
CCV	Steve COFAR	4/17/18	1405	17042A	5/18	10,000	9978	(P) F	(L) F
CCV								P / F	L / F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	JOHN BARRINGTON	1/17/18	0748	176157	8/19	7.0	7.0	-35.5	(P) F	(L) F
Calibr.	JOHN BARRINGTON	1/17/18	0750	176044	8/19	4.0	4.0	137.5	(P) F	(L) F
Calibr.	JOHN BARRINGTON	1/17/18	0752	172962	4/19	10.0	10.0	-24.0	(P) F	(L) F
ICV	JOHN BARRINGTON	1/17/18	0754	176044	8/19	4.0	3.9	136.6	(P) F	(L) F
CCV	Steve COFAR	1/17/18	1405	172962	4/19	10.0	10.0	-24.7	(P) F	(L) F
CCV									P / F	L / F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ; mV pH 4 Range $+180 \pm 50$; mV pH 10 Range -180 ± 50 ;

If mV are recorded: slope from 7 to 10 -172.5 , slope from 4 to 7 173 (both must be between 165 and 180 mV)

Is meter equipped with depth sensor? Yes ☒ No ☐ If yes, list date of last quarterly depth verification

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value meters	Pass / Fail	Lab / Field
Pressure mode in air						P / F	L / F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS: