

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on

Meter ID:

YSI 556 #1

Project:

Rose C SCT

RQ-2016-04-11-12

- Notes: (1) Numbers ≤ 4 , are rounded down; numbers ≥ 5 are rounded up (e.g., 5.15 becomes 5.2).
 (2) Always wait for meter to stabilize before recording any readings.
 (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Lab

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification

04/16

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass /	Lab /
Calibr.	B Davis	4/18/16	805	23.46	8.49	8.49	100	-	-	P	L
ICV	↓	↓	806	23.47	8.49	8.50	100	-	-	P	L
CCV	↓	↓	1555	24.6	8.32	8.27	99.3	-	-	P	L
CCV											

Report DO mg/L with one decimal figure and DO % saturation as a whole number with no decimals.
 Acceptance criteria from Table ± 0.3 mg/L. Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A. Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec.	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ hos/cm	Meter Reading μ hos/cm	Pass /	Lab /
Cond.									
Calibr.	B Davis	4/18/16	808	160216A	02/17	1000	1000	P	L
ICV	↓	↓	809	160216A	02/17	1000	1000	P	L
CCV	B Davis	4/18/16	1558	160216B	08/16	100	102	P	L
CCV									

Report specific conductance as a whole number with no decimal figure. Conductivity Acceptance criteria $\pm 5\%$

pH	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass /	Lab /
DEP SOP										
Calibr.	B Davis	4/18/16	817	2509677	8/17	7.0	7.0	-	P	L
Calibr.	↓	↓	820	2509F74	9/17	4.0	4.0	-	P	L
Calibr.	↓	↓	823	2510H88	4/17	10.0	10.0	-	P	L
ICV	↓	↓	825	2509677	8/17	7.0	7.04	-17.5	P	L
CCV	↓	↓	1600	2509F74	9/17	4.0	4.15	132.3	P	L
CCV										

Report pH with one decimal place; pH Acceptance criteria ± 0.2 SU; mV pH7 Range 0 $\pm$ 50; mV pH 4 Range +180 $\pm$ 50;
 mV pH 10 Range -180 $\pm$ 50; Slope from 7 to 10 and 4 to 7 must be between 165 and 180 m

Depth (Quarterly)

Date of Last Depth Verification

Depth Sensor	Name	Date	Time	Zero the Sensor	ICV Value	Pass /	Lab /
Pressure mode in air				0.000			

ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater