

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this name.

Meter ID:

A

Project:

Indian Creek

- Notes: (1) Numbers ≤ 4 , are rounded down; numbers ≥ 5 are rounded up (e.g., 5.15 becomes 5.2).
 (2) Always wait for meter to stabilize before recording any readings.
 (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 1/7/16

DO DEP SOP FT 1500	Name	Date	Time (ET)	Temp. (°C)	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Chris Link	3/30/16	0730	23.6	8.4	8.4	100	56.3		P F	L F
ICV	"	"	0732	23.6	8.4	8.4	99.0	55.3		P F	L F
CCV	Kaitlin DeFesth	3/30/16	1130	23.3	8.4	8.0	96.5	57.4		P F	L F
CCV										P F	L F

Report DO mg/L with one decimal figure and DO % saturation as a whole number with no decimals.

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time (ET)	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	Chris Link	3/30/16	0734	150915D	9/16	1000	1000	P F	L F
ICV	"	"	0736	150915D	9/16	1000	1001	P F	L F
CCV	Kaitlin DeFesth	3/30/16	1131	150915E	9/16	500	503	P F	L F
CCV								P F	L F

Report specific conductance as a whole number with no decimal figure. Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time (ET)	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Chris Link	3/10/16	0739	156244	6/17	7.0	7.0	-63.1	P F	L F
Calibr.	"	"	0741	160222B	3/17	4.0	4.0	64.3	P F	L F
Calibr.	"	"	0744	150915D	3/17	10.0	10.0	-238.1	P F	L F
ICV	"	"	0745	150915D	3/17	10.0	9.9	-235.5	P F	L F
CCV	Kaitlin DeFesth	3/30/16	1133	160222B	3/17	4.0	4.0	112.0	P F	L F
CCV									P F	L F

Report pH with one decimal place; pH Acceptance criteria ± 0.2 SU; mV pH7 Range 0 ± 50 ; mV pH 4 Range $+180 \pm 50$;
 mV pH 10 Range -180 ± 50 ; Slope from 7 to 10 and 4 to 7 must be between 165 and 180 mV

Depth (Quarterly)

Date of Last Depth Verification

Depth Sensor (Daily)	Name	Date	Time CT-ET	Zero the Sensor	ICV Value	Pass / Fail	Lab / Field
Pressure mode in air				0.000			

ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater

Notes:

Field Meter Calibration Log

Meter ID:

YSI multiprobe

		Date	3-29-16	3-30-16	3-31-16	4-14-16	4-26-16
AM	pH 4.00		4	4	4	4	4
	pH 7.00		7	7	7	7	7
	pH 10.00		10	10	10	10	10
	Cond 147						
	Cond 717.5						
	Cond 1413						
	@ Temp						
	DO %		100.2	100.4	100.3	100.1	100.6
	DO @ Temp		25.41	23.78	24.69	24.61	24.77
PM	pH all		4/7/10	4/7/10	4/7/10	4/7/9.99	4/7/10
	Cond		—	—	—	—	—
	DO% @ Temp		100.3 / 26.48	100.4 / 25.54	100.3 / 25.81	100.1 / 26.00	99.9 / 25.96
	Batteries		48%	48%	48%	48%	46%
	Comments						
	User		J.D.F.	J.D.F.	J.D.F.	J.D.F.	J.D.F.