

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this page.

Meter ID: Betty 67

RQ: 2017-12-18-26

Project: SMP

Notes: (1) Always wait for meter to stabilize before recording any readings.

(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).

(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification

12/17

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Natalie Ayala	12/19/17	755	22.28	8.693	8.70	100.2	28.8	1.11345	☒ F	☒ F
ICV	↓	↓	↓	22.34	8.693	8.77	100.9	28.8	↓	☒ F	☒ F
CCV	Natalie Ayala	12/19/17	1710	23.00	8.578	8.41	98.0	28.8	1.11345	☒ F	☒ F
CCV										P/F	L/F

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	Natalie Ayala	12/19/17	757	170831	09/18	1000	1000	☒ F	☒ F
ICV	↓	↓	↓	171023	11/18	100	99	☒ F	☒ F
CCV	Natalie Ayala	12/19/17	1712	171023	11/18	100	98	☒ F	☒ F
CCV								P/F	L/F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Natalie Ayala	12/19/17	0810	165674	08/18	7.0	7.00	-22.8	☒ F	☒ F
Calibr.	↓	↓	↓	171629	04/19	4.0	4.00	151.5	☒ F	☒ F
Calibr.	↓	↓	↓	172191	03/19	10.0	10.00	-198.6	☒ F	☒ F
ICV	↓	↓	↓	172191	04/03/19	10.0	10.00	-198.4	☒ F	☒ F
CCV	Natalie Ayala	12/19/17	1714	171629	04/19	4.0	4.02	150.5	☒ F	☒ F
CCV									P/F	L/F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ;

mV pH 4 Range $+180 \pm 50$;

mV pH 10 Range -180 ± 50 ;

If mV are recorded: slope from 7 to 10 _____, slope from 4 to 7 _____ (both must be between 165 and 180 mV)

Is meter equipped with depth sensor? Yes / No If yes, list date of last quarterly depth verification _____

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value meters	Pass / Fail	Lab / Field
Pressure mode in air						P/F	L/F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS: