

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this page

Meter ID:

Li1 Bit

Project:

SMP: Ten Thousand Islands

- Notes: (1) Numbers ≤ 4 , are rounded down; numbers ≥ 5 are rounded up (e.g., 5.15 becomes 5.2).
 (2) Always wait for meter to stabilize before recording any readings.
 (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification

2/7/17

DO DEP SOP FT 1500	Name	Date	Time (ET)	Temp. (°C)	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Veronica Ruge	3/21/17	0700	25.0	8.3	8.3	99.5			P F	L F
ICV	" "		0705	25.0	8.3	8.3	99.5			P F	L F
CCV	Rosemary Murphy	↓	1645	24.3	8.3	8.1	98			P F	L F
CCV				24.5	8.3	8.3	99.2			P F	L F

Report DO mg/L with one decimal figure and DO % saturation as a whole number with no decimals.

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time (ET)	Lot #	Expir. Date	Standard μ hos/cm	Meter Reading μ hos/cm	Pass / Fail	Lab / Field
Calibr.	Veronica Ruge	3/21/17	0708	161216A	12/17	1000	1000	P F	L F
ICV	" "		0710	161216B	6/17	100	103	P F	L F
CCV	Rosemary Murphy	↓	1415	2511C38	11/17	50000	50030	P F	L F
CCV								P F	L F

Report specific conductance as a whole number with no decimal figure.

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time (ET)	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Veronica Ruge	3/21/17	0712	164224	6/18	7.0	7.0	-30.2	P F	L F
Calibr.	" "		0714	167431	11/18	4.0	4.0	100.8	P F	L F
Calibr.	" "		0716	161216C	6/18	10.0	10.0	-160.5	P F	L F
ICV	" "	↓	0718	167431	11/18	4.0	4.0	99.8	P F	L F
CCV	Rosemary Murphy		1620	167431	11/18	4.0	4.1	91.6	P F	L F
CCV									P F	L F

Report pH with one decimal place; pH Acceptance criteria ± 0.2 SU; mV pH7 Range 0 ± 50 ;

mV pH 4 Range $+180 \pm 50$;

mV pH 10 Range -180 ± 50 ; Slope from 7 to 10 and 4 to 7 must be between 165 and 180 mV

Depth (Quarterly)

Date of Last Depth Verification

Depth Sensor (Daily)	Name	Date	Time CT-ET	Zero the Sensor	ICV Value	Pass / Fail	Lab / Field
Pressure mode in air				0.000			

ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater

Notes: