

Quarterly Temperature Verification Regional Operation Centers

DEP SOP FT 1400; Acceptance Criteria for Temp. $\pm 0.5^{\circ}\text{C}$.

Correction factor needed if acceptance criteria are exceeded.

Record all digits displayed for temperature readings. Do not round before reporting measurements.

Meter ID#:	<u>132237</u>	Date of Last Verification:	<u>9/27/17</u>			
Date:	<u>1/22/18</u>	Time:	<u>0715</u> ETZ / <u>CTZ</u> NIST Reference Device ID#:	<u>SN 3575</u>		
Cold Bath (between 0 – 10°C):	Sonde:	<u>5.4</u> °C;	NIST:	<u>5.2</u> °C;	Result:	<u>Pass</u> / Fail
Warm Bath (between 30 – 40°C):	Sonde:	<u>36.7</u> °C;	NIST:	<u>36.4</u> °C;	Result:	<u>Pass</u> / Fail
Is Correction Factor Needed?	Y / <u>N</u>	If yes, describe: _____				
Person Performing Verification:	<u>J. PINS</u>					

Comments: _____

Meter ID#:	_____	Date of Last Verification:	_____			
Date:	_____	Time:	_____	ETZ / CTZ	NIST Reference Device ID#:	_____
Cold Bath (between 0 – 10°C):	Sonde:	_____ °C;	NIST:	_____ °C;	Result:	Pass / Fail
Warm Bath (between 30 – 40°C):	Sonde:	_____ °C;	NIST:	_____ °C;	Result:	Pass / Fail
Is Correction Factor Needed?	Y / N	If yes, describe: _____				
Person Performing Verification:	_____					

Comments: _____

Meter ID#:	_____	Date of Last Verification:	_____			
Date:	_____	Time:	_____	ETZ / CTZ	NIST Reference Device ID#:	_____
Cold Bath (between 0 – 10°C):	Sonde:	_____ °C;	NIST:	_____ °C;	Result:	Pass / Fail
Warm Bath (between 30 – 40°C):	Sonde:	_____ °C;	NIST:	_____ °C;	Result:	Pass / Fail
Is Correction Factor Needed?	Y / N	If yes, describe: _____				
Person Performing Verification:	_____					

Comments: _____