

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this name.

Meter ID:

Leia

Project:

2018-04-23-05

- Notes:** (1) Numbers ≤ 4 , are rounded down; numbers ≥ 5 are rounded up (e.g., 5.15 becomes 5.2).
 (2) Always wait for meter to stabilize before recording any readings.
 (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 3/29/18

DO DEP SOP FT 1500	Name	Date	Time (ET)	Temp. (°C)	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	H-SPRINKLE	5/10	0710	23.6	8.482	—	100.1	—	—	(P) F	(L) F
ICV			0712	23.6	8.482	8.50	100.5	—	—	(P) F	(L) F
CCV			1456	27.5	7.898	7.90	101.0	—	—	(P) F	(L) F
CCV										P F	L F

Report DO mg/L with one decimal figure and DO % saturation as a whole number with no decimals.

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time (ET)	Lot #	Expir. Date	Standard μ hos/cm	Meter Reading μ hos/cm	Pass / Fail	Lab / Field
Calibr.	H-SPRINKLE	5/10	0715	2711453	10/19	1000	1000	(P) F	(L) F
ICV			0716	1711050	10/19	100	100.6	(P) F	(L) F
CCV			1459	2707875	06/19	500	506	(P) F	(L) F
CCV								P F	L F

Report specific conductance as a whole number with no decimal figure.

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time (ET)	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	H-SPRINKLE	5/10	0720	177435	10/19	7.0	7.01	-15.2	(P) F	(L) F
Calibr.			0722	177759	10/20	4.0	4.00	164.2	(P) F	(L) F
Calibr.			0724	173794	05/19	10.0	10.00	-192.4	(P) F	(L) F
ICV			0727	173794	05/19	10.0	9.98	—	(P) F	(L) F
CCV			1502	177435	10/19	7.0	7.04	—	(P) F	(L) F
CCV									P F	L F

Report pH with one decimal place; pH Acceptance criteria ± 0.2 SU; mV pH7 Range 0 $\pm$ 50;

mV pH 4 Range +180 $\pm$ 50;

mV pH 10 Range -180 $\pm$ 50; Slope from 7 to 10 and 4 to 7 must be between 165 and 180 mV

Depth (Quarterly)

Date of Last Depth Verification

Depth Sensor (Daily)	Name	Date	Time CT-ET	Zero the Sensor	ICV Value	Pass / Fail	Lab / Field
Pressure mode in air				0.000			

ICV-acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater

Notes: