

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Meter ID:

KEYS

RQ:

2019-07-15-29

Project:

SMP: Canals

Boldly "X" this box if there are questionable data on this page.

- Notes: (1) Always wait for meter to stabilize before recording any readings.
 (2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).
 (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 06/18/19

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp °C	Baro-meter mmHg	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Nicole Reistad	07/18/19	0711	24.0	760	8.4	8.41	100.0	NR		P / F	L / F
ICV			0715	23.1	760	8.6	8.56	100.0			(P) / F	(L) / F
CCV			0716	22.8	760	8.6	8.58	99.6			(P) / F	(L) / F
CCV			1428	23.9	760	8.4	8.26				(P) / F	(L) / F

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15 (Pro DSS 0.75 to 1.50); DO charge N/A. Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	Nicole Reistad	07/18/19	0717	2404E34	04/21	1000	1000	(P) / F	(L) / F
ICV			0719	2804A90	04/20	500	506	(P) / F	(L) / F
CCV			1424	2904D82	04/21	100	99	(P) / F	(L) / F
CCV								P / F	L / F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Temp °C	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Nicole Reistad	07/18/19	0727	191304	03/21	7.	24.2	7.00	+2.6	(P) / F	(L) / F
Calibr.			0728	191303	03/21	4.	24.6	4.00	+33.6	(P) / F	(L) / F
Calibr.			0730	191040	03/21	10.	24.8	10.00	-145.3	(P) / F	(L) / F
ICV			0740	191303	03/21	4	23.9	3.99	136.0	(P) / F	(L) / F
CCV			1426	191040	03/21	10	23.5	9.58	-121.1	(P) / F	(L) / F
CCV								9.58		P / F	L / F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ; mV pH 4 Range $+180 \pm 50$; mV pH 10 Range -180 ± 50 ;

If mV are recorded: slope from 7 to 10 _____, slope from 4 to 7 _____ (both must be between 165 and 180 mV)

Does meter have a depth sensor that will be used to measure total depth & sample depth? YES / **NO** / NA (not surf. water project)

If YES, complete daily Calibr. & ICV below and list date of last quarterly depth verification:

If NO, what will be used? (circle one) **Secchi Disk Line** / Sonar Unique ID: **DEEPER BLUER** Date of last verification: **06/18/19**

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value, meters	Pass / Fail	Lab / Field
Pressure mode in air						P / F	L / F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS: