

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Meter ID: 55072

RO: 2020-11-30-43

Project: SMP

Boldly "X" this box if there are qualified data on this page.

Notes: (1) Always wait for meter to stabilize before recording any readings.

(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).

(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 10/13/20

DO	Name	Date	Time CT-ET	Temp °C	Baro-meter mmHg	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
DEP SOP FT 1500												
Calibr.	H Schmidt	12/2	0749	18.3	770	9.5	9.63	100.9			P/F	L/F
ICV	↓	↓	0756	18.3	770	9.5	9.63	100.9			P/F	L/F
CCV	↓	↓	15:44	18.9	767	9.4	9.60	102.5			P/F	L/F
CCV											P/F	L/F

DO Acceptance criteria from Table ± 0.3 mg/L. Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15 (Pro/DSS 0.75 to 1.50); DO charge N/A. Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond.	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard umhos/cm	Meter Reading umhos/cm	Pass / Fail	Lab / Field
FT 1200									
Calibr.	H Schmidt	12/2	0751	20024B	2/21	1000	1000	P/F	L/F
ICV	↓	↓	0753	20103A	10/24	100	101.3	P/F	L/F
CCV	↓	↓	1552	20103A	10/24	100	103.9	P/F	L/F
CCV								P/F	L/F

Conductivity Acceptance criteria ± 5%

pH	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Temp °C	Meter reading SU	mV	Pass / Fail	Lab / Field
DEP SOP FT 1100											
Calibr.	H Schmidt	12/2	0750	2904882	3/24	7.02	19.6	702	-30.0	P/F	L/F
Calibr.	↓	↓	0756	203626	6/22	4.00	20.3	4100	1486	P/F	L/F
Calibr.	↓	↓	0757	201473	5/22	10.06	20.3	10.06	-207.5	P/F	L/F
ICV	↓	↓	0758	203620	6/22	4	19.2	3.99	150.5	P/F	L/F
CCV	↓	↓	1553	2904882	3/24	7.0	19.8	7.03	-273	P/F	L/F
CCV										P/F	L/F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50; mV pH 4 Range +180 ± 50; mV pH 10 Range -180 ± 50;

If mV are recorded: slope from 7 to 10, slope from 4 to 7 (both must be between 165 and 180 mV)

Does meter have a depth sensor that will be used to measure total depth & sample depth? YES / NO / NA (not surf. water project)

If YES, complete daily Calibr. & ICV below and list date of last quarterly depth verification: 10/13/20

If NO, what will be used? (circle one) Secchi Disk Line / Sonar Unique ID: _____; Date of last verification: _____

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value, meters	Pass / Fail	Lab / Field
Pressure mode in air	H Schmidt	12/2	0759	0.00	0.00	P/F	L/F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria ± 5 % or ± 0.05m, whichever is greater.

REMARKS: