

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there are qualified data on this page.

Meter ID: Friday RQ: 2021-06-28-12 Project: Hatchec Creeks

Notes: (1) Always wait for meter to stabilize before recording any readings.
(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).
(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 05/18/21

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp °C	Baro- meter mmHg	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Thomas Baker	06/28/21	0701	24.4	758.6	8.3	8.39	100.3		1.05	Ⓟ / F	Ⓟ / F
ICV	"	"	0702	24.2	758.6	8.3	8.38	99.8			Ⓟ / F	Ⓟ / F
CCV	Nicole Reistad	06/28/21	1341	23.2	758.7	8.5	8.54	100.0			P / F	L / F
CCV												

DO Acceptance criteria from Table ± 0.3 mg/L. Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.
Optical: DO gain range 0.85 to 1.15 (Pro DSS 0.75 to 1.50); DO charge N/A. Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	Thomas Baker	06/28/21	0704	1002A78	2/22	10000	10000	Ⓟ / F	Ⓟ / F
ICV	"	06/28/21	0706	2612A70	11/22	500	489.9	Ⓟ / F	Ⓟ / F
CCV	Nicole Reistad	06/28/21	1337	2103E96	03/23	100	98.4	P / F	L / F
CCV									

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Temp °C	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Thomas Baker	06/28/21	0700	2102H67	07/23	7.00	25.0	7.00	-78.2	Ⓟ / F	Ⓟ / F
Calibr.	"	"	0712	2104A60	3/23	4.01	25.1	4.01	91.4	Ⓟ / F	Ⓟ / F
Calibr.	"	"	0714	1102821	7/22	10.01	25.0	10.00	-242.3	Ⓟ / F	Ⓟ / F
ICV	Thomas Baker	06/28/21	0715	2104A60	3/23	4.01	25.0	4.00		Ⓟ / F	Ⓟ / F
CCV	Nicole Reistad	06/28/21	1339	1102821	07/22	10.03	23.3	10.03		Ⓟ / F	Ⓟ / F
CCV						10.03	10.12	10.12		P / F	L / F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ; mV pH 4 Range $+180 \pm 50$; mV pH 10 Range -180 ± 50 ;
If mV are recorded: slope from 7 to 10 184.1, slope from 4 to 7 169.6 (both must be between 165 and 180 mV)

Does meter have a depth sensor that will be used to measure total depth & sample depth? YES / NO NA (not surf. water project)

If YES, complete daily Calibr. & ICV below and list date of last quarterly depth verification: 02/11/21

If NO, what will be used? (circle one) Secchi Disk Line / Sonar Unique ID: DEEPER BLUE Date of last verification: 02/11/21

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value, meters	Pass / Fail	Lab / Field
Pressure mode in air						P / F	L / F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS: