

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there are qualified data on this page.

Meter ID:

Hodor

RQ

2021-09-13-55

Project

SMP

Notes: (1) Always wait for meter to stabilize before recording any readings.

(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).

(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 7/22/2021

DO DEP SOP FT 1500	Name	Date	Time GT-ET	Temp. °C	Baro-meter mmHg	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Andrew Luering	9/16/21	812	22.7	754	8.6	8.56	99.3	-	1.08	0/F	0/F
ICV	"	"	814	22.7	755	8.6	8.56	99.3	-	1.08	0/F	0/F
CCV	S Fischer	9/16/21	1243	25.2	756	8.2	8.16	99.2	-	1.08	0/F	0/F
CCV											P/F	L/F

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15 (Pro DSS 0.75 to 1.50); DO charge N/A. Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time GT-ET	Lot #	Expir. Date	Standard μ hos/cm	Meter Reading μ hos/cm	Pass / Fail	Lab / Field
Calibr.	Andrew Luering	9/16/21	817	1108F51	8/2023	1000	995	0/F	0/F
ICV	"	9/16/21	820	1102792	1/2023	100	97.3	0/F	0/F
CCV	S Fischer	9/16/21	1245	1108F51	08/23	1000	997	0/F	0/F
CCV								P/F	L/F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time GT-ET	Lot #	Expir. Date	pH Buffer SU	Temp °C	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Andrew Luering	9/16/21	825	210039	10/2023	7.0	22.8	7.06	-24.0	0/F	0/F
Calibr.	"	"	827	2107E46	7/2023	4.0	22.6	4.0	154.3	0/F	0/F
Calibr.	"	"	830	2012C64	6/2022	10.0	22.8	9.95	-192.9	0/F	0/F
ICV	"	"	832	2012C64	6/2022	10.0	22.8	9.98	-193.6	0/F	0/F
CCV	S Fischer	9/16/21	1247	2107E46	07/23	4.	22.6	4.03	152.1	0/F	0/F
CCV										P/F	L/F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ;

mV pH 4 Range $+180 \pm 50$;

mV pH 10 Range -180 ± 50 ;

If mV are recorded: slope from 7 to 10 -168.9 , slope from 4 to 7 -178.3 (both must be between 165 and 180 mV)

Does meter have a depth sensor that will be used to measure total depth & sample depth? YES / NO / NA (not surf. water project)

If YES, complete daily Calibr. & ICV below and list date of last quarterly depth verification: 7/22/2021

If NO, what will be used? (circle one) Secchi Disk Line / Sonar Unique ID: ; Date of last verification:

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time GT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value, meters	Pass / Fail	Lab / Field
Pressure mode in air	Andrew Luering	9/16/21	833	0.00	0.00	0/F	0/F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS: