

BILL BRANCH CHEVROLET, INC.

3980 FOWLER STREET
FORT MYERS, FLORIDA 33901

web address: www.branchchevy.com
email: www.branchchev@aol.com

CHEV

SEE BACK FOR ADDITIONAL CUSTOMER INFORMATION REGARDING REPAIRS

FORT MYERS, FLORIDA
(239) 936-8561

STATE OF FLORIDA REGISTRATION MV-08568

INSIDE FLORIDA
1-800-226-7806

DEP-4853

CUSTOMER NO.	83055	ADVISOR	LISA GARDINER	7841	TAG NO.	283B	INVOICE DATE	03/09/04	INVOICE NO.	CTCS328251
DEPT OF ENVIRONMENTAL PROTECTION 2295 VICTORIA AVE. FORT MYERS, FL 33901		LABOR RATE	75.00	LICENSE NO.		MILEAGE	58,134	COLOR	WHITE/	STOCK NO.
		YEAR / MAKE / MODEL						DELIVERY DATE	DELIVERY MILES	
		VEHICLE I.D. NO.						SELLING DEALER NO.	PRODUCTION DATE	
		F.T.E. NO.						R.O. DATE		
RESIDENCE PHONE	941-332-6975	COMMENTS							MILES OUT	58134

LABOR & PARTS
J# 1 02CVZ

DRIVE & EMISSIONS

TECH(S):7327

1196.40

DRIVE & EMISSIONS TEL#07-1821
CUST ST: DROVE VEHICLE UNDER WATER. WILL NOT START
DIAGNOSIS: FOUND WATER INTRUSION IN ENGINE, TRANSMISSION,
FRONT DIFF. CASE, REAR DIFF. CASE AND TRANSFER CASE; FOUND
WATER IN AIR CLEANER; WATER IN FUEL TANK
R&R SPARK PLUGS TO CLEAN; CHANGED ENGINE OIL TWICE;
REPLACED OIL FILTER; PERFORMED TRANSMISSION FLUSH AND
REPLACED TRANSMISSION FILTER AND PAN GASKET; CHANGED
FLUID IN FRONT AND REAR DIFF. CASES AND TRANSFER CASE;
R&R FUEL TANK AND REPLACED FUEL PUMP AND FUEL PUMP RELAY;
REPLACED THROTTLE POSITION SENSOR; REPLACED STARTER MOTOR;
REPLACE IDLE CONTROL VALVE; REPLACED AIR FILTER; REPLACED
FUEL FILTER; CLEANED FUEL INJECTORS

PARTS	QTY	FP	NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	PRICE
JOB # 1	1		25176789	*MODULE 3.107	471.03		448.61
JOB # 1	3		1052271	LUBE 8.800	12.63		6.38
JOB # 1	16		ATF	FLUID	2.58		2.58
JOB # 1	1		24208576	FLTR KIT 4.197	81.54		55.02
JOB # 1	1		25168594	FILTER 3.890	28.38		28.38
JOB # 1	1		17123852	SENS-TROT 3.339	48.10		42.60
JOB # 1	1		26016661	GASKET 5.399	8.18		7.18
JOB # 1	1		25098463	AIR FLTR 3.410	26.52		19.95
JOB # 1	1		25171377	FILTER 1.836	9.69		7.00
JOB # 1	1		17113209	VALVE-IDL 3.820	109.08		109.08
JOB # 1	1		12088567	RELAY ASM 16.480	25.92		25.92
JOB # 1	1		25162556	SPARKPLUG 2.270	8.44		8.44
JOB # 1	1		9417866	BULB 8.991	1.00		1.00
JOB # 1	1		10465462	*STRTR REM 2.041	325.00		325.00
JOB # 1	-1		10465462	CORE RETURN	45.00		-45.00
JOB # 1	1		TRANS	TREATMENT	19.40		19.40
JOB # 1	1		25010792	OIL FLTR 1.836	9.69		7.00
					JOB # 1 TOTAL PARTS		1120.00

JOB # 1 TOTAL LABOR & PARTS 2316.40

J# 2+90CVZ

MISCELLANEOUS

TECH(S):7334

0.00

TOWED IN--SUPERIOR TOWING--INVOICE #28960
SUBLET TO MOBILE DETAIL EXPRESS TO CLEAN CARPET
NOTE: CARPET AND JUTE COME AS ONE UNIT---EST. IS \$898 TO
REPLACE CARPET AND JUTE ASSEMBLY

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	LIST PRICE-JOB # 2	UNIT PRICE-TOTAL	PRICE-PARTS
						0.00
						0.00

SUBLET	PO#	VEND	INV#	INV DATE	DESCRIPTION	
JOB # 2	89436	28960	03/03/04	TOW		81.00
JOB # 2	89459	479149	03/08/04	CLEAN-UP		26.00
				TOTAL	SUBLET	107.00

G.O.G. & SUPPLIES

G.O.G. & SUPPLIES					
JOB # 1	5.0 MOTOR OIL	@	1.260	/UNIT	6.30

ANY USED RESULT OR RECONDITIONED PART WILL BE STATED AS SUCH IN THE PARTS DESCRIPTION ABOVE. WE GUARANTEE OUR SERVICE WORK FOR 90 DAYS OR 1,000 MILES WHICHEVER COMES FIRST. IF OUR REPAIR OR REPLACEMENT FAILS IN NORMAL SERVICE WITHIN THE PERIOD, WE'LL FIX IT FREE OF CHARGE. THE ABOVE MISC. CHARGE REPRESENTS COSTS AND PROFITS TO THE MOTOR VEHICLE REPAIR FACILITY FOR ITEMS SUCH AS MISCELLANEOUS SHOP SUPPLIES AND GARBAGE WASTE DISPOSAL.

Invoice No.
131015003

Cook's Automotive of Bartow Inc.

State Certification # MV06028
1790 N Park Ave
Bartow, FL 33830
Phone: 863-533-0109 FAX: 863-533-9307

Dept of Env Protection
2001 Homeland Garfield Rd

BARTOW FL 33830
Hm: 534-7077
Wk: 534-7143 Fax

00 CHEVROLET S10 BLAZER 4x4
52805 Mi. Last in 7/2/03
Lic: DEP04853/FL 6Cyl 4.3 Eng
Vin: 1GNDT13W5Y2348544 04/00
Equipment: AT AC PS FI
Profile:

Order Date 10/15/03 12:38 pm
Paid: 10/17/03 11:47 am

Job01 Diagnostics - Check Engine Light

Labor: 1.00 hrs@ \$52.00/hr = \$52.00

Computer Analysis for Check Engine Light
Retrieve Trouble Codes From Computer,
Check Affected Areas For Proper Operation
Code P0300, Random Misfire
Perform Tuneup, Clear Codes

Job Subtotal: \$52.00

Job02 Oil-Lube-Filter Synthetic

Labor: 0.19 hrs@ \$50.00/hr = \$9.55

Change Oil, Lube Chassis, Install New Oil Filter
Check Fluids, Air Pressure, Up to Five Qts Motor Oil

PH51A	Oil Filter-N	1.0 @	1.85 =S	1.85	
28701	Synthetic Motor Oil-N	5.0 @	5.22 =S	26.10	27.95

Job Subtotal: \$37.50

Job03 Tune-up

Labor: 1.70 hrs@ \$52.00/hr = \$88.40

Replace Tune-up and Engine Performance Checks

6241	Spark Plug-Platinum-N	6.0 @	4.21 =S	25.26	25.26
------	-----------------------	-------	---------	-------	-------

Job Subtotal: \$113.66

Job04 Air Filter Replace

Labor: 0.00 hrs@ \$52.00/hr = \$0.00

AF7863	Air Filter-N	1.0 @	12.95 =S	12.95	12.95
--------	--------------	-------	----------	-------	-------

Job Subtotal: \$12.95

Part Warranty 12 Months 12000 Miles
Labor Warranty 90 Days 4000 Miles
Unless Otherwise Stated

Payments to Cook's Automotive of Bartow Inc.

Status: Paid Work Order

Payments: \$221.43

1 10/17/03 221.43 Visa 063391

Cost Summary

Labor	149.95
Parts	66.16
Haz Waste	1.00
Misc Supplies	4.32
Tax	0.00
Total	\$221.43
Payments	221.43
Bal Due	0.00

COOK'S AUTOMOTIVE OF
1790 N PARK AVE.
BARTOW, FL 33830

BATCH: 325
S-A-L-E-S D-R-A-F-T
74486219
030123655201

REF: 0002
CD TYPE: VISA
TR TYPE: PURCHASE
DATE: OCT 17, 03 11:47:18

TOTAL \$221.43

AP: 063391
NAME: CHERYL WHITNEY
TRAIL: 013290568377817
VALID: XBCU AUDIT 0500E

CARDMEMBER ACKNOWLEDGES RECEIPT OF GOODS
AND/OR SERVICES IN THE AMOUNT OF THE
TOTAL SHOWN HEREON AND AGREES TO PERFORM
THE OBLIGATIONS SET FORTH BY THE
CARDMEMBER'S AGREEMENT WITH THE ISSUER

THANKS FOR USING VISA

PCard Visa
241010
CWhitney
10/17/03
\$221.43

Cook's Automotive of Bartow Inc.

State Certification # MV06028

1790 N Park Ave

Bartow, FL 33830

Phone: 863-533-0109 FAX: 863-533-9307

Invoice No.

130702005

Order Date 07/02/03 01:45 pm

Paid: 07/03/03 11:31 am

Dept of Env Protection
2001 Homeland Garfield Rd

BARTOW FL 33830

Hm: 534-7077

Wk: 534-7143 Fax

00 CHEVROLET S10 BLAZER 4x4
47510 Mi Last In 12/12/02
Lic: DEP04853/FL 6Cyl 4.3 Eng
Vin: 1GNDT13W5Y2348544 04/00
Equipment: AT AC PS FI
Profile:**Job01 Oil-Lube-Filter Synthetic**

Labor: 0.19 hrs@ \$50.00/hr = \$9.55

Change Oil, Lube Chassis, Install New Oil Filter
Check Fluids, Air Pressure, Up to Five Qts Motor Oil

PH400	Oil Filter-N	1.0 @	1.85 =S	1.85	
28701	Synthetic Motor Oil-N	5.0 @	5.22 =S	26.10	27.95

Job Subtotal: \$37.50

Job02 Retrieve Computer Codes

Labor: 0.50 hrs@ \$52.00/hr = \$26.00

Computer Analysis for Check Engine Light
Retrieve Trouble Codes From Computer,
Code P0300, Random Cylinder Misfire
No Problem At This Time

Job Subtotal: \$26.00

Part Warranty 12 Months 12000 Miles
Labor Warranty 90 Days 4000 Miles
Unless Otherwise Stated

Payments to Cook's Automotive of Bartow Inc.

Status: Paid Work Order

Payments: \$65.77

1 7/3/03 65.77 Visa 008637

241010
Repair/Maint Auto
\$65.77**Cost Summary**

Labor	35.55
Parts	27.95
Haz Waste	1.00
Misc Supplies	1.27
Tax	0.00
Total	\$65.77
Payments	65.77
Bal Due	0.00

Thank you for choosing Cook's Automotive of Bartow Inc.

COOK'S AUTOMOTIVE OF
1790 N PARK AVE.
BARTOW, FL 33830BATCH: 268
S-A-L-E-S D-R-A-F-T
74486219
030123655281REF: 0001
CD TYPE: VISA
TR TYPE: PURCHASE
DATE: JUL 03, 03 11:31:27

TOTAL \$65.77

AP: 008637
NAME: CHERYL WHITNEY
TRAIL: 09318455807824
VALID: 68C2 RUDIT 0500ECARDHOLDER ACKNOWLEDGES RECEIPT OF GOODS
AND/OR SERVICES IN THE AMOUNT OF THE
TOTAL SHOWN HEREON AND AGREES TO PERFORM
THE OBLIGATIONS SET FORTH BY THE
CARDHOLDER'S AGREEMENT WITH THE ISSUERTHANKS FOR USING VISA
C. J. Whitney