



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION GROUND WATER MANAGEMENT

CALIBRATION LOG

METER ID # 101901

PRE-SAMPLE CALIBRATION (circle one)

IN-LAB

ON-SITE

ON-SITE LOCATION

DATE 5/29/13

TIME 7:30

POST-SAMPLE CALIBRATION (circle one)

IN-LAB

ON-SITE

ON-SITE LOCATION

DATE 5/30/13

TIME 7:15

DISSOLVED OXYGEN

Reading Type	mg/L	Temp °C	% Sat	Pass or Fail
INITIAL	8.63	22.53	99.7	Pass
CALIBRATION	8.65	22.53	100.0	Pass
PRE-VERIFICATION	8.65	22.53	100.0	Pass
POST-VERIFICATION	8.63	22.82	100.3	Pass

SPECIFIC CONDUCTANCE

Reading Type	Standard	Lot #	Exp. Date	µS/cm	Pass or Fail
INITIAL	100	2301231	6/14	99	Pass
CALIBRATION	100	2301231	6/14	100	Pass
PRE-VERIFICATION	100	2301231	6/14	100	Pass
POST-VERIFICATION	100	2301231	6/14	103	Pass

pH

Reading Type	Standard	Lot #	Exp. Date	SU	Temp °C	Pass or Fail
INITIAL	7.00	115471	10/13	6.99	22.32	Pass
CALIBRATION	7.00	115471	10/13	7.00	22.31	Pass
PRE-VERIFICATION	7.00	115471	10/13	7.00	22.31	Pass
POST-VERIFICATION	7.00	115471	10/13	6.98	22.73	Pass

Acceptance Criteria:

DO ± 0.3 mg/L

Sp. Cond. ± 5%

pH ± 0.2 SU

Temperature ± 0.2 °C

Was the Specific Conductance Probe cleaned? (circle one)

YES

NO

Was the Dissolved Oxygen Membrane changed? (circle one)

YES

NO

RQ & SITE IDS

RQ-2013-05-20-34

SPRG1304

DEVILS EYE
Spring
(GILCHRIST)
SPRG1304



DEVILS EAR SPRING (GILCHRIST)
SPRG1304 DEVILS EAR SPRING (GILCHRIST)

9677



ICHETUCKNEE HEAD SPRING
SPRG1304 ICHETUCKNEE HEAD SPRING

9713



BLUE HOLE SPRING (COLUMBIA)
SPRG1304 BLUE HOLE SPRING (COLUMBIA)

9743



MISSION SPRINGS
SPRG1304 MISSION SPRINGS

9714



MILL POND SPRINGS (COLUMBIA)
SPRG1304 MILL POND SPRINGS (COLUMBIA)

10786

SAMPLER NAMES & SIGNATURES (All team members present)

EDGAR WADE

Edgar Wade

KIRSTIN ELLER

Kirstin Eller