

Appendix A RD 2019-06-24-60

WATERBODY: Tampa Bay / Mouth of Hillsborough River		DATE (M/D/YY): 06/26/2019	TIME: (AM) 1400	Case ID#: 4133
COUNTY: Hillsborough	LOCATION: HILLS RIVER 2 DAVIS ISLAND		NEAREST TOWN/CITY: Davis Island	
Visit Type: Initial ☐ Recon ☐ Sampling ☒ Follow-up ☐	Samples collected: ☒ yes ☐ no	Samples submitted to: FDEP		Photos Taken: ☒ yes ☐ no
Sample collection method: Single Grab: ☒ Grab Composite: ☐ Depth integrated composite: ☐				
Sample & Analysis types: Aqueous: ☒ Surface Scum: ☐ Benthic mat: ☐ Tissue: ☐				
Algal ID & enumeration: ☐ Nutrients: ☐ Chl-a: ☐ AGP: ☐ Turbidity: ☐ Toxin: ☐ Specify _____				
Estimated size of bloom: Not observed	Impounded: ☐ yes ☐ no	Stream/River/Canal m wide		
Lake/Estuary Typical depth m deep	Inflows: ☒ yes ☐ no	Typical Transect m deep m deep m deep		
	Outflows: ☒ yes ☐ no	Water velocity m/s m/s m/s Left bank Middle Right bank		

Canopy Cover: Open : ☒ Lightly Shaded (11-45%): ☐ Moderately Shaded (46-80%): ☐ Heavily Shaded: ☐

Description of Bloom/not obs. Latitude

Degrees	Minutes	Seconds

 Longitude

Degrees	Minutes	Seconds

Present Weather conditions
Sunny & hot
w/ light wind
27.9091 - 82.4465

Print a map from GIS tool or Internet mapping service (e.g., Mapquest, Google Map) Last rain event 3 DAYS

Sketch bloom area on the attached map. Indicate wind direction.
ONLY ATTACHED MAPS ARE VISIBLE
Rainfall amount _____

WATER QUALITY	Depth (m):	Temp. (°C):	pH (SU):	D.O. (mg/l):	Cond. (µmho/cm) or Salinity (ppt):	Sal	DO %	Secchi (m)
Top	0.3	32.8	7.92	9.30	33746	20.97	145.6	0.75
Mid-depth								
Bottom								

System Type:	Stream: ☐ (1st - 2nd order 3rd - 4th order	☐ (5th - 6th order 7th order or greater	) Lake: ☐	Wetland: ☐	Estuary: ☒	Other: ☐
Water Odors (check box):	Normal: ☒	Sewage: ☐	Petroleum: ☐	Chemical: ☐	Other: ☐	
Water Surface (check box):	Clear: ☒	Scum: ☐	Globs: ☐	Slick: ☐		
Water Clarity (check box):	Clear: ☒	Slightly turbid: ☐	Turbid: ☐	Opaque: ☐		
Bloom Color (check box):	Green: ☐	Red: ☐	Brown: ☐	Other: ☐	NO COLOR	

Abundance	Abundant	Poor	Concentration	Abundance
Phytoplankton	☐	☐	☐	☐
Fish	☐	☐	☒	☐
Aquatic Macrophytes	☐	☐	☒	☐
Iron/sulfur Bacteria	☒	☐	☐	☐

AGENCY:

FDEF

Site Name: Hills. River Mouth @ Davis Island

Date: 06/26/2019

Pa
Th

the on-line version

Group: A	Bottle Type: BLOOM-ID	PT-50ML	# of Bottles: 6	Preservative:	ICE	Enter Number of Bottles Sent to Lab	/
Group: B	Bottle Type: W-MCYST-FA	BG-250ML-WDMT H	# of Bottles: 6	Preservative:	ICE	Enter Number of Bottles Sent to Lab	/
Group: C	Bottle Type: CHLSUITE-A	BP-1L	# of Bottles: 6	Preservative:	ICE	Enter Number of Bottles Sent to Lab	/
Group: C	Bottle Type: W-NH3 W-NO2NO3 W-S-A-TP W-TKN	P-500ML	# of Bottles: 6	Preservative: ICE And H2SO4		Enter Number of Bottles Sent to Lab	/
Group: C	Bottle Type: W-PO4-F	P-125ML	# of Bottles: 6	Preservative: FILTER-ICE		Enter Number of Bottles Sent to Lab	/
Group: D	Bottle Type: DTY-QN-C PKD-QN-C	BP-1L	# of Bottles: 6	Preservative: Lugols		Enter Number of Bottles Sent to Lab	/