



Email scanned submittal forms to lab.receiving@FloridaDEP.gov

RQ - 2019-12-23-10		Collected By: <i>M. Bearden</i>	
Customer: FDEP	Field Report Prepared By: <i>M. Bearden</i>		
Project ID: Bloom Response	Sampling Agency: 21FLTPA - SW ROC		
Location: WIN/Field ID		Comments: Heavy wind chop. Particulates seen in water column	
HAB-SW-0009			
Site Name: Lake Clinch - NE Lobe		Coordinates: 27.7448, -81.5365	
WIN ID: HAB-SW-0009		Collection Equip: Bottles - Direct Grab	
Matrix: Fresh	Grab	High Tide Time: N/A	Low Tide Time: N/A
Water Quality			
Date	Time ☒ EST ☐ CEN	D.O. (%)	D.O. (mg/L)
11/22/20	0915	95.0	9.09
		17.5	7.26
		0.3	1.5
		0.6	125.3
			0.00
Bloom Observations			
Algal Bloom Observed? ☒ Yes ☐ No			
Water Surface	☒ Clear	☐ Scum	☐ Slick
Water Clarity	☐ Clear	☒ Slightly Turbid	☐ Opaque
Bloom Color	☒ Green	☐ Red	☐ Other: N/A
Algae Distribution	☒ Suspended in water column	☐ On surface	☐ Other: N/A
Water Odors	☒ Normal	☐ Sewage	☐ Chemical
Parameter Suite			
Parameter Suite	Parameter Methods	Preservation	pH Check
Bloom ID (PT-50mL)	☒ BLOOM-ID	☒ Ice	☐ #Bottles Sent to Lab
Chlorophyll (BP-1L)	☒ CHLSUITE-W	☒ Ice	☐ 1 A
Toxins (BG-WD250)	☒ W-MCVST-AA	☒ Ice	☐ 1 B
Preserved Nutrients (500mL HDPE)	☒ W-NH3 / W-NO2NO3 / W-TKN / W-S-A-TP	☒ Ice	☐ 1 B
Acid Lot:		Exp:	
☒ W-PO4-F		☒ Field Filtered 0.45um Filter	
Filtered Nutrients (p125mL)	☒ DTY-QN-C / PKD-QN-C	☒ Ice	
Quantitative Algae	Date/Time	Received By:	
11/22/20 1030	<i>M. Bearden</i>	<i>M. Bearden</i>	