



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
SEPTIC TANK DRAINFIELD STUDY FIELD SHEET

RQ: 2017-06-05-17

Site: PEELER RESIDENCE

Date: 6/29/17

Samplers: MIKE ORENNAN / LEIF ROMAN

Site Name: <u>L4D</u>	Time: <u>11:22</u>
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: <u>L3S</u>	Time: <u>11:12</u>
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: <u>L3D</u>	Time: <u>11:16</u>
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: <u>L1S</u>	Time: <u>10:42</u>
Water Availability: DRY ☐ LOW ☐ MEDIUM ☒ HIGH ☐	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: <u>L2S</u>	Time: <u>10:44</u>
Water Availability: DRY ☐ LOW ☒ MEDIUM ☐ HIGH ☐	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: <u>L1D</u>	Time: <u>10:46</u>
Water Availability: DRY ☐ LOW ☐ MEDIUM ☒ HIGH ☐	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: <u>MS</u>	Time: <u>11:04</u>
Water Availability: DRY ☒ LOW ☐ MEDIUM ☐ HIGH ☐	Water Clear? YES ☐ NO ☐
Sample Acidified? YES ☐	Comments: <u>NOTHING PRODUCED</u>

Site Name: <u>M6</u>	Time: <u>10:55</u>
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

H₂SO₄

Lot # 81096

Exp: 30-Sept-2017

1 of 4



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
SEPTIC TANK DRAINFIELD STUDY FIELD SHEET

RQ: 2017-06-05-17

Site: PEEVER RESIDENCE

Date: 6/29/17

Samplers: MIKE DRENNAN / Leif Boman

Site Name: MW1	Time:
Water Availability: DRY ☐ LOW ☐ MEDIUM ☒ HIGH ☐ ?	Water Clear? YES ☐ NO ☒ ^{semi} cloudy
Sample Acidified? YES ☒	Comments: DTW: 29.5 ft Tubing / Valve issue. low amount collected. Filtered

Site Name: BLANK 1	Time: 10:25
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☐	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: BLANK 2	Time: 10:25
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☐	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: LGS	Time: 11:02
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: LGS	Time: 10:52
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments: Darker brown than most.

Site Name: LSS	Time: 10:58
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: LSD	Time: 10:50
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: L4S	Time: 11:19
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
SEPTIC TANK DRAINFIELD STUDY FIELD SHEET

RQ: 2017-06-05-17

Site: PEEVER RESIDENCE

Date: 6/29/17

Samplers: MIKE DRENNAN / LEIF ROMAN

Site Name: M6 (DUPE)	Time: 10:55
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: L2D	Time: 10:34
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: L7S	Time: 10:40
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: M3	Time: 11:10
Water Availability: DRY ☐ LOW ☐ MEDIUM ☒ HIGH ☐	Water Clear? YES ☐ NO ☒
Sample Acidified? YES ☒	Comments: Darker brown, contains ant remains & sediment

Site Name: M3 (DUPE)	Time: 11:10
Water Availability: DRY ☐ LOW ☐ MEDIUM ☒ HIGH ☐	Water Clear? YES ☐ NO ☒
Sample Acidified? YES ☒	Comments: Darker brown, contains ant remains & sediment

Site Name: M4	Time: 11:14
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments: grey, brown. Ant remains + sediment

Site Name: M1	Time: 10:30
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments: grey

Site Name: M2	Time: 10:32
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments: grey



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
SEPTIC TANK DRAINFIELD STUDY FIELD SHEET

RQ: 2017-06-05-17 Site: PEELER RESIDENCE

Date: 6/29/17 Samplers: LEIF ROMAN / MIKE / DRENNAN

Site Name: <u>STE 1</u>	Time: <u>12:10</u>
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☒	Water Clear? YES ☒ NO ☐
Sample Acidified? YES ☒	Comments:

Site Name: <u>P2</u>	Time: <u>12:01</u>
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☐	Water Clear? YES ☐ NO ☐
Sample Acidified? YES ☐	Comments: <u>Very low - DTW: 5.3 ft</u>

Site Name:	Time:
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☐	Water Clear? YES ☐ NO ☐
Sample Acidified? YES ☐	Comments:

Site Name:	Time:
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☐	Water Clear? YES ☐ NO ☐
Sample Acidified? YES ☐	Comments:

Site Name:	Time:
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☐	Water Clear? YES ☐ NO ☐
Sample Acidified? YES ☐	Comments:

Site Name:	Time:
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☐	Water Clear? YES ☐ NO ☐
Sample Acidified? YES ☐	Comments:

Site Name:	Time:
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☐	Water Clear? YES ☐ NO ☐
Sample Acidified? YES ☐	Comments:

Site Name:	Time:
Water Availability: DRY ☐ LOW ☐ MEDIUM ☐ HIGH ☐	Water Clear? YES ☐ NO ☐
Sample Acidified? YES ☐	Comments: