

DEP TIER 1
STATUS NETWORK SITE CHARACTERIZATION

Stream/Water Body Name: **Mildred Lake**

Site ID	Latitude	Longitude	Type of Recon	Date of Recon
Z3-SL-15021			Site Visit	5/16/2021

Return Recon #1 _____

Return Recon #2 _____

Return Recon #3 _____

Resource Type	Secondary Resource Type
Small Lake	No 2nd Type
Desk Recon: 12/15/2020 By: Nate Gargas	Letter Sent:
Recon Team:	

Site Location Address & Contact Information	Property Owner's Address
<i>Data Requested:</i>	<i>County:</i> Putnam

Tidal Info: _____

Access and Permission
PUBLIC ACCESS

Reason for Exclusion

Recon Result
For Site:
Z3-SL-15021

INCLUDE

ADDITIONAL NOTES

Additional Items: Jon Boat w/Trolling Motor 4x4 truck

DIRECTIONS:

From the district take FL-100 W go ~1.4 miles, turn left onto CR 309C go ~2.4 miles, turn right onto Motes Rd go ~1 mile, Continue straight for ~0.4 miles, turn right onto FL-20 W go ~15.4 miles, turn left onto CR 21 go ~0.1 miles, turn left onto Morris Lake Dr go ~0.3 miles, Slight right onto Frances St. Go ~200ft, continue straight onto Lake Mildred Rd go ~0.3 miles, when you come to the intersection for Millie St turn left down a trail next to a house (See pics/maps) follow trail to left drive down to lake

FILES GENERATED:
(i.e. digital photos, GPS, etc.)

PHOTOS



Generalized Water Information System Database Utilities

Recon Tracking

Existing Station

New SW Station

New GW Station

PK RANDOM SAMPLE LOCATION = Z3-SL-15021

County

PUTNAM

Quarter Quad

WMD

ST. JOHNS RIVER WMD

HUC

OKLAWAHA

Random Latitude

29° 36m 30.3729s

Random Longitude

81° 58m 24.351s

29.6084

81.9762

Is Z3-SL-15021 sampleable?

☐ Yes ☐ No ☒ N/A

Exclusion Category:

Exclusion Criteria:(definitions):

Was Z3-SL-15021 sampled?

☐ Yes

Month 5 ▾ Day 24 ▾ Year 2021 ▾

Add to LF

Comments:

Save

Reset

☒ Aerial Photo ☐ Quad Map ☐ No Image

Show Map

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there are qualified data on this page.

Meter ID:

Pro DSS Stitch

RQ:

2021-10-18-15

Project:

Scap Nassau North 2

Notes: (1) Always wait for meter to stabilize before recording any readings.

(2) Report all digits displayed. Do not round before reporting measurements. (See special instructions for depth).

(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification

8/16/21

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp °C	Baro- meter mmHg	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Kim Appleby	8/19/21	738	21.2	765.7	9.0	—	100.8	—	1.02646	P/F	L/F
ICV			739	21.2	765.8	9.0	8.96	100.9	—	1.02646	P/F	L/F
CCV	JPumsh	10/19/21	1612	21.2	765.8	8.9	8.98	100.9	—	—	P/F	L/F
CCV											P/F	L/F

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15 (Pro DSS 0.75 to 1.50); DO charge N/A. Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ hos/cm	Meter Reading μ hos/cm	Pass / Fail	Lab / Field
Calibr.	Kim Appleby	8/19/21	742	210426B	5/22	1000	1000	P/F	L/F
ICV			744	210426A	5/22	100	101.6	P/F	L/F
CCV	JPumsh	10/19/21	1613	210426C	5/22	1413	1400	P/F	L/F
CCV								P/F	L/F

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Temp °C	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Kim Appleby	10/19/21	748	2107F56	7/23	7.02	21.7	7.02	-29.7	P/F	L/F
Calibr.			752	2107640	7/23	4.00	21.8	4.00	148.2	P/F	L/F
Calibr.			754	2107F56	7/23	10.04	21.6	10.04	-200.1	P/F	L/F
ICV			758	2107F56	7/23	7.02	21.8	7.07	-29.9	P/F	L/F
CCV	JPumsh	10/19/21	1615	2107F56	7/23	10.00	21.4	10.14	207.6	P/F	L/F
CCV										P/F	L/F

pH Acceptance criteria ± 0.2 SU; mV pH 7 Range 0 ± 50 ;

mV pH 4 Range $+180 \pm 50$;

mV pH 10 Range -180 ± 50 ;

If mV are recorded: slope from 7 to 10 170.4 , slope from 4 to 7 177.9 (both must be between 165 and 180 mV)

Does meter have a depth sensor that will be used to measure total depth & sample depth? YES / NO / NA (not surf. water project)

If YES, complete daily Calibr. & ICV below and list date of last quarterly depth verification: 8/18/21

If NO, what will be used? (circle one) Secchi Disk Line / Sonar Unique ID: ; Date of last verification:

Depth Sensor (Daily Calibration & ICV)	Name	Date	Time CT-ET	Calibrated Value (0.00 or Offset), meters	ICV Value, meters	Pass / Fail	Lab / Field
Pressure mode in air	Kim Appleby	10/19/21	800	0.00	0.00	P/F	L/F

Report two decimal places. Round numbers ≤ 4 down, ≥ 5 up. ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater.

COMMENTS:

FORM FD 9000-27: LAKE VEGETATION INDEX FIELD SHEET

Site:					Date:				
SPECIES				Collected? (✓)	SPECIES				Collected? (✓)
Myriophyllum aquaticum					Salix caroliniana				
*Myriophyllum heterophyllum					Salvinia minima				
*Myriophyllum laxum					Sambucus canadensis				
*Myriophyllum pinnatum					Sapium sebiferum				
Myriophyllum spicatum					Saururus cernuus				
*Najas filifolia					Schinus terebinthifolius				
*Najas guadalupensis					*Schoenoplectus californicus				
*Najas minor					*Schoenoplectus pungens				
Nelumbo lutea					*Schoenoplectus tabernaemontani (Scirpus validus)				
Nitella spp.					Scirpus cubensis (Oxycaryon cubense)				
Nuphar sp.					Scirpus cyperinus				
Nymphaea odorata	D	D	D	D	*Sesbania				
Nymphoides aquatica					Solidago sp.				
Nyssa sylvatica var. biflora					Sparganium americanum				
Orontium aquaticum					Spartina bakeri				
Osmunda cinnamomea					Spirodela polyrhiza				
Osmunda regalis					Taxodium sp.				
Panicum hemitomon				✓	Thalia geniculata				
Panicum repens					Thelypteris palustris				
Paspalidium geminatum					Triadenum virginicum				✓
*Paspalum repens					Typha sp.				
Paspalum urvillei					Urochloa mutica (Brachiaria mutica)				
Peltandra sp.					*Utricularia gibba (U. biflora)				✓
Persea sp.					*Utricularia floridana				✓
Pennisetum purpureum					*Utricularia foliosa				✓
Phragmites australis					*Utricularia inflata				✓
Pinus elliotii					*Utricularia purpurea				✓
Pistia stratioides				✓	*Utricularia cornuta				✓
Pluchea sp.				✓	*Utricularia radiata				✓
*Polygonum glabrum (densiflorum)					Vallisneria americana				
*Polygonum hydropiperoides					*Websteria confervoides				
*Polygonum punctatum					Wedelia trilobata (Sphagneticola trilobata)				
*Polygonum hirsutum	✓	✓	✓	✓	Wolffiella spp.				
Pontederia cordata	✓	✓	✓	✓	Woodwardia virginica				
*Potamogeton diversifolius					Xyris sp.				
*Potamogeton illinoensis					Zizania aquatica				
*Potamogeton pusillus					Zizaniopsis milacea				
*Potamogeton pectinatus (Stuckenia pectinatus)									
Proserpinaca pectinata				✓	<i>Rigidulum</i>				
*Rhexia				✓	<i>Panicum strictum</i>				✓
*Rhynchospora corniculata					<i>Phynchospora micro.</i>				✓
*Rhynchospora inundata									✓
Rhynchospora tracyi									✓
Ricciocarpus natans									
Sabal palmetto									
Sacciolepis striata	✓	✓	✓	✓					
*Sagittaria filiformis									
*Sagittaria graminea									
*Sagittaria isoetiformis									
Sagittaria lancifolia									
Sagittaria latifolia									

DEP Form FD 9000-6: Lake Habitat Assessment Field Sheet

STORET STATION NUMBER:	DATE (M/D/Y) 10/19/21	LAKE NAME 23-SI-15021		FIELD ID / NAME:
ECO-REGION:	COUNTY: Putnam	SAMPLING LOCATION/DESCRIPTION: Mildred Lake		LAKE SIZE:
PARAMETER	No surface inflow or outflow present, very long water residence time, groundwater seepage dominates ☒	Surface water inflow present, but flow is rare, moderate to long water residence time ☐	Surface water inflow and outflow present (or outflow only), sometimes with visible flow, short water residence time ☐	Impounded, hydrology of system artificially controlled ☐
HYDROLOGY				
Color	Very clear, uncolored water (benthic sampling appropriate) ☐	Water somewhat tannin stained (benthic sampling appropriate) ☒	Dark, discolored water (water color 20 PCU or higher) ☐	Visibility extremely reduced due to high color ☐
	Optimal	Suboptimal	Marginal	Poor
Secchi ☐	Secchi >3 m Or VOB 20 19 18 17 16	3 2.6 2.2 1.8 1.4 15 14 13 12 11	1.0 0.9 0.8 0.7 0.6 10 9 8 7 6	0.5 0.4 0.3 0.2 0.1 5 4 3 2 1
Vegetation Quality 14 ☒	Diverse, expected native vegetation (emergent or submersed), less than 5% nuisance taxa 20 19 18 17 16	Mostly expected native plants, but moderate growths (6%-20% of lake) of nuisance macrophytes, or more than 50% of lake covered with plants 15 14 13 12 11	Large masses (21%-40%) of nuisance macrophytes (e.g., Hydrilla, hyacinth, cattail, etc.) or algal mats 10 9 8 7 6	Lake choked (>40%) with nuisance macrophytes (duckweed, hyacinth, etc.) or algal mats, or few plants present at all (e.g., plants removed) 5 4 3 2 1
Stormwater Inputs 13 ☐	Stormwater enters system via sheet flow over non-cultivated and/or natural vegetation 20 19 18 17 16	Some direct stormwater inputs (ditches, pipes, cultivated vegetation < 10%) but good BMPs in place 15 14 13 12 11	Moderate direct inputs of stormwater (ditches, pipes, cultivated vegetation 11%-50%) but few BMPs in place 10 9 8 7 6	Much direct input of stormwater (ditches, pipes, cultivated vegetation > 51%) and no or ineffective BMPs in place 5 4 3 2 1
Bottom Substrate Quality 19 ☐	Diverse mixture of sand, detritus, with small amounts of CPOM/mud/muck. SAV may be present 20 19 18 17 16	Mixture of sand or clay and detritus with higher % CPOM/mud/muck content. SAV may be present 15 14 13 12 11	Moderate layer of CPOM/mud/muck, or hardpacked sand only, or moderate algal growth (mats or Chara) on bottom 10 9 8 7 6	Thick deposits of CPOM, or fine detritus and anaerobic muck/mud/silt, or algal growth or nuisance plants (Hydrilla) cover bottom 5 4 3 2 1
Lakeside Adverse Human Alterations 13 ☐	Very few man-made structures, roads, or other disturbance adjacent to lake (<10%) 20 19 18 17 16	Moderate disturbance visible (structures, roads or other), 10%-49% lakeside affected 15 14 13 12 11	Many structures, roads or other human disturbance visible (50%-70%) lakeside affected 10 9 8 7 6	Highly developed or disturbed (>70% of lakeside affected) 5 4 3 2 1
Upland Buffer Zone 13 ☐	Expected native vegetation between uplands and littoral zone, greater than 90% of shore with >18 m buffer 20 19 18 17 16	89%-51% of shoreline with >18m buffer or >75% with 10m to 18m buffer 15 14 13 12 11	50%-30% of shoreline with >18m buffer or 50%-74% with 10m to 18m buffer 10 9 8 7 6	< 29% of shoreline with >18m buffer 5 4 3 2 1
Adverse Watershed Land Use 14 ☐	Score the potential effects from adverse human land uses, based on a continuum of amount and type, with least to most adverse as follows: Native vegetation, Silviculture, Pasture or Citrus, Low Density Residential, Row Crops, Commercial, High Density Residential, Urban, Industrial 20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
TOTAL SCORE 97	COMMENTS:			

ANALYSIS DATE: 10/19/21	ANALYST: J. Lane	SIGNATURE: J. Lane
----------------------------	---------------------	-----------------------

DEP FORM FD 9000-31: LAKE OBSERVATION FIELD SHEET

SAMPLE ID: _____ MACROPHYTE ID: _____ LATITUDE: _____
COUNTY: _____ STORET #: _____ LONGITUDE: _____
DATE: 10/19/21 TIME: 1145 SAMPLING AGENCY: _____
SITE NAME: Mildred Lake WBID: _____
FIELD ID/NAME: 23-56-15021 LAKE SIZE: _____ RQ: _____

WATERSHED / LAKESIDE FEATURES

PREDOMINANT LAND-USE IN WATERSHED (specify relative percent in each category – from GIS) : Forest/Natural ☐ Silviculture ☐ Field/Pasture ☐ Agricultural ☐ Residential ☐ Commercial ☐ Industrial ☐ Other (Specify) ☐				LANDSCAPE DEVELOPMENT INTENSITY (100 m buffer) LDI:	
Local Watershed Erosion (select one) : ☒ None ☐ Slight ☐ Moderate ☐ Heavy				Artificially Impounded ☐ Yes ☐ No	
Local Watershed NPS Pollution : ☒ No evidence ☐ Slight ☐ Moderate ☐ Heavy				Land Use Source & Year:	
STORMWATER INPUTS <u>13</u>	Stormwater enters system via sheet flow over non-cultivated and/or natural vegetation 20 19 18 17 16	Some direct stormwater inputs (ditches, pipes, cultivated vegetation < 10%) but good BMPs in place 15 14 13 12 11	Moderate direct inputs of stormwater (ditches, pipes, cultivated vegetation 11%-50%) but few BMPs in place 10 9 8 7 6	Much direct input of stormwater (ditches, pipes, cultivated vegetation > 51%) and no or ineffective BMPs in place 5 4 3 2 1	
LAKESIDE ALTERATIONS <u>13</u>	Very few man-made structures, roads, or other disturbance adjacent to lake (<10% lakeside affected) 20 19 18 17 16	Moderate disturbance visible - structures, roads or other (10%-49% lakeside affected) 15 14 13 12 11	Many structures, roads or other human disturbance visible (50%-70% lakeside affected) 10 9 8 7 6	Highly developed or disturbed (>70% of lakeside affected) 5 4 3 2 1	
BUFFER ZONE <u>13</u>	Expected native vegetation between uplands and littoral zone, greater than 90% of shore with >18 m buffer 20 19 18 17 16	89%-51% of shoreline with >18m buffer or >75% with 10m to 18m buffer 15 14 13 12 11	50%-30% of shoreline with >18m buffer or 50%-74% with 10m to 18m buffer 10 9 8 7 6	< 29% of shoreline with >18m buffer 5 4 3 2 1	

WATER / SUBSTRATE / BIOLOGICAL: SAMPLES AND OBSERVATIONS


Water: Nutrient Sample Taken? ☐ Yes ☒ No Preserved? ☐ Yes ☐ pH<2 ☒ No Color Sample Taken? ☐ Yes ☒ No Lot # _____ Exp. Date: _____ Alkalinity Sample Taken? ☐ Yes ☒ No Water Level ☐ Low ☐ Normal ☐ High								Water Odors: ☒ Normal ☐ Sewage ☐ Petroleum ☐ Other _____							
Meter Readings: Top: <u>0.3</u> <u>25.5</u> <u>6.4</u> <u>5.07</u> <u>62.0</u> <u>36</u> <u>0.02</u> Mid-Depth: <u>2.0</u> <u>25.3</u> <u>6.27</u> <u>4.68</u> <u>56.8</u> <u>35.8</u> <u>0.02</u> Bottom: <u>6.0</u> <u>6.5</u> <u>21.4</u> <u>5.9</u> <u>0.7</u> <u>8.4</u> <u>106</u> <u>0.05</u> Meter ID: _____								Water Surface Oils: ☒ None ☐ Sheen/Slick ☐ Glob ☐ Other _____							
Clarity: ☒ Clear ☐ Opaque ☐ Turbid ☐ Slightly Turbid								Color: ☒ Clear ☐ Tannic ☐ Green							
SECCHI (M) <u>1.5</u> Total Station Depth (M) <u>6.5</u> VOB ☐															
Sediment Type: (may check more than one) ☒ Sandy ☒ Organic fibrous (peaty, CPOM) ☐ Vegetated ☐ Sand/Silt ☐ Organic smooth (muck) ☐ Other (Specify): _____								Sediment Odors: ☒ Normal ☐ Other (Specify): ☐ Anaerobic							
Biological Communities: LVI Conducted? ☒ Yes ☐ No Phytoplankton Sample Taken? ☐ Yes ☒ No Sample Preserved? ☐ Yes ☒ No Lot #: _____ Exp Date: _____ Algal Bloom/Algal ID Sample Taken? ☐ Yes ☒ No Active Vegetation Mgmt? ☐ Yes ☒ No ☐ Don't Know								Abundance: Absent Rare Common Abundant Periphyton ☐ ☒ ☐ ☐ Nuisance Plants ☐ ☐ ☒ ☐ Submersed Plants ☐ ☐ ☐ ☒ Exotic Apple Snails ☒ ☐ ☐ ☐				Additional Notes: Powerline easement access			

Weather Conditions :


SAMPLING TEAM: Jerry Lamm / B Davis SIGNATURE: Jerry Lamm DATE: 10/19/21

23-SL-15021

Marker shows Map Coordinate



October 7, 2021



Maxar, Microsoft, Esri, HERE, Garmin, (c) OpenStreetMap contributors, and the GIS user community, Esri, HERE, iPC