



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
STRATEGIC MONITORING PROGRAM FIELD SHEET

PAGE ____ OF ____

February 2016

Data Qualified?

Yes / No

STORET Station Name: Rocky Creek @ SR51

Date: 02/25/2016
(mm/dd/yyyy)

STORET Station ID: 22050065 61TLHR0004

Latitude: 29.745686

(Decimal Degrees)

WBID: 3577

RQ: 2016-02-15-60

ORG ID: 21FITLHR

Longitude: 83.354669

(Decimal Degrees)

Receiving Body of Water: Steinhatchee River

Field ID: 22050065 61TLHR0004

County: Taylor

Sampling Team Members				WQ Measurements	Sample Collection	Documentation	Preservation	Preservation Check	Duplicate Collection	Blank Collection
Chris Green				✓	✓	✓	✓	✓		
Colby Marshall					✓		✓	✓		

Sampling Equipment		
☒ Sample Container	☐ Van Dorn	☐ Pole
☐ Carboy	☐ Syringe	
☐ Dipper	☐ Other	
Equipment ID		

Collection Method		
☒ Wading	Via Boat	
☐ From Shore	☐ Canoe/Kayak	
☐ Other (note below)	☐ Electric Motor	
	☐ Gasoline Motor	

Water Level: Dry / Low / Normal / High / Flooded

Meter ID# 12 YSI 600 X2M Photos: Yes / No

Matrix: Fresh / Marine / DI

Tide Falling: Yes / No / NA

Time Zone	Time	Sample Depth (m)	Total Depth (m)	DO (mg/L)	DO (%SAT)	pH	Salinity (ppt)	Secchi Disk (m)	Sp COND (µmhos/cm)	Temp. (C°)
EST	<u>11:45</u>	<u>0.3</u>	<u>0.6</u>	<u>8.0</u>	<u>80</u>	<u>7.4</u>	<u>0.6</u>	<u>0.45</u>	<u>275</u>	<u>15.6</u>
CEN										

Biological Samples Collected: None HA SCI LVS RPS LVI Other

Parameter Suite	Parameter Methods	Preservation	Acid Lot#	Expiration	pH Check
Preserved Nutrients	☒ TKN / TP / Nox / NH3 / TOC ☐ Other	☒ Ice ☒ H ₂ SO ₄	<u>SA-5259020</u>	<u>9/16</u>	☒ <2
Metals	☐ W-ICPMS ☐ W-ICP	☐ Ice ☐ HNO ₂			☐ <2
Filtered Nutrients	☒ oP ☒ Field Filtered 0.45 µm Filter	☒ Ice			
Chlorophyll	☒ CHLSUITE-W	☒ Ice			
BOD	☐ BOD-INHB ☒ BOD-UNIN	☒ Ice			
Physical/Aggregate	☒ TSS / Turbidity / Alkalinity / Color ☐ Other	☒ Ice			
Macroinvertebrates	☒ MI-FW-QLDC	☒ Formalin			
Microbiology	☐ E Coli ☐ F Coli ☐ Entero ☐ QPCR	☐ Ice			
Periphyton	☐ ALGAE-ID	☐ Ice			
Pesticides	☐ W-PSNP-TQ ☐ W-AHERB-AA ☐ W-PYR-AA-R ☐ W-PC-AA-SF ☐ W-LIHERB-AA ☐ W-GLYPH	☐ Ice ☐ Other			

Place Preservative Sticker(s) Here
(If Available)

Notes:

Signature: CLB

Date: 2/25/2016

Field Parameters Entered into LIMS: cm 4-4-16


Date Migrated to STORET: 5/17/16

Field Parameters QC in LIMS: cm 5-12-16

Field Sheets Scanned/Saved: 16 7-21-16

Place Label Here
(If Available)

DEP Form FD 9000-4 Stream/River Habitat Assessment Sketch Sheet



Location: Rocky Creek @ SR51

Date: 2-25-2016

Sampler: Chris Green

100 m: Latitude _____
Longitude _____

0 m: Latitude _____
Longitude _____

Substrates: Code key, draw proportionate habitat abundance. %

☐ S	Snags	<u>4.3</u>
☐ U	Roots/undercut banks	<u>0.4</u>
☐ L	Leaf Packs (or mats)	<u>8.8</u>
☐ A	Aquatic Macrophytes	<u>0</u>
☐ R	<u>Rock</u>	<u>69</u>
☐		
☐	Pools	total # observed = _____ # range expected = _____

Average width 4 m

Average depth 0.6 m

Velocity measured at 50 meter mark. 3 sec.

WQ & chemistry taken at 50 meter mark.

Habitat Smothering: slight silt
Note areas (on map) where sand or silt is smothering substrates, limiting habitability.

Bank Stability: good
Note areas (on map) with unstable, eroding banks.

Riparian Buffer Width: >18m
Note areas (on map) where natural vegetation is altered or eliminated.

Plants observed / other notes:

80% of system rock
river bottom
bottom

S 17
U 2.5
L 35

Length of grid represents 100 m of stream (not linear meters).
(Horizontal scale is double vertical scale, draw proportionately).

DEP Form FD 9000-3 Physical/Chemical Characterization Field Sheet

SAMPLE ID _____ ORG ID 21FLTLHR LATITUDE 29.745686
 COUNTY Taylor STORET # 22050065 LONGITUDE 83.354669
 DATE 2-25-16 TIME 12:00 SAMPLING AGENCY HEP 8034
 SITE NAME Rocky Creek @ SR51
 FIELD ID/NAME 22050065 RECEIVING BODY OF WATER Steinhatchee River

RIPARIAN ZONE / STREAM FEATURES

PREDOMINANT LAND-USE IN WATERSHED (specify relative percent in each category): Forest/Natural <u>20</u> Silviculture <u>70</u> Field/Pasture <u>10</u> Agricultural <u>0</u> Residential <u>0</u> Commercial <u>0</u> Industry <u>0</u> Other (Specify) <u>10</u>							Landscape Development Intensity Index (LDI) <u>5</u>
Local Watershed Erosion (select one): ☒ None ☐ Slight ☐ Moderate ☐ Heavy Local Watershed NPS Pollution: ☒ No evidence ☐ Slight ☐ Moderate ☐ Heavy							Typical Width (m) Depth (m)/Velocity (m/sec) Transect <u>4</u> m wide <u>.20</u> m/s <u>.33</u> m/s <u>.20</u> m/s <u>0.3</u> m deep <u>0.6</u> m deep <u>0.2</u> m deep
Width of Riparian Vegetation (m) on Each Buffer Side Left Bank: <u>715m</u> Right Bank: <u>715m</u>				Hydrologic Modification Score (per FT 3101) <u>0</u>			
High Water Mark: <u>0.1</u> + <u>0.6</u> = <u>0.7</u> (m) (above present water level) (present depth) (above bed)				Artificially Impounded ☐ Yes ☒ No			
Artificially ☒ No ☐ Mostly recovered, more sinuous Channelized: ☐ Some recovery ☐ Recent, severe				Canopy Cover % ☐ Open ☐ Lightly Shaded (11-45%) ☒ Heavily Shaded ☐ Moderate Shaded (46-80%)			

SEDIMENT / SUBSTRATE

Sediment Oils ☒ Absent ☐ Slight ☐ Moderate ☐ Profuse		Sediment Odors ☒ Normal ☐ Sewage ☐ Petroleum ☐ Chemical ☐ Anaerobic ☐ Other (Specify): _____		Smothering of Substrates Sand Smothering: None ☐ Slight ☐ Moderate ☐ Severe ☐ Silt Smothering: None ☐ Slight ☒ Moderate ☐ Severe ☐ Algae Smothering: None ☐ Slight ☒ Moderate ☐ Severe ☐	
SUBSTRATE TYPE Assessment Tool: ☒ SCI ☐ RPS ☐ LVS ☐ LCI ☐ BioRecon			WATER QUALITY Depth (M) Temp. (°C) pH (SU) D.O. (MG/L) D.O. Sat (%) Cond. (UMHO/CM) Salinity (PPT) SECCHI (M) Top: <u>0.3</u> <u>15.6</u> <u>7.4</u> <u>800</u> <u>80</u> <u>275</u> <u>0.65</u> Mid: <u>0.6</u> <u>1</u> <u>1</u> <u>8.0</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> Bottom: <u>0.6</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> Meter ID: <u>12 YSI 600 XLM</u>		
Woody Debris (Snags) <u>4.7</u> <u>5</u> <u>5</u> Undercut Banks / Roots <u>0.6</u> <u>1</u> <u>1</u> Leaf Packs or Mat <u>8.8</u> <u>4</u> <u>4</u> Aquatic Vegetation <u>0</u> <u>0</u> <u>0</u> Rock or Shell Rubble.. <u>6.9</u> <u>6</u> <u>6</u> Sand..... <u>17.3</u> <u>4</u> <u>4</u> Mud / Muck / Silt <u>0</u> <u>0</u> <u>0</u> Other <u>0</u> <u>0</u> <u>0</u> Other <u>0</u> <u>0</u> <u>0</u>			Water Odors Normal ☒ Petroleum ☐ Sewage ☐ Chemical ☐ Other ☐ Water Sample Taken? ☒ Yes ☐ No Sample Preserved? ☒ Yes ☐ No Lot Number: <u>5259020</u> Exp: <u>9/16</u> Algae Sample Taken? ☐ Yes ☒ No Sample Preserved? ☐ Yes ☒ No Lot Number: _____ Exp: _____		
ABUNDANCE Not Obs. Rare Common Abundant Periphyton: ☐ ☐ ☒ ☐ Fish: ☐ ☐ ☒ ☐ Aquatic Plants: ☐ ☒ ☐ ☐ Iron/Sulfur Bacteria: ☒ ☐ ☐ ☐			Water Surface Oils Normal ☒ Sheen ☐ Globbs ☐ Slick ☐ Other ☐ Color Tannic ☐ Green (Algae) ☐ Clear ☒ Other (Specify) ☐ Clarity Clear ☒ Slightly Turbid ☐ Turbid ☐ Opaque ☐		
System Type: Stream ☒ Lake ☐ Wetland ☐ Estuary ☐ Other (Specify) ☐			AMBIENT FIELD CONDITIONS / NOTES: ☒ The antecedent hydrologic conditions have been met to my best knowledge.		

SAMPLING TEAM Chris Green / Colby Marshall **SIGNATURE:** Chris Green **DATE:** 2-25-16

DEP Form FD 9000-5 Stream/River Habitat Assessment Field Sheet

SAMPLING AGENCY: <u>DEP 8034</u>		STORET STATION NUMBER: <u>225-16</u> <u>12050065</u>	DATE (MM/DD/YY): <u>2-25-16</u>	RECEIVING BODY OF WATER: <u>St. John's River</u>
REMARKS:	COUNTY: <u>Taylor</u>	LOCATION: <u>Rocky Creek @ SR51</u>	FIELD ID/NAME: <u>22050065</u>	

Habitat Parameter	Optimal	Suboptimal	Marginal	Poor
Primary Habitat Components	Four or more major productive habitats present (snags, tree roots, aquatic vegetation, leaf packs (partially decayed), rock)	Three major productive habitats present. Adequate habitat. Some substrates may be new fall (fresh leaves or snags)	Two major productive habitats present. Less than desirable habitat, frequently disturbed or removed	One or less major productive habitat. Lack of habitat is obvious, substrates unstable or smothered
Substrate Diversity <u>19</u>	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Substrate Availability <u>18</u>	Greater than 30% major productive habitat present at site 20 19 18 17 16	16% to 30% major productive habitat, by aerial extent 15 14 13 12 11	6% to 15% major productive habitat 10 9 8 7 6	Less than 5% major productive habitat 5 4 3 2 1
Water Velocity <u>20</u>	Max. observed at typical transect: > 0.25 m/sec. But < 1 m/sec ≥0.33 0.31 0.29 0.27 >0.25 20 19 18 17 16	Max. observed at typical transect: >0.1 to 0.25 m/sec 0.25 0.21 0.17 0.13 >0.1 15 14 13 12 11	Max. observed at typical transect: 0.05 to 0.1 m/sec 0.1 0.09 0.07 0.06 0.05 10 9 8 7 6	Max. observed at typical transect: <0.05 m/sec; or spate occurring: > 1 m/sec <0.05 0.04 0.03 0.01 <0.01 5 4 3 2 1
Habitat Smothering <u>18</u> ----- Primary Score <u>75</u>	Adequate number of stable pools (1-2 per 12 times width) and <25% of habitats affected by sand, silt, or algae. 20 19 18 17 16	Adequate number of stable pools (1-2 per 12 times width) and >25% of habitats affected by sand, silt, or algae. 15 14 13 12 11	Does not have required number of stable pools (1-2 per 12 x width) and/or has shallow pools (<2 x prevailing depth). 10 9 8 7 6	Stable pools are absent. Most habitats affected by sand, silt, or algae accumulation. 5 4 3 2 1
Secondary Habitat Components	Expected sinuosity given the stream width. No evidence of dredging or artificial straightening. No spoil banks.	Good sinuosity within old channelized area. Evidence of dredging in the past (>25 yrs) but mostly recovered.	Straightened with trapezoidal cross section, but has a small degree of sinuosity developed within channelized area.	Straightened or engineered by dredging, has trapezoidal or box cut cross section, lacks required pools. May have spoil banks.
Artificial Channelization <u>19</u>	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Bank Stability	Bankfull > 60% of bank height. Slope of bank ≤ 60° from bankfull to top of bank. Bankfull is within or above the root zone with few raw, eroded areas.	Only meets 2 of the 3 requirements for optimal bank stability.	Only meets 1 of the 3 requirements for optimal bank stability.	Bankfull < 60% of bank height. Slope of bank > 60°. Bankfull is below the root zone with raw, eroded areas.
Right Bank <u>9</u> Left Bank <u>9</u>	10 9	8 7 6	5 4	3 2 1
Riparian Buffer Zone Width	Width of vegetation greater than 18 m	Width of vegetation >12 to 18m	Width of vegetation 6 to 12 m. human activities close to system	Less than 6 m of buffer zone due to intensive human activities
Right Bank <u>10</u> Left Bank <u>10</u>	10 9	8 7 6	5 4	3 2 1
Riparian Zone Vegetation Quality	Over 80% of riparian surfaces consist of normal, expected plant community for given sunlight & habitat conditions (e.g., native plants; tree, shrub, and forbs represented, if appropriate). Minimal disturbance.	>50% to 80% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Some disruption in community observed.	25% to 50% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Disruption obvious.	Less than 25% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions).
Right Bank <u>10</u> Left Bank <u>10</u> ----- Secondary Score <u>77</u>	10 9	8 7 6	5 4	3 2 1

152 TOTAL SCORE

Date: <u>2-25-2016</u>	Analyst: <u>Chris Green</u>	Signature: <u>CKZ</u>
------------------------	-----------------------------	-----------------------

DEP FORM FD 9000-32: LINEAR VEGETATION SURVEY FIELD SHEET

Waterbody: Rocky Creek @ SR51	Date: 2/25/16	County: Taylor	Storet Number: 22050065
Analyst: Colby Marshall		Signature:	

Comments:

Instructions: Note taxa growing in the water with a checkmark if present, "D" if dominant, and "C" if codominant (dominance only if 1 m² of taxa present). Note in the boxes below if no dominant are selected, and note total macrophyte abundance rank for each section. Only the most common taxa are listed, so use blank spaces for additional taxa names.

[illegible]

DEP FORM FD 9000-25 Rapid Periphyton Survey Field Sheet

Site: Rocky Creek SR51 County: Taylor Date: 2-25-16 Investigators: Chris Green / Colby Marshall

Transect (m) Point 1=right 9=left Algal Thickness Rank (N-6, X) Estimated Canopy Cover

Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover
0	1	3		
	2	5		
	3	~		
	4	~		
	5	~		91
	6	~		
	7	~		
	8	~		
	9	6		
10	1	~		
	2	~		
	3	~		
	4	~		
	5	~		94
	6	~		
	7	~		
	8	~		
	9	~		
20	1	~		
	2	~		
	3	~		
	4	~		
	5	~		91
	6	~		
	7	~		
	8	~		
	9	~		
30	1	~		
	2	~		
	3	~		
	4	~		
	5	~		82
	6	~		
	7	~		
	8	~		
	9	~		
40	1	~		
	2	~		
	3	~		
	4	6		
	5	6		90
	6	3		
	7	3		
	8	~		
	9	4		
50	1	~		
	2	~		
	3	~		
	4	~		
	5	~		91
	6	~		
	7	~		
	8	~		
	9	~		

STORET Station Number: 22050065

Secchi depth 0.6
Estimated?

points ranked 4-6 4
total points assessed 44
% points ranked 4-6 4

Check accompanying data collected at same site/date.
Algal mat sample
Linear Veg Survey ☒
Habitat Assessment ☒
SCI/Biorecon ☒
Water sample ☒
RQ- 2016-02-15-60

Algal Thickness Rank	
N	rough, no algae, slimy, algae up to 1mm
3	>1mm - 6mm
4	>6mm - 20mm
5	>20mm - 10 cm
6	>10 cm

Record "N" and check "Estimated" for points deeper than the Secchi depth; algae are presumed absent. Check "Estimated" if thickness estimated for deep points which can be seen but not reached.
Record "X" for points shallower than Secchi depth for which substrate cannot be seen or reached with the hand. No estimated rank.
Record canopy cover as the number of small densiometer quadrants (out of 96) that HAVE canopy cover. Measure facing upstream at point 4, 5, or 6.
Collect algal mat sample following DEP SOP FS 7240 if the percentage of total sampled points with a thickness rank of 4, 5, or 6 is >20%.