

RA-2016-01-18-43

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this page.

Meter ID: **AE3**

Project: **SMP**

- Notes: (1) Numbers ≤ 4 , are rounded down; numbers ≥ 5 are rounded up (e.g., 5.15 becomes 5.2).
 (2) Always wait for meter to stabilize before recording any readings.
 (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site _____

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification 1/15/16

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Olga Sanchez	1/20/16	6:40am	18.9	9.9	9.3	100	37	1.08	P	L
ICV	Olga Sanchez	1/20/16	6:42am	18.9	9.3	9.3	100	38	—	P	L
CCV	Olga Sanchez	1/20/16	4:08pm	21.5	8.8	8.8	100	39	—	P	L
CCV											

Report DO mg/L with one decimal figure and DO % saturation as a whole number with no decimals.

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	Olga Sanchez	1/20/16	6:43	150929	10/2016	1000	1000	P	L
ICV	Olga Sanchez	1/20/16	6:44	150811	2/16	100	102	P	L
CCV	Olga Sanchez	1/20/16	4:09pm	150929	10/2016	1000	997	P	L
CCV	Olga Sanchez	1/20/16	4:09pm	150811	2/16	100	101	P	L

Report specific conductance as a whole number with no decimal figure.

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Olga Sanchez	1/20/16	6:50	150812	3/17	7.0	7.0	-760	P	L
Calibr.	Olga Sanchez	1/20/16	6:51	153225	5/17	4.0	4.0	163	P	L
Calibr.	Olga Sanchez	1/20/16	6:52	149101	1/17	10.0	10.0	-181	P	L
ICV	Olga Sanchez	1/20/16	6:53	149101	1/17	10.0	10.0	-182	P	L
CCV	Olga Sanchez	1/20/16	4:10am	150812	3/17	7.0	7.0	-7	P	L
CCV	Olga Sanchez	1/20/16	4:12am	149101	1/17	10.0	10.0	-182	P	L

Report pH with one decimal place; pH Acceptance criteria ± 0.2 SU;

mV pH7 Range 0 ± 50 ;

mV pH 4 Range $+180 \pm 50$;

mV pH 10 Range -180 ± 50 ;

Slope from 7 to 10 and 4 to 7 must be between 165 and 180 mV

Depth (Quarterly)

Date of Last Depth Verification 1/15/16

Depth Sensor (Daily)	Name	Date	Time CT-ET	Zero the Sensor	ICV Value	Pass / Fail	Lab / Field
Pressure mode in air	Olga Sanchez	1/20/16	6:55am	0.000	0.000	P	L

ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater