

ials/Date)

DEP Form FD 9000-5 Stream/River Habitat Assessment Field Sheet

78155/


SAMPLING AGENCY: NE ROC		STORET STATION NUMBER: 20030653	DATE (MM/DD/YY): 12/27/17	RECEIVING BODY OF WATER: PUNN CR.
REMARKS:	COUNTY: Punalu	LOCATION: Terrapin @ Faye Rd.	FIELD ID/NAME:	

Habitat Parameter	Optimal	Suboptimal	Marginal	Poor
Primary Habitat Components	Four or more major productive habitats present (snags, tree roots, aquatic vegetation, leaf packs (partially decayed), rock)	Three major productive habitats present. Adequate habitat. Some substrates may be new fall (fresh leaves or snags)	Two major productive habitats present. Less than desirable habitat, frequently disturbed or removed	One or less major productive habitat. Lack of habitat is obvious, substrates unstable or smothered
Substrate Diversity <u>3</u>	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Substrate Availability <u>2</u>	Greater than 30% major productive habitat present at site 20 19 18 17 16	16% to 30% major productive habitat, by aerial extent 15 14 13 12 11	6% to 15% major productive habitat 10 9 8 7 6	Less than 5% major productive habitat 5 4 3 2 1
Water Velocity <u>12</u>	Max. observed at typical transect: > 0.25 m/sec. But < 1 m/sec ≥0.33 0.31 0.29 0.27 >0.25 20 19 18 17 16	Max. observed at typical transect: >0.1 to 0.25 m/sec 0.25 0.21 0.17 0.13 >0.1 15 14 13 12 11	Max. observed at typical transect: 0.05 to 0.1 m/sec 0.1 0.09 0.07 0.06 0.05 10 9 8 7 6	Max. observed at typical transect: <0.05 m/sec; or spate occurring: > 1 m/sec <0.05 0.04 0.03 0.01 <0.01 5 4 3 2 1
Habitat Smothering <u>5</u> Primary Score <u>22</u>	Adequate number of stable pools (1-2 per 12 times width) and <25% of habitats affected by sand, silt, or algae. 20 19 18 17 16	Adequate number of stable pools (1-2 per 12 times width) and >25% of habitats affected by sand, silt, or algae. 15 14 13 12 11	Does not have required number of stable pools (1-2 per 12 x width) and/or has shallow pools (<2 x prevailing depth). 10 9 8 7 6	Stable pools are absent. Most habitats affected by sand, silt, or algae accumulation. 5 4 3 2 1
Secondary Habitat Components	Expected sinuosity given the stream width. No evidence of dredging or artificial straightening. No spoil banks.	Good sinuosity within old channelized area. Evidence of dredging in the past (>25 yrs) but mostly recovered.	Straightened with trapezoidal cross section, but has a small degree of sinuosity developed within channelized area.	Straightened or engineered by dredging, has trapezoidal or box cut cross section, lacks required pools. May have spoil banks.
Artificial Channelization <u>10</u>	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Bank Stability	Bankfull > 60% of bank height. Slope of bank ≤ 60° from bankfull to top of bank. Bankfull is within or above the root zone with few raw, eroded areas.	Only meets 2 of the 3 requirements for optimal bank stability.	Only meets 1 of the 3 requirements for optimal bank stability.	Bankfull < 60% of bank height. Slope of bank > 60°. Bankfull is below the root zone with raw, eroded areas.
Right Bank <u>4</u> Left Bank <u>4</u>	10 9	8 7 6	5 4	3 2 1
Riparian Buffer Zone Width	Width of vegetation greater than 18 m	Width of vegetation >12 to 18m	Width of vegetation 6 to 12 m. human activities close to system	Less than 6 m of buffer zone due to intensive human activities
Right Bank <u>6</u> Left Bank <u>9</u>	10 9	8 7 6	5 4	3 2 1
Riparian Zone Vegetation Quality	Over 80% of riparian surfaces consist of normal, expected plant community for given sunlight & habitat conditions (e.g., native plants; tree, shrub, and forbs represented, if appropriate). Minimal disturbance.	>50% to 80% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Some disruption in community observed.	25% to 50% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Disruption obvious.	Less than 25% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions).
Right Bank <u>6</u> Left Bank <u>6</u> Secondary Score <u>45</u>	10 9	8 7 6	5 4	3 2 1

7767 TOTAL SCORE

Date: 12/27/17	Analyst: Jeremy Parnis	Signature: Jeremy Parnis
----------------	------------------------	--------------------------

DEP Form FD 9000-4 Stream/River Habitat Assessment Sketch Sheet



Length of grid represents 100 m of stream (not linear meters).
(Horizontal scale is double vertical scale, draw proportionately).

Location: Terrapin
Open Kaye Rd.
Date: 12/27/17
Sampler: JP

100 m: Latitude _____	Longitude _____
0 m: Latitude _____	Longitude _____
Substrates: Code key, draw proportionate habitat abundance.	
☒	Snags 21
☒	Roots/undercut banks 21
☒	Leaf Packs (or mats) 2
☐	Aquatic Macrophytes _____
☐	_____
☐	_____
☐	total # observed = _____
☐	Pools # range expected = _____
Average width _____ m	
Average depth _____ m	
Velocity measured at _____ meter mark.	
WQ & chemistry taken at _____ meter mark.	
Habitat Smothering: Note areas (on map) where sand or silt is smothering substrates, limiting habitability.	
Bank Stability: Note areas (on map) with unstable, eroding banks.	
Riparian Buffer Width: Note areas (on map) where natural vegetation is altered or eliminated.	

Plants observed / other notes:

<2 M of Macrophytes was observed while doing the LVS? YES or NO

0.17 velocity

1.7 wide

DEP Form FD 9000-3 Physical/Chemical Characterization Field Sheet

98199 ✓

SAMPLE ID _____ ORG ID _____ LATITUDE 30.434361
 COUNTY Punk STORET # 20030653 LONGITUDE 81.565555
 DATE 12/27/17 TIME 940 SAMPLING AGENCY DEAR NEP
 SITE NAME Tekapin @ Faye Rd
 FIELD ID/NAME _____ RECEIVING BODY OF WATER FCW

RIPARIAN ZONE / STREAM FEATURES

Meter ID: YSI#4

PREDOMINANT LAND-USE IN WATERSHED (specify relative percent in each category): Forest/Natural ☐ Silviculture ☐ Field/Pasture ☐ Agricultural ☐ Residential ☐ Commercial ☐ Industry ☐ Other (Specify) ☐								Landscape Development Intensity Index (LDI) ☐	
Local Watershed Erosion (select one): ☐ None ☐ Slight ☐ Moderate ☒ Heavy Local Watershed NPS Pollution: ☒ No evidence ☐ Slight ☐ Moderate ☐ Heavy								Typical Width (m) Depth (m) Velocity (m/sec) Transect 1.7 m wide m/s 0.17 m/s m/s m deep 0.1 m deep m deep	
Width of Riparian Vegetation (m) on Each Buffer Side Left Bank: <u>>18</u> Right Bank: <u>12h</u>				Hydrologic Modification Score (per FT 3101) <u>3-4</u>					
High Water Mark: <u>0.4</u> + <u>0.1</u> = <u>0.5</u> (m) (above present water level) (present depth) (above bed)				Artificially Impounded ☐ Yes ☒ No					
Artificially ☒ No ☐ Mostly recovered, more sinuous Channelized: ☒ Some recovery ☐ Recent, severe				Canopy Cover % ☐ Open ☐ Lightly Shaded (11-45%) ☐ Heavily Shaded ☒ Moderate Shaded (46-80%)					

SEDIMENT / SUBSTRATE

Sediment Oils ☒ Absent ☐ Slight ☐ Moderate ☐ Profuse			Sediment Odors ☒ Normal ☐ Sewage ☐ Petroleum ☐ Chemical ☐ Anaerobic ☐ Other (Specify): _____			Smothering of Substrates Sand Smothering: None ☐ Slight ☐ Moderate ☐ Severe ☒ Silt Smothering: None ☐ Slight ☐ Moderate ☐ Severe ☐ Algae Smothering: None ☒ Slight ☐ Moderate ☐ Severe ☐		
SUBSTRATE TYPE Assessment Tool: ☐ SCI ☒ RPS ☒ LVS ☐ LCI ☐ BioRecon INVERT PERI % # Times # Times Coverage Sampled Sampled Woody Debris (Snags) <u><1</u> ☐ ☐ Undercut Banks / Roots <u><1</u> ☐ ☐ Leaf Packs or Mat <u>2</u> ☐ ☐ Aquatic Vegetation ☐ ☐ ☐ Rock or Shell Rubble.. ☐ ☐ ☐ Sand..... ☐ ☐ ☐ Mud / Muck / Silt ☐ ☐ ☐ Other ☐ ☐ ☐ Other ☐ ☐ ☐			WATER QUALITY Depth (M) Temp. (°C) pH (SU) D.O. (MG/L) D.O. Sat (%) Cond. (UMHO/CM) Salinity (PPT) SECCHI (M) Top: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Mid: <u>0.1</u> <u>13.3</u> <u>5.9</u> <u>8.30</u> <u>79.2</u> <u>195</u> <u>0.09</u> <u>100</u> Bottom: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ System Type: Stream ☒ Lake ☐ Wetland ☐ Estuary ☐ Other (Specify) ☐					
			Water Odors Normal ☒ Petroleum ☐ Sewage ☐ Chemical ☐ Other ☐			Water Surface Oils Normal ☐ Sheen ☐ Globbs ☐ Slick ☐ Other ☐		
			Water Sample Taken? ☒ Yes ☐ No Sample Preserved? ☐ Yes ☐ No Lot Number: <u>SA7163010</u> Exp: <u>6/13/18</u>			Color Tannic ☒ Green (Algae) ☐ Clear ☐ Other (Specify) ☐		
			Algae Sample Taken? ☐ Yes ☒ No Sample Preserved? ☐ Yes ☒ No Lot Number: _____ Exp: _____			Clarity Clear ☒ Slightly Turbid ☐ Turbid ☐ Opaque ☐		
ABUNDANCE Not Obs. Rare Common Abundant Periphyton: ☐ ☒ ☐ ☐ Fish: ☐ ☒ ☐ ☐ Aquatic Plants: ☒ ☐ ☐ ☐ Iron/Sulfur Bacteria: ☐ ☐ ☐ ☒			AMBIENT FIELD CONDITIONS / NOTES: Hydrologic Disturbance Scoring ☐ 1-2 ☐ 3-4 ☐ 5-6 ☐ 7-8 ☐ 9-10 ☐ The antecedent hydrologic conditions have been met to my best knowledge.					
SAMPLING TEAM			SIGNATURE :					

78195 455 4657

DEP FORM FD 9000-25 Rapid Periphyton Survey Field Sheet

Site: Terrapin Cn @ Faye Rd County: Paul Date: 12/27/17 Investigators: 13/Rev13

Transect (m) Point 1=right 9=left Algal Thickness Rank (N-6, X) Estimated Canopy Cover

STORET Station Number: 20030653

0	1	N			60	1	N		
	2					2			
	3					3			
	4					4			
	5			76		5			75
	6					6			
	7					7			
	8					8			
	9					9			
10	1	N			70	1	N		
	2					2			
	3					3			
	4					4			
	5			87		5			35
	6					6			
	7					7			
	8					8			
	9					9			
20	1	N			80	1	N		
	2					2			
	3					3			
	4					4			
	5			86		5			52
	6					6			
	7					7			
	8					8			
	9					9			
30	1	N			90	1	N		
	2					2			
	3					3			
	4					4			
	5			80		5			96
	6					6			
	7					7			
	8					8			
	9					9			
40	1	N			100	1	N		
	2					2			
	3					3			
	4					4			
	5			93		5			96
	6					6			
	7					7			
	8					8			
	9					9			
50	1	N				1	N		
	2					2			
	3					3			
	4					4			
	5			93		5			
	6					6			
	7					7			
	8					8			
	9					9			

Secchi depth 100
Estimated? ✓

points ranked 4-6 2
total points assessed 99
% points ranked 4-6 21

Check accompanying data collected at same site/date.
Algal mat sample ✓
Linear Veg Survey ✓
Habitat Assessment ✓
SCI/Biorecon ✓
Water sample ✓
RQ-2017-12-18-10

Algal Thickness Rank	
N	rough, no algae, slimy, algae up to 1mm
3	>1mm - 6mm
4	>6mm - 20mm
5	>20mm - 10 cm
6	>10 cm

Record "N" and check "Estimated" for points deeper than the Secchi depth; algae are presumed absent. Check "Estimated" if thickness estimated for deep points which can be seen but not reached.
Record "X" for points shallower than Secchi depth for which substrate cannot be seen or reached with the hand. No estimated rank.
Record canopy cover as the number of small densiometer quadrants (out of 96) that HAVE canopy cover. Measure facing upstream at point 4, 5, or 6.
Collect algal mat sample following DEP SOP FS 7240 if the percentage of total sampled points with a thickness rank of 4, 5, or 6 is >20%.

Waterbody: <u>Terrapin Bayou</u>	Date: <u>12/21/12</u>	County: _____	Storet Number: <u>2003065</u>
Analyst: <u>JP</u>	Signature: <u>JP</u>		
Comments: _____			

Instructions: Note taxa growing in the water with a checkmark if present, "D" if dominant, and "C" if codominant (dominance only if 1 m² of taxa present). Note in the boxes below if no dominant are selected, and note total macrophyte abundance rank for each section. Only the most common taxa are listed, so use blank spaces for additional taxa names.

Revision Date: March 1, 2014