

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this name.

Meter QUANTA+ RQ- 2017-04-17-11 Project Interlachen Lakes

- Notes: (1) Numbers ≤ 4 , are rounded down; numbers ≥ 5 are rounded up (e.g., 5.15 becomes 5.2).
 (2) Always wait for meter to stabilize before recording any readings.
 (3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification

02-09-17

DO DEP SOP FT 1500	Name	Date	Time CT-ET	Temp	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	PO Conn	05-04-17	0705	23.0	8.57	8.57	100.0	-	Pass	Pass	Lab
ICV	↓	↓	0708	23.0	8.57	8.56	99.9	-	-	Pass	Lab
CCV	PO Conn	05-04-17	1315	23.6	8.48	8.42	99.3	-	-	Pass	Lab
CCV											

Report DO mg/L with one decimal figure and DO % saturation as a whole number with no decimals.

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time CT-ET	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	PO Conn	05-04-17	0710	170315B	03/2018	1000	1000	Pass	Lab
ICV	↓	↓	0713	2142017	12-2017	147	145	Pass	Lab
CCV	PO Conn	05-04-17	1317	161101B	05-2017	100	100		
CCV									

Report specific conductance as a whole number with no decimal figure.

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time CT-ET	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	PO Conn	05-04-17	0715	2702C47	02-2019	7.0	7.00	-	Pass	Lab
Calibr.	↓	↓	0725	2610F42	10-2018	4.0	4.00	-	Pass	Lab
Calibr.	↓	↓	0730	2611998	05-2018	10.0	9.85	-	Pass	Lab
ICV	PO Conn	05-04-17	1328	2610F42	10-2018	4.0	3.96	-	Pass	Lab
CCV	PO Conn	↓	1330	2702C47	02-2019	7.0	6.97	-	Pass	Lab
CCV										

Report pH with one decimal place; pH Acceptance criteria ± 0.2 SU;

mV pH7 Range 0 ± 50 ;

mV pH 4 Range $+180 \pm 50$;

mV pH 10 Range -180 ± 50 ;

Slope from 7 to 10 and 4 to 7 must be between 165 and 180 mV

Depth (Quarterly)

Date of Last Depth Verification

N/A

Depth Sensor (Daily)	Name	Date	Time CT-ET	Zero the Sensor	ICV Value	Pass / Fail	Lab / Field
Pressure mode in air				0.000			

ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater