

CALIBRATION AND VERIFICATION LOG (FDEP SOP FT 1000-FT 1500, FD 1000-FD 4000)

Boldly "X" this box if there is qualified data on this page

Meter ID:

7

Project:

Woodmere, Goodfield

RP - 2017-05-22-05

Notes: (1) Numbers ≤ 4 , are rounded down; numbers ≥ 5 are rounded up (e.g., 5.15 becomes 5.2).

(2) Always wait for meter to stabilize before recording any readings.

(3) For Calibrations, record calibrated meter reading. Do not record initial meter reading before calibration.

Circle/Fill In: Lab Calibration

or Calibration/Verification on Site

Temperature (Quarterly) FT 1400

Date of Last Temperature Verification

5/1/17

DO DEP SOP FT 1500	Name	Date	Time (ET)	Temp. (°C)	D.O. Chart mg/L	Meter D.O. mg/L	% DO	Probe Charge	Probe Gain	Pass / Fail	Lab / Field
Calibr.	Chase Long	6/19/17	0115	25.0	8.3	8.3	100	46		☒ F	☒ F
ICV	Chase Long	6/19/17	0718	25.0	8.3	8.3	100	46		☒ F	☒ F
CCV	Chase Long	6/19/17	1600	26.4	8.1	8.0	99	46		☒ F	☒ F
CCV										P F	L F

Report DO mg/L with one decimal figure and DO % saturation as a whole number with no decimals.

DO Acceptance criteria from Table ± 0.3 mg/L.

Rapid-Pulse Sensors: DO Gain Range 0.7 to 1.4; DO Charge Range 25-75.

Optical: DO gain range 0.85 to 1.15; DO charge N/A.

Steady-state & Galvanic Sensors: DO Gain & Charge N/A.

Spec. Cond. FT 1200	Name	Date	Time (ET)	Lot #	Expir. Date	Standard μ mhos/cm	Meter Reading μ mhos/cm	Pass / Fail	Lab / Field
Calibr.	Chase Long	6/19/17	0720	120412	4/18	1000	1000	☒ F	☒ F
ICV	Chase Long	6/19/17	0722	110412A	4/18	500	503	☒ F	☒ F
CCV	Chase Long	6/19/17	1358	2511C38	11/17	52000	50543	☒ F	☒ F
CCV								P F	L F

Report specific conductance as a whole number with no decimal figure.

Conductivity Acceptance criteria $\pm 5\%$

pH DEP SOP FT 1100	Name	Date	Time (ET)	Lot #	Expir. Date	pH Buffer SU	Meter reading SU	mV	Pass / Fail	Lab / Field
Calibr.	Chase Long	6/19/17	0724	167801	12/18	7.0	7.0	14	☒ F	☒ F
Calibr.	Chase Long	6/19/17	0726	167431	11/18	4.0	4.0	159	☒ F	☒ F
Calibr.	Chase Long	6/19/17	0730	170903	2/19	10.0	10.0	161	☒ F	☒ F
ICV	Chase Long	6/19/17	0732	167431	11/18	4.0	4.0	168	P F	L F
CCV	Chase Long	6/19/17	1555	170903	2/19	10.0	9.9	155	☒ F	☒ F
CCV									P F	L F

Report pH with one decimal place; pH Acceptance criteria ± 0.2 SU;

mV pH7 Range 0 $\pm$ 50;

mV pH 4 Range +180 $\pm$ 50;

mV pH 10 Range -180 $\pm$ 50;

Slope from 7 to 10 and 4 to 7 must be between 165 and 180 mV

Depth (Quarterly)

Date of Last Depth Verification

Depth Sensor (Daily)	Name	Date	Time CT-ET	Zero the Sensor	ICV Value	Pass / Fail	Lab / Field
Pressure mode in air				0.000			

ICV acceptance criteria $\pm 5\%$ or ± 0.05 m, whichever is greater

Notes: