From: Murphy, Rosemary
To: Tull, Carina
Subject: RE: RQ-2017-06-12-09
Date: Tuesday, August 1, 2017 11:51:26 AM
Attachments: image002.png

Carina,
Yes, 1005 is the correct sampling time.

-Rosemary

From: Tull, Carina
Sent: Tuesday, August 1, 2017 10:54 AM
To: Paswater, Benjamin <Benjamin.Paswater@dep.state.fl.us>; Murphy, Rosemary <Rosemary.Murphy@dep.state.fl.us>
Cc: Savage, Jacqueline <Jacqueline.Savage@dep.state.fl.us>
Subject: RQ-2017-06-12-09

Good Morning,

Could you please confirm the collection time for this sample? It shows as 10:05 in the coc that went to DEP.

Thank You,
Carina.



Request Number: RQ-2017-06-12-09
Pollywog, OK Branch, Roberts, Telegraph #2
Customer: WQAP
Project ID: SMP

Florida Department of Environmental Protection
Central Laboratory Submittal Form

Page 1 of 3
last revised Apr 7, 2016

Requester: Benjamin Paswater
Field Report Prepared By: Ben Paswater
Collected By: Ben Paswater, Rosemary Murphy
Sampling Agency: FDEP

Location: RQ-2017-06-12-09 7/12/2017; WBID 3235F; Pollywog Creek @ SR78; G3SD071217-1; Field ID; STORET 2820268FTM
Comp / Grab; Collection (comp begin or grab) Date 7/12/17 Time 1005 Eastern / Central
Composite end Date Time
Bottle Group(s) (See pg 2): B, C
Matrix (type, e.g., Salt, Fresh, etc): Diss. Oxygen 5.7, 68% mg/L / % sat
Total Res. Chlorine (mg/L)
Temp (C) 25.4; pH 6.4; Sample Depth 0.3 ft / m; Sp. Conductance (umho/cm) 138
dd / dms; Salinity (ppt)
Comments
Location: Comp; Collection (comp begin or grab) 1310 Eastern; Composite end; Bottle

Carina Tull
Biological Scientist I
FDEP Laboratory - Biology Program
Florida Department of Environmental Protection
Carina.Tull@dep.state.fl.us
Office: 850.245.8174