

SCI

Site Name Elder Springs Run / Six Mile Sample Date 11/19/18
 WBID 2984 WIN ID G2CE0120 RQ 2018-11-19-44

	Initial/Date	QC Initial/Date
Water chemistry data to LIMS	KWM NOV 29 2018	LB 12/4/18
Create SBIO station visit	KWM NOV 29 2018	n/a
Phys/Chem entry	KWM NOV 29 2018	LB 12/4/18
Habitat Assesment entry	KWM NOV 29 2018	LB 12/4/18
Vascular entry (add LIMS ID to entry)	n/a	N/A
RPS entry	KWM NOV 29 2018	LB 12/4/18
Authorize SBIO data	LB 12/4/18	n/a
Scan all sheets to 21FLCEN folder		n/a
LIMS/WIN migration		n/a
File in cabinet		n/a

Comments/notes:



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
STRATEGIC MONITORING PROGRAM FIELD SHEET

April 2018

Data Qualified?

Yes ☒ No ☐

WIN Station Name: Elder Springs Run @ US of Myrtle St

Date: 11/19/18

WIN/ Field ID: G2CE0120

WBID: 2984

Latitude: 28.73495

(mm/dd/yyyy)

County: Seminole

ORG ID: 21 FL CEN

Longitude: -81.26709

(Decimal Degrees)

Receiving Body of Water: Lake Jesup

RQ-2018- 11-19-46

(Decimal Degrees)

Sampling Team Members

Katie March

Leif Roman

WQ Measurements	Sample Collection	Documentation	Preservation	Preservation Check
☒	☒	☒	☒	☒

Sampling Equipment

- ☒ Sample Container ☐ Van Dorn ☐ Pole
☐ Carboy ☒ Syringe
☐ Dipper ☐ Other

Depth Measured with SECCHI DISK LINE

Equipment ID KNOTHEAD

Collection Method

- ☒ Wading ☐ Canoe/Kayak
☐ From Shore ☐ Electric Motor
☐ Other ☐ Gasoline Motor

Water Level: Dry/ Pooled/ Low / Normal / High / Flooded

Meter ID# Bath Boop-Non

Matrix: Fresh / Marine / DI

Photos: Yes ☒ No ☐ Flow: No Flow / Intestinal / Flowing / NA

Tide: Rising/ Falling/ Slack/ NA

Tide Times: High Low

Time Zone	Time	Total Depth (m)	Sample Depth (m)	Secchi Disk (m)	DO (mg/L)	DO (%SAT)	pH	Salinity (PPT)	Sp COND (umhos/cm)	Temp. (C°)
EST	1057	0.3	0.15	0.3(s)	7.90	86.5	7.14	0.14	332	19.72
CEN										

Biological Samples Collected: None HA SCI RPS Algae ID LVS LVI Other:

S BIO ID Numbers: SBIO-ID: 79042 HA-ID: 15494 RPS-ID: 9145 Macrophyte-ID: n/a LIMS#: 2042822

Parameter Suite	Parameter Methods	Preservation	Lot#	Expiration	pH Check
Preserved Nutrients	☒ W-NH3 / W-NO2NO3 / W-TKN / W-TOC / W-S-A-TP	☒ Ice ☒ H2SO4	<u>SA8197090</u>	<u>7/14/19</u>	☒ <2
Metals	☒ W-ICPMS ☒ W-ICP	☒ Ice ☒ HNO3	<u>NA7341010</u>	<u>12/7/18</u>	☒ <2
Filtered Nutrients	☒ W-PO4-F ☒ Field Filtered 0.45 um Filter	☒ Ice	<u>13615055</u>		
Chlorophyll	☒ CHLSUTE-W	☒ Ice			
Physical/Aggregate (Fresh)	☒ Alkalinity / W-F / W-TSS / TURBIDITY / W-CI-IC / W-COLOR / W-SO4-IC / W-TDS	☒ Ice			
Physical/Aggregate (Marine)	☐ Alkalinity / W-F / W-TSS / TURBIDITY	☐ Ice			
Macroinvertebrates	☒ MI-FW-QLDC	☒ Formalin			
Periphyton	☐ ALGAE-ID	☐ Ice			
Microbiology	☐ E Coli ☐ F Coli ☐ Enterococci	☐ Ice			
Molecular	☐ PCR-FILTER ☐ PCR-HF183 ☐ PCR-BacR ☐ PCR-GULL2 ☐ PCR-GFD	☐ Ice			
Tracers	☐ W-E8321-D1 ☐ W-E8321-MS	☐ Ice			
Pesticides	☐ W-PSNP-TQ ☐ W-CT-CL-R ☐ W-E8321-D1 ☐ W-PCL-SQ-R ☐ WE8321-MS ☐ W-CARB-AA	☐ Ice ☐ Other			

Place Preservative Sticker(s) Here
(If Available)

Notes:

WIN ID / Field ID →

Elder Springs Run @
US of Myrtle St
(2984)



G2CE0120

Signature: K March

Date: 11/19/18

Enter Field Parameters, Verify Station ID In LIMS DMT: KWM NOV 29 2018

QC Station ID, Field Parameters In LIMS DMT:

Scan/Save Field Sheets

Migrate Data to WIN:

Verify Data In WIN:

DEP Form FD 9000-3 Physical/Chemical Characterization Field Sheet

SAMPLE ID _____ ORG ID _____ LATITUDE _____
 COUNTY Seminole STORET # 6260120 LONGITUDE _____
 DATE 11/19/10 TIME _____ SAMPLING AGENCY 2IFLUCN
 SITE NAME Elder Springs Run
 FIELD ID/NAME _____ RECEIVING BODY OF WATER Lake Jesup

RIPARIAN ZONE / STREAM FEATURES

PREDOMINANT LAND-USE IN WATERSHED (specify relative percent in each category): Forest/Natural ☐ Silviculture ☐ Field/Pasture ☐ Agricultural ☐ Residential ☐ Commercial ☐ Industry ☐ Other (Specify) ☐								Landscape Development Intensity Index (LDI) ☐	
Local Watershed Erosion (select one): ☐ None ☒ Slight ☐ Moderate ☐ Heavy Local Watershed NPS Pollution: ☐ No evidence ☐ Slight ☒ Moderate ☐ Heavy						Typical Width (m) Depth (m)/Velocity (m/sec) Transect _____ m wide _____ m/s _____ m/s _____ m/s			
Width of Riparian Vegetation (m) on Each Buffer Side Left Bank: <u>16</u> Right Bank: <u>12</u>				Hydrologic Modification Score (per FT 3101) ☐				_____ m/s _____ m/s _____ m/s	
High Water Mark: <u>0.3</u> + <u>0.3</u> = <u>0.6</u> (m) (above present water level) (present depth) (above bed)				Artificially Impounded ☐ Yes ☒ No				_____ m deep _____ m deep _____ m deep	
Artificially ☒ No ☐ Mostly recovered, more sinuous Channelized: ☐ Some recovery ☐ Recent, severe				Canopy Cover % ☐ Open ☒ Lightly Shaded (11-45%) ☐ Heavily Shaded ☒ Moderate Shaded (46-80%)					

SEDIMENT / SUBSTRATE

Sediment Oils ☒ Absent ☐ Slight ☐ Moderate ☐ Profuse			Sediment Odors ☒ Normal ☐ Sewage ☐ Petroleum ☐ Chemical ☐ Anaerobic ☐ Other (Specify): _____			Smothering of Substrates Sand Smothering: None ☐ Slight ☒ Moderate ☐ Severe ☐ Silt Smothering: None ☐ Slight ☒ Moderate ☐ Severe ☐ Algae Smothering: None ☒ Slight ☐ Moderate ☐ Severe ☐		
SUBSTRATE TYPE Assessment Tool: ☒ SCI ☐ RPS ☐ LVS ☐ LCI ☐ BioRecon			WATER QUALITY Depth (M) Temp. (°C) pH (SU) D.O. (MG/L) D.O. Sat (%) Cond. (UMHO/CM) Salinity (PPT) SECCHI (M) Top: <u>0.15</u> <u>19.72</u> <u>7.14</u> <u>7.90</u> <u>84.5</u> <u>332</u> <u>0.14</u> ☐ Mid: _____ _____ _____ _____ _____ _____ _____ ☒ VOB Bottom: _____ _____ _____ _____ _____ _____ _____ ☐ Meter ID: <u>Boop-Nan</u> <u>0.3</u>					
Woody Debris (Snags) ☐ <u>7</u> ☐ Undercut Banks / Roots ☐ <u>7</u> ☐ Leaf Packs or Mat ☐ <u>3</u> ☐ Aquatic Vegetation ☐ ☐ ☐ Rock or Shell Rubble.. ☐ ☐ ☐ Sand..... ☐ <u>3</u> ☐ Mud / Muck / Silt ☐ ☐ ☐ Other ☐ ☐ ☐ Other ☐ ☐ ☐			Water Odors Normal ☒ Petroleum ☐ Sewage ☐ Chemical ☐ Other ☐			Water Surface Oils Normal ☒ Sheen ☐ Globbs ☐ Slick ☐ Other ☐		
			Water Sample Taken? ☒ Yes ☐ No Sample Preserved? ☒ Yes ☐ No Lot Number: _____ Exp: _____			Color Tannic ☒ Green (Algae) ☐ Clear ☐ Other (Specify) ☐		
			Algae Sample Taken? ☐ Yes ☒ No Sample Preserved? ☐ Yes ☐ No Lot Number: _____ Exp: _____			Clarity Clear ☒ Slightly Turbid ☐ Turbid ☐ Opaque ☐		
ABUNDANCE Not Obs. Rare Common Abundant Periphyton: ☒ ☐ ☐ ☐ Fish: ☐ ☒ ☐ ☐ Aquatic Plants: ☒ ☒ ☐ ☐ Iron/Sulfur Bacteria: ☒ ☐ ☐ ☐			System Type: Stream ☒ Lake ☐ Wetland ☐ Estuary ☐ Other(Specify) ☐					
AMBIENT FIELD CONDITIONS / NOTES: ☒ The antecedent hydrologic conditions have been met to my best knowledge.								
SAMPLING TEAM <u>KWM, LGB</u>				SIGNATURE: <u>KWM</u>			DATE: <u>11/19/10</u>	

DEP FORM FD 9000-25 Rapid Periphyton Survey Field Sheet

Site: Elder/Six Mile County: Seneca Date: 11/19/18 Investigators: KWM, LGB

STORET Station Number: 62CE0120

Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover
0	1	N			60	1	N		
	2	N				2	N		
	3	N				3	N		
	4	N				4	N		
	5	N		96		5	N		92
	6	N				6	N		
	7	N				7	N		
	8	N				8	N		
	9	N				9	N		
10	1	N			70	1	N		
	2	N				2	N		
	3	N				3	N		
	4	N				4	N		
	5	N		84		5	N		96
	6	N				6	N		
	7	N				7	N		
	8	N				8	N		
	9	N				9	N		
20	1	N			80	1	N		
	2	N				2	N		
	3	N				3	N		
	4	N				4	N		
	5	N		90		5	N		94
	6	N				6	N		
	7	N				7	N		
	8	N				8	N		
	9	N				9	N		
30	1	N			90	1	N		
	2	N				2	N		
	3	N				3	N		
	4	N				4	N		
	5	N		94		5	N		76
	6	N				6	N		
	7	N				7	N		
	8	N				8	N		
	9	N				9	N		
40	1	N			100	1	N		
	2	N				2	N		
	3	N				3	N		
	4	N				4	N		
	5	N		96		5	N		70
	6	N				6	N		
	7	N				7	N		
	8	N				8	N		
	9	N				9	N		
50	1	N				1	N		
	2	N				2	N		
	3	N				3	N		
	4	N				4	N		
	5	N		88		5	N		
	6	N				6	N		
	7	N				7	N		
	8	N				8	N		
	9	N				9	N		

Secchi depth 0.3 (m)
Estimated?

points ranked 4-6 0
total points assessed 99
% points ranked 4-6 0

Check accompanying data collected at same site/date.

Algal mat sample	
Linear Veg Survey	
Habitat Assessment	✓
SCI/Biorecon	✓
Water sample	✓
RQ-	

Algal Thickness Rank

N	rough, no algae, slimy, algae up to 1mm
3	>1mm - 6mm
4	>6mm - 20mm
5	>20mm - 10 cm
6	>10 cm

Record "N" and check "Estimated" for points deeper than the Secchi depth; algae are presumed absent. Check "Estimated" if thickness estimated for deep points which can be seen but not reached.

Record "X" for points shallower than Secchi depth for which substrate cannot be seen or reached with the hand. No estimated rank.

Record canopy cover as the number of small densiometer quadrants (out of 96) that HAVE canopy cover. Measure facing upstream at point 4, 5, or 6.

Collect algal mat sample following DEP SOP FS 7240 if the percentage of total sampled points with a thickness rank of 4, 5, or 6 is >20%.

DEP FORM FD 9000-32: LINEAR VEGETATION SURVEY FIELD SHEET

Storet Number:

Signature:

Instructions: Note taxa growing in the water with a checkmark if present, "D" if dominant, and "C" if codominant (dominance only if 1 m² of taxa present). Note in the boxes below if no dominant are selected, and note total macrophyte abundance rank for each section. Only the most common taxa are listed, so use blank spaces for additional taxa names.

HERBACEOUS SPECIES	Meter Mark										Specimen collected (check)	HERBACEOUS SPECIES	Meter Mark										Specimen collected (check)
	0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100			0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100	
<i>Alternanthera philoxeroides</i>												<i>Micranthemum glomeratum</i>											
<i>Bacopa caroliniana</i>												<i>Micranthemum umbrosum</i>											
<i>Bacopa monnieri</i>												<i>Myriophyllum aquaticum</i>											
<i>Bidens mitis</i>												<i>Najas guadelupensis</i>											
<i>Boehmeria cylindrica</i>												<i>Nuphar luteum</i>											
<i>Centella asiatica</i>												<i>Orontium aquaticum</i>											
<i>Ceratophyllum demersum</i>												<i>Panicum hemitomon</i>											
<i>Chara</i>												<i>Panicum repens</i>											
<i>Cicuta maculata</i>												<i>Panicum rigidulum</i>											
<i>Cladium jamaicense</i>												<i>Pistia stratioides</i>											
<i>Colocasia esculenta</i>												<i>Polygonum glabra</i>											
<i>Commelina diffusa</i>												<i>Polygonum hydropiperoides</i>											
<i>Commelina virginica</i>												<i>Polygonum punctatum</i>											
<i>Crinum americanum</i>												<i>Pontederia cordata</i>											
<i>Diodia virginiana</i>												<i>Potamogeton illinoensis</i>											
<i>Eichhornia crassipes</i>												<i>Ruellia simplex</i>											
<i>Eleocharis (wispy viviparous)</i>												<i>Sacciolepis striata</i>											
<i>Hydrilla verticillata</i>												<i>Sagittaria kurziana</i>											
<i>Hydrocotyle</i>												<i>Sagittaria lancifolia</i>											
<i>Hydrophila polysperma</i>												<i>Sagittaria latifolia</i>											
<i>Hymenocallis</i>												<i>Salvinia minima</i>											
<i>Lachnanthes caroliniana</i>												<i>Samolus parviflora</i>											
<i>Landoltia punctata</i>												<i>Saururus cernuus</i>											
<i>Lemna</i>												<i>Sparganium americanum</i>											
<i>Limnophila sessiflora</i>												<i>Typha</i>											
<i>Ludwigia leptocarpa</i>												<i>Vallisneria americana</i>											
<i>Ludwigia palustris</i>												<i>Zizania aquatica</i>											
<i>Ludwigia peruviana</i>																							
<i>Ludwigia repens</i>																							
<i>Luziola fluitans</i>																							
					</																		

DEP Form FD 9000-5 Stream/River Habitat Assessment Field Sheet


SAMPLING AGENCY:		STORET STATION NUMBER: <u>G260120</u>	DATE (MM/DD/YY): <u>11/19/18</u>	RECEIVING BODY OF WATER: <u>Lk. Jesup</u>
REMARKS:	COUNTY: <u>Seminole</u>	LOCATION: <u>Eden/Six Mile</u>		FIELD ID/NAME:

Habitat Parameter	Optimal	Suboptimal	Marginal	Poor
Primary Habitat Components	Four or more major productive habitats present [snags, tree roots, aquatic vegetation, leaf packs (partially decayed), rock]	Three major productive habitats present. Adequate habitat. Some substrates may be new fall (fresh leaves or snags)	Two major productive habitats present. Less than desirable habitat, frequently disturbed or removed	One or less major productive habitat. Lack of habitat is obvious, substrates unstable or smothered
Substrate Diversity <u>6</u>	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Substrate Availability <u>3</u>	Greater than 30% major productive habitat present at site 20 19 18 17 16	16% to 30% major productive habitat, by aerial extent 15 14 13 12 11	6% to 15% major productive habitat 10 9 8 7 6	Less than 5% major productive habitat 5 4 3 2 1
Water Velocity <u>14</u> <u>5 seconds</u>	Max. observed at typical transect: > 0.25 m/sec. But < 1 m/sec ≥0.33 0.31 0.29 0.27 >0.25 20 19 18 17 16	Max. observed at typical transect: >0.1 to 0.25 m/sec 0.25 0.21 0.17 0.13 >0.1 15 14 13 12 11	Max. observed at typical transect: 0.05 to 0.1 m/sec 0.1 0.09 0.07 0.06 0.05 10 9 8 7 6	Max. observed at typical transect: <0.05 m/sec; or spate occurring: > 1 m/sec <0.05 0.04 0.03 0.01 <0.01 5 4 3 2 1
Habitat Smothering <u>18</u> ----- Primary Score <u>41</u>	Adequate number of stable pools (1-2 per 12 times width) and <25% of habitats affected by sand, silt, or algae. 20 19 18 17 16	Adequate number of stable pools (1-2 per 12 times width) and >25% of habitats affected by sand, silt, or algae. 15 14 13 12 11	Does not have required number of stable pools (1-2 per 12 x width) and/or has shallow pools (<2 x prevailing depth). 10 9 8 7 6	Stable pools are absent. Most habitats affected by sand, silt, or algae accumulation. 5 4 3 2 1
Secondary Habitat Components	Expected sinuosity given the stream width. No evidence of dredging or artificial straightening. No spoil banks.	Good sinuosity within old channelized area. Evidence of dredging or straightening in the past (>25 yrs) but mostly recovered.	Straightened with trapezoidal cross section, but has a small degree of sinuosity developed within channelized area.	Straightened or engineered by dredging, has trapezoidal or box cut cross section, lacks required pools. May have spoil banks.
Artificial Channelization <u>19 18</u>	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Bank Stability	Bankfull > 60% of bank height. Slope of bank ≤ 60° from bankfull to top of bank. Bankfull is within or above the woody root zone with few raw, eroded areas.	Only meets 2 of the 3 requirements for optimal bank stability.	Only meets 1 of the 3 requirements for optimal bank stability.	Bankfull < 60% of bank height. Slope of bank > 60°. Bankfull is below the woody root zone with raw, eroded areas.
Right Bank <u>4</u> Left Bank <u>3</u>	10 9	8 7 6	5 4	3 2 1
Riparian Buffer Zone Width	Width of vegetation greater than 18 m	Width of vegetation >12 to 18m	Width of vegetation 6 to 12 m. human activities close to system	Less than 6 m of buffer zone due to intensive human activities
Right Bank <u>10 5</u> Left Bank <u>6 0</u>	10 9	8 7 6	5 4	3 2 1
Riparian Zone Vegetation Quality	Over 80% of riparian surfaces consist of normal, expected plant community for given sunlight & habitat conditions (e.g., native plants; tree, shrub, and forbs represented, if appropriate). Minimal disturbance.	>50% to 80% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Some disruption in community observed.	25% to 50% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Disruption obvious.	Less than 25% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions).
Right Bank <u>3</u> Left Bank <u>4</u> ----- Secondary Score <u>45</u>	10 9	8 7 6	5 4	3 2 1

86 TOTAL SCORE

Date: <u>11/19/18</u>	Analyst: <u>KWM, LGB</u>	Signature: <u>KWM</u>
-----------------------	--------------------------	-----------------------

DEP Form FD 9000-4 Stream/River Habitat Assessment Sketch Sheet



Location: Six Mile Creek @ Myrtle St.
 Date: 11/19/18
 Sampler: Leif Bowen, Katie Wood

100 m: Latitude _____	Longitude _____
0 m: Latitude _____	Longitude _____
Substrates: Code key, draw proportionate habitat abundance. %	
Snags	1.5
Roots/undercut banks	1.15
Leaf Packs (or mats)	.25
Aquatic Macrophytes	_____
Pools	total # observed = <u>16</u> # range expected = _____
Average width <u>2</u> m	
Average depth _____ m	
Velocity measured at _____ meter mark.	
WQ & chemistry taken at _____ meter mark.	
Habitat Smothering: Note areas (on map) where sand or silt is smothering substrates, limiting habitability.	
Bank Stability: Note areas (on map) with unstable, eroding banks.	
Riparian Buffer Width: Note areas (on map) where natural vegetation is altered or eliminated.	

Plants observed / other notes:

Snags
 roots
 minor leaf
 mats

water level has dropped
 pools meet required # still