

FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP- Orlando
3319 Maguire Blvd., Suite 232
Orlando, FL 32803

PO #: SMP
Client Project #: RQ-2018-02-12-56
Date Sampled: Feb 12, 2018
Feb 13, 2018; Invoice: 357098

Invoice


Description	Amount	Units	Extension
EColi-QT	51.00	10	510.00
TOTAL			510.00

This invoice is due upon receipt.

Please remit to: P.O. Box 150597
Altamonte Springs, FL 32715-0597

VISA, MasterCard, and American Express cards will be accepted.

There will be a 1.5% service charge per month on all unpaid balances.



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP- Orlando
3319 Maguire Blvd., Suite 232
Orlando, FL 32803

PO #: SMP
Client Project #: RQ-2018-02-12-56
Date Sampled: Feb 12, 2018
Feb 13, 2018; Invoice: 357098

Report Summary

Date Received: Feb 12, 2018

FCL Project Manager: June S. Flowers


Laboratory #	Sample Description	Analysis	Chemist	Location	Sample Matrix
357098SW1	G2CE0171	SM9223B	ECG	Main Lab	Surface Water
357098SW2	G2CE0145	SM9223B	ECG	Main Lab	Surface Water
357098SW3	G2CE0098	SM9223B	ECG	Main Lab	Surface Water
357098SW4	G2CE0144	SM9223B	ECG	Main Lab	Surface Water
357098SW5	G2CE0067	SM9223B	ECG	Main Lab	Surface Water
357098SW6	G1CE0090	SM9223B	ECG	Main Lab	Surface Water
357098SW7	G2CE0011	SM9223B	ECG	Main Lab	Surface Water
357098SW8	G1CE0089	SM9223B	ECG	Main Lab	Surface Water
357098SW9	G1CE0088	SM9223B	ECG	Main Lab	Surface Water
357098SW10	G1CE0087	SM9223B	ECG	Main Lab	Surface Water

Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAC Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.
President/Technical Director



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050


Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP- Orlando
3319 Maguire Blvd., Suite 232
Orlando, FL 32803

PO #: SMP
Client Project #: RQ-2018-02-12-56
Date Sampled: Feb 12, 2018
Feb 13, 2018; Invoice: 357098

Analysis Report

Lab #: 357098SW1	Sampled: 02/12/18 01:28 PM	Desc: G2CE0171								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	2.00	mpn/100mL	1.00	1.00	1.00	10363953	SM9223B		02/12/18	03:20 PM
Lab #: 357098SW2	Sampled: 02/12/18 01:15 PM	Desc: G2CE0145								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	5.20	mpn/100mL	1.00	1.00	1.00	10363953	SM9223B		02/12/18	03:20 PM
Lab #: 357098SW3	Sampled: 02/12/18 01:03 PM	Desc: G2CE0098								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	6.30	mpn/100mL	1.00	1.00	1.00	10363953	SM9223B		02/12/18	03:20 PM
Lab #: 357098SW4	Sampled: 02/12/18 01:10 PM	Desc: G2CE0144								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	3.00	mpn/100mL	1.00	1.00	1.00	10363953	SM9223B		02/12/18	03:20 PM
Lab #: 357098SW5	Sampled: 02/12/18 09:37 AM	Desc: G2CE0067								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	43.1	mpn/100mL	1.00	1.00	1.00	10363953	SM9223B		02/12/18	03:20 PM
Lab #: 357098SW6	Sampled: 02/12/18 11:55 AM	Desc: G1CE0090								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	3.00	mpn/100mL	1.00	1.00	1.00	10363953	SM9223B		02/12/18	03:20 PM
Lab #: 357098SW7	Sampled: 02/12/18 10:20 AM	Desc: G2CE0011								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	186	mpn/100mL	1.00	1.00	1.00	10363953	SM9223B		02/12/18	03:20 PM



FLOWERS CHEMICAL LABORATORIES INC.


P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP- Orlando
3319 Maguire Blvd., Suite 232
Orlando, FL 32803

PO #: SMP
Client Project #: RQ-2018-02-12-56
Date Sampled: Feb 12, 2018
Feb 13, 2018; Invoice: 357098

Lab #: 357098SW8 Sampled: 02/12/18 11:45 AM Desc: G1CE0089										
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	2.00	mpn/100mL	1.00	1.00	1.00	10363953	SM9223B		02/12/18	03:20 PM
Lab #: 357098SW9 Sampled: 02/12/18 11:35 AM Desc: G1CE0088										
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	2.00	mpn/100mL	1.00	1.00	1.00	10363953	SM9223B		02/12/18	03:20 PM
Lab #: 357098SW10 Sampled: 02/12/18 11:28 AM Desc: G1CE0087										
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	6.30	mpn/100mL	1.00	1.00	1.00	10363953	SM9223B		02/12/18	03:20 PM




FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP- Orlando
3319 Maguire Blvd., Suite 232
Orlando, FL 32803

PO #: SMP
Client Project #: RQ-2018-02-12-56
Date Sampled: Feb 12, 2018
Feb 13, 2018; Invoice: 357098



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP- Orlando
3319 Maguire Blvd., Suite 232
Orlando, FL 32803

PO #: SMP
Client Project #: RQ-2018-02-12-56
Date Sampled: Feb 12, 2018
Feb 13, 2018; Invoice: 357098

Narrative Report

Sample Handling

Sample handling and holding time criteria were met for all samples. Samples collected by submitter. No unusual events occurred during analysis. Results were read on 2/13/18 at 10:28AM.

Quality Control

Enclosed analyses met method or FCL criteria, unless otherwise denoted on the sample results. Applied data qualifiers are defined below.

Attachments

Chain of Custody

Qualifier	Meaning
U	Compound was analyzed for but not detected.
J	Estimated value; one or more QC components associated with this data value exceed current QC limits.
Q	Sample held beyond the accepted holding time.
L	Off-scale high; reported concentration exceeds the highest standard.
V	Analyte was detected in both the sample and the associated method blank.
W	The dissolved oxygen blank was above 0.2 mg/L but less than the MDL.
Z	Too numerous to count colonies on plate.
A	Absent
P	Present
T	Value reported is less than the statistical method detection limit. Reported for informational purposes only.
M	Value reported is greater than the statistical method detection limit, but less than the reported MDL.
G	The greatest of the dilutions performed did not yield sufficient oxygen depletion for valid data.
S	The least of the dilutions performed did not yield sufficient oxygen residual for valid data.
O	Result is greater than (over) the specified value.
I	Reported value is between the laboratory method detection limit and the laboratory practical quantitation limit.
B	Results based upon colony plate count outside ideal range.
Y	The laboratory analysis was from an improperly preserved sample. The data may not be accurate.